

## Enterprise Hub 38 Toh Guan Road East #01-57 S(608581) Email: motor@wahhong.sg

(199806235M)

## Page No. 1

Vehicle No. SJU4658Y Mitsubishi Lancer 1.5A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Front bumper		450.00	de
1	Front bumper tow cover		25.00	
1	Front bumper lower skirt		220.00	
1	Front center grille with logo		205.00	are
1	Front bumper lower grille		110.00	
1	Fog lamp cover LH/RH @ \$70.00		140.00	-
1	Fog lamp LH/RH @ 340.00		680.00	0
1	Front bumper undercover		180.00	\$ .
1	Front door RH	7111	700.00	<b>(%</b>
1	Rear door RH		600.00	PK.
1	Front door handle RH		90.00	×
1	Rear door handle RH		90.00	×
1	Front fender LH/RH @ \$390.00		780.00	RY
1	Front fender signal light RH/LH @ \$65.00		130.00	X
1	Front bumper retainer LH/RH @ \$35.00		70.00	ne -
1	Front innershield LH/RH @ \$125.00		250.00	7.
1	Bonnet		550.00	61/
1	Bonnet insulator		190.00	de -
1	Bonnet hinge LH/RH @\$45.00		90.00	7 .
1	Radiator top cover		115.00	de/
1	Headlamp LH/RH @ \$460.00		920.00	
1	Front support panel		290.00	
1	Front reinforcement beam		270.00	1/
1	Air intake piping		75.00	1
1	Air box assy		160.00	0
1	condenser		635.00	1 1
1	Radiator	14 1 1 1 1 1	825.00	
1	Lock assy		110.00	61-
1	Wiper water tank		80.00	j,
1	Passenger air bag unit		1050.00	aut/
1	Driver air bag unit		1100.00	
1	Air bag sensor		450.00	
1	Dashboard		950.00	

		Total Parts	12690.00
l	Rear Number plate with holder		65.00 45 kt
L	Rear bumper clips		40.00 30 000
l	Front Number plate with holder		65.00 45 61
L	Center grille clips		30.00 www
L	Front undercover clips		30.00 70 New
L	Front innershield clips		60.00 Xnn.
L	Front bumper clips		40.00 30m
	CRECIAL NETT ITEMS		12360.00
		LESS 20%	3090.00
			15450.00
	EXITUASE		· ·
	Exhuast		350.00 64
	Boot lamp LH/RH@195.00		390.00 ×
	Rear reinforcement Rear bumper reflector LH/RH@\$65.00		130.00 cm
	Rear bumper		390.00
	Driver seat belt unit		420.00 de
	Passenger seat belt unit		420.00 out
	Steering wheel		350.00 act



## Enterprise Hub 38 Toh Guan Road East #01-57 S(608581) Email: motor@wahhong.sg (199806235M)

Page No. 2

Vehicle No. SJU4658Y Mitsubishi Lancer 1.5A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)		SURVEYOR'S ADJUSTMENT
1	LABOUR  To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	2000.00	14	00.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1600.00	14	000
3	To remove and re-fix wiring and check all electrical components	150.00	60	,
4	To remove anfd refit dashboard, air bags	450.00	2	50.
5	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	180.00	6	)·
6	To provide anti-rust treatment on affected areas	180.00	61	o ·
7	To conduct full computerised wheel alignment test	150.00	×	
	Labour Total :	4710.00		
	TOTAL (PARTS & LABOUR):	17400.00		

Taylin 97495749

WP

17/11/19 e 515pm

11 days

surchantonom

To cheek repair limit.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: