

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/III19020169/KGA3Q2**Date:** 30/07/2020REFERENCE

|   |                             |          |           |             |
|---|-----------------------------|----------|-----------|-------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No:                  | MCOM0015 |           |             |
| <b>Claimant</b>   |                             |          |           |             |
| <b>Vehicle No :</b> SHD5560B                            | <b>Insured Vehicle No :</b> | SHC3401X |           |             |
| Date of Loss: 08/11/2019                                | Nature of Claim:            | TP       | Claim No: | MCT19110213 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                     |             |                   |  |
|-----------------------------|-------------------------------------|-------------|-------------------|--|
| Reg No:                     | <b>SHD5560B</b>                     |             |                   |  |
| Make & Model:               | TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) | Engine No:  | 2ZR2B75831        |  |
| Reg. Date:                  | 22/11/2018 (Man. Year: 2018)        | Chassis No: | JTDKB3FU503076908 |  |
| Colour:                     | Metallic White/Red                  | Odometer:   | 80052 km          |  |
| Engine Capacity:            | 1798 cc                             |             |                   |  |
| Market Value/New Car Price: | N/A                                 |             |                   |  |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>   |             |                   |  |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |            |                  |               |
|-------------------|------------|------------------|---------------|
| Front Tyre Size:  | 195/65 R15 | Rear Tyre Size:  | 195/65 R15    |
| Front Left Side:  | Giti 9 mm  | Rear Left Side:  | Goodyear 5 mm |
| Front Right Side: | Giti 9 mm  | Rear Right Side: | Goodyear 5 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b>                  | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|------------------------------------|-------------------|---------------|
| Parts  | 19,894.75         | 5,109.40                           | 14,785.35         | 74.32         |
| Miscellaneous Items                              | 0.00              | 0.00                               | 0.00              |               |
| Labour   | 19,410.00         | 2,740.00                           | 16,670.00         | 85.88         |
| Paintwork Labour                                 | 0.00              | 0.00                               | 0.00              |               |
| Towing   | 0.00              | 0.00                               | 0.00              |               |
| <b>Gross Total (S\$)</b>                         | <b>39,304.75</b>  | <b>7,849.40</b>                    | <b>31,455.35</b>  | <b>80.03</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | <b>2,751.33</b>   | <b>549.46</b>                      | <b>2,201.87</b>   | <b>80.03</b>  |
| <b>Nett Amount (S\$)</b>                         | <b>42,056.08</b>  | <b>8,398.86</b>                    | <b>33,657.22</b>  | <b>80.03</b>  |
| <b>+ Loss of Use (10.0 x S\$40.00/day) (S\$)</b> |                   | <b>400.00</b>                      |                   |               |
| <b>+ Car Rental (10.0 x S\$113.40/day) (S\$)</b> |                   | <b>1,134.00</b>                    |                   |               |
|  |                   | <b>Nett Liability (S\$)</b>        | <b>9,932.86</b>   |               |
|  |                   | <b>Global Sum Settlement (S\$)</b> | <b>9,900.00</b>   |               |

INSPECTION

|                     |            |               |  |
|---------------------|------------|---------------|--|
| Date of Assignment: | 12/11/2019 |               |  |
| Date Inspected:     | 12/11/2019 | Inspected At: | Trans-cab Auto Services Pte Ltd<br>No 2 Ang Mo Kio Street 63<br>Singapore 569111 |

Estimated Period of Repair: 7.0 days

**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                            |  |
|----------------------------|--|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 05 Feb 2020)  |
| <b>Parts:</b> 144          | TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)  |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SHD5560B)  |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                    | Condition       | Repairer's  | Amount       |
|-----|-----|----------|--|-----------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                                   | Torn            | 442.60 FL   | *442.60 FL   |
| 2   | 1   |          | *REAR BUMPER RE-INFORCEMENT                    | Bent            | 332.70 FL   | *332.70 FL   |
| 3   | 1   |          | *REAR BUMPER TOWING COVER                      | Serviceable     | 15.40 FL    | *- FL        |
| 4   | 1   |          | *REAR BUMPER UNDER COVER (BLACK)               | Bent            | 576.30 FL   | *576.30 FL   |
| 5   | 1   |          | *REAR BUMPER SIDE RETAINER LH                  | Distorted       | 116.50 FL   | *116.50 FL   |
| 6   | 1   |          | *REAR BUMPER SIDE RETAINER RH                  | Serviceable     | 117.70 FL   | *- FL        |
| 7   | 1   |          | *REAR BUMPER SIDE SEAL LH                      | Necessary       | 88.50 FL    | *88.50 FL    |
| 8   | 1   |          | *ANTENNA, ELECTRICAL KEY                       | Serviceable     | 72.00 FL    | *- FL        |
| 9   | 1   |          | *REAR TAILGATE                                 | Bent            | 1,147.80 FL | *1,147.80 FL |
| 10  | 1   |          | *REAR TAILGATE OUTER GARNISH                   | Cracked         | 925.60 FL   | *925.60 FL   |
| 11  | 1   |          | *REAR SPOILER SUB ASSY                         | Serviceable     | 1,575.40 FL | *- FL        |
| 12  | 1   |          | *GLASS, BACK WINDOW FIX                        | Serviceable     | 746.50 FL   | *- FL        |
| 13  | 1   |          | *COVER, REAR COMBINATION LAMP, RH              | Serviceable     | 64.50 FL    | *- FL        |
| 14  | 1   |          | *COVER, REAR COMBINATION LAMP, LH              | Serviceable     | 64.50 FL    | *- FL        |
| 15  | 1   |          | *GARNISH, BACK DOOR SIDE, LH                   | Serviceable     | 95.60 FL    | *- FL        |
| 16  | 1   |          | *GARNISH, BACK DOOR SIDE, RH                   | Serviceable     | 95.60 FL    | *- FL        |
| 17  | 1   |          | *MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH | Serviceable     | 56.50 FL    | *- FL        |
| 18  | 1   |          | *MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH | Serviceable     | 56.50 FL    | *- FL        |
| 19  | 1   |          | *BOARD ASSY, BACK DOOR TRIM                    | Distorted / Cut | 259.20 FL   | *259.20 FL   |
| 20  | 1   |          | *PANEL ASSY, BACK DOOR TRIM, UPPER             | Serviceable     | 52.10 FL    | *- FL        |
| 21  | 1   |          | *REAR TAILGATE WEATHERSTRIP                    | Serviceable     | 372.30 FL   | *- FL        |
| 22  | 1   |          | *PANEL SUB-ASSY, BODY LOWER BACK               | Repair          | 650.30 FL   | *- FL        |
| 23  | 1   |          | *TAILLAMP LOWER RH                             | Serviceable     | 502.00 FL   | *- FL        |
| 24  | 1   |          | *TAILLAMP UPPER RH                             | Serviceable     | 451.80 FL   | *- FL        |
| 25  | 1   |          | *REAR BUMPER SIDE RH                           | Serviceable     | 123.70 FL   | *- FL        |
| 26  | 1   |          | *REAR BUMPER SIDE LH                           | Cracked         | 123.70 FL   | *123.70 FL   |
| 27  | 1   |          | *TAILLAMP LOWER LH                             | Cracked         | 502.00 FL   | *502.00 FL   |
| 28  | 1   |          | *TAILLAMP UPPER LH                             | Mtg Cracked     | 443.30 FL   | *443.30 FL   |
| 29  | 1   |          | *REAR LH FENDER PANEL                          | Bent            | 854.80 FL   | *854.80 FL   |
| 30  | 1   |          | *LINER, REAR WHEEL HOUSE, LH                   | Repair          | 139.80 FL   | *- FL        |
| 31  | 1   |          | *PANEL, QUARTER WHEEL HOUSE, OUTER LH          | Serviceable     | 296.20 FL   | *- FL        |
| 32  | 1   |          | *BOARD, BACK DOOR TRIM                         | Serviceable     | 225.20 FL   | *- FL        |
| 33  | 1   |          | *PANEL ASSY, DECK TRIM SIDE, RH                | Serviceable     | 355.90 FL   | *- FL        |
| 34  | 1   |          | *PANEL ASSY, DECK TRIM SIDE, LH                | Serviceable     | 355.90 FL   | *- FL        |
| 35  | 1   |          | *COVER, FLOOR UNDER, NO.1                      | Serviceable     | 175.10 FL   | *- FL        |
| 36  | 1   |          | *COVER, FLOOR UNDER, NO.2                      | Serviceable     | 241.90 FL   | *- FL        |
| 37  | 1   |          | *COVER, REAR FLOOR                             | Serviceable     | 229.90 FL   | *- FL        |
| 38  | 1   |          | *COVER, DECK TRIM, REAR                        | Serviceable     | 126.70 FL   | *- FL        |
| 39  | 1   |          | *DUCT ASSY, QUARTER VENT, LH                   | Dented          | 67.00 FL    | *67.00 FL    |
| 40  | 1   |          | *HUB & BEARING ASSY, REAR AXLE, LH             | Serviceable     | 725.60 FL   | *- FL        |
| 41  | 1   |          | *DISC REAR                                     | Serviceable     | 450.70 FL   | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                            | Condition     | Repairer's  | Amount     |
|-----|-----|----------|--|---------------|-------------|------------|
| 42  | 1   |          | *CARRIER SUB ASSY, REAR AXLE, LH       | Serviceable   | 953.60 FL   | *- FL      |
| 43  | 1   |          | *CYLINDER ASSY, DISC BRAKE, REAR LH    | Serviceable   | 1,001.90 FL | *- FL      |
| 44  | 1   |          | *PAD KIT, DISC BRAKE, REAR             | Serviceable   | 188.40 FL   | *- FL      |
| 45  | 1   |          | *COVER, DISC BRAKE DUST, REAR LH       | Serviceable   | 58.20 FL    | *- FL      |
| 46  | 1   |          | *BAR, STABILIZER, REAR                 | Serviceable   | 295.70 FL   | *- FL      |
| 47  | 1   |          | *LINK ASSY, REAR STABILIZER, LH        | Serviceable   | 179.10 FL   | *- FL      |
| 48  | 1   |          | *BUSH, STABILIZER, REAR                | Serviceable   | 71.20 FL    | *- FL      |
| 49  | 1   |          | *BRACKET, REAR STABILIZER BAR, NO.1    | Serviceable   | 11.50 FL    | *- FL      |
| 50  | 1   |          | *BRACKET, REAR SUSPENSION ARM, LH      | Serviceable   | 107.20 FL   | *- FL      |
| 51  | 1   |          | *COVER, REAR SUSPENSION ARM, LH        | Serviceable   | 49.70 FL    | *- FL      |
| 52  | 1   |          | *ARM ASSY, REAR SUSPENSION, NO.1 LH    | Serviceable   | 239.20 FL   | *- FL      |
| 53  | 1   |          | *ARM ASSY, TRAILING, REAR LH           | Serviceable   | 370.40 FL   | *- FL      |
| 54  | 1   |          | *ABSORBER ASSY, SHOCK, REAR LH         | Serviceable   | 127.00 FL   | *- FL      |
| 55  | 1   |          | *SUPPORT ASSY, REAR SUSPENSION, LH     | Serviceable   | 149.30 FL   | *- FL      |
| 56  | 1   |          | *SPRING, COIL, REAR LH                 | Serviceable   | 199.00 FL   | *- FL      |
| 57  | 1   |          | *INSULATOR, REAR COIL SPRING, LOWER LH | Serviceable   | 13.90 FL    | *- FL      |
| 58  | 1   |          | *INSULATOR, REAR COIL SPRING, UPPER LH | Serviceable   | 19.80 FL    | *- FL      |
| 59  | 1   |          | *ARM ASSY, REAR SUSPENSION, NO.2 LH    | Serviceable   | 497.50 FL   | *- FL      |
| 60  | 1   |          | *ARM ASSY, UPPER CONTROL, REAR LH      | Serviceable   | 420.80 FL   | *- FL      |
| 61  | 1   |          | *MEMBER SUB ASSY, REAR SUSPENSION      | Serviceable   | 2,245.20 FL | *- FL      |
| 62  | 1   |          | *WIRE, SKID CONTROL SENSOR, LH         | Serviceable   | 94.70 FL    | *- FL      |
| 63  | 1   |          | *TROUGH, BACK DOOR OPENING, LH         | Serviceable   | 103.40 FL   | *- FL      |
| 64  | 1   |          | *SET PARKING AID                       | Dented        | 700.00 FS   | *250.00 FS |
| 65  | 1   |          | *SET REAR BUMPER CLIP                  | Necessary     | 66.00 FS    | *66.00 FS  |
| 66  | 2   |          | *REAR WINDSCREEN SEALANT               | Necessary     | 80.00 FS    | *40.00 FS  |
| 67  | 1   |          | *WINDSCREEN MOULDING                   | Necessary     | 100.00 FS   | *100.00 FS |
| 68  | 1   |          | *REAR WINDSCREEN INNER SPONGE SEAL     | Necessary     | 100.00 FS   | *30.00 FS  |
| 69  | 1   |          | *REAR TAILGATE TOYOTA LOGO             | Necessary     | 47.00 FS    | *47.00 FS  |
| 70  | 1   |          | *REAR TAILGATE WORDING PRIUS           | Necessary     | 52.90 FS    | *52.90 FS  |
| 71  | 1   |          | *REAR TAILGATE WORDING HYBRID          | Necessary     | 53.50 FS    | *53.50 FS  |
| 72  | 1   |          | *REAR TAILGATE STICKER TRANS-CAB       | Necessary     | 80.00 FS    | *30.00 FS  |
| 73  | 1   |          | *REAR TAILGATE STICKER 6555-3333       | Necessary     | 80.00 FS    | *30.00 FS  |
| 74  | 1   |          | *REAR BUMPER PROTECTOR                 | Serviceable   | 100.00 FS   | *- FS      |
| 75  | 1   |          | *REAR WHEEL RIM                        | Serviceable   | 1,570.55 FS | *- FS      |
| 76  | 1   |          | *REAR TYRE 195/65/15                   | Serviceable   | 350.00 FS   | *- FS      |
| 77  | 1   |          | *REAR WHEEL RIM COVER                  | Serviceable   | 175.80 FS   | *- FS      |
| 78  | 1   |          | *SET REAR LH FENDER LINER CLIP         | Not Necessary | 35.00 FS    | *- FS      |
| 79  | 1   |          | *SET BUMPER RETAINER LH CLIP           | Not Necessary | 20.00 FS    | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                  |                 |
|--|------------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>25,322.75</b> | <b>6,579.40</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$)</b> | 5,428.00         | 1,470.00        |
| <b>Total Parts (\$)</b>                                  | <b>19,894.75</b> | <b>5,109.40</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's       | Amount          |
|---------------------------------|--|----------|------------------|-----------------|
| <b>Labour Items</b>             |  |          |                  |                 |
| 1                               | TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.  | New      | 170.00           | 60.00           |
| 2                               | PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. | New      | 7,500.00         | 1,200.00        |
| 3                               | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.  | New      | 7,500.00         | 1,100.00        |
| 4                               | TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.   | New      | 170.00           | 0.00            |
| 5                               | TO RUST-PROOFING OF THE AFFECTED AREAS.  | New      | 170.00           | 90.00           |
| 6                               | TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.  | New      | 170.00           | 120.00          |
| 7                               | TO REINSTALL REAR BUMPER PARKING SENSOR.   | New      | 170.00           | 50.00           |
| 8                               | TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.   | New      | 170.00           | 0.00            |
| 9                               | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.   | New      | 220.00           | 0.00            |
| 10                              | TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.   | New      | 170.00           | 0.00            |
| 11                              | TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.}   | New      | 380.00           | 100.00          |
| 12                              | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.}                          | New      | 380.00           | 0.00            |
| 13                              | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.  | New      | 380.00           | 0.00            |
| 14                              | TO CHECK ELECTRICAL LIGHTING CONCERNED.  | New      | 170.00           | 20.00           |
| 15                              | TOWING FEES.   | New      | 170.00           | 0.00            |
| 16                              | TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.   | New      | 380.00           | 0.00            |
| 17                              | TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING.                    | New      | 380.00           | 0.00            |
| 18                              | TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.   | New      | 380.00           | 0.00            |
| 19                              | TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.        | New      | 380.00           | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>19,410.00</b> | <b>2,740.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >