

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/AIG19020190/GEA3Q2

Date:

11/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SKZ4934L

Policy No:

Insured Vehicle No :

GBD6387A

Date of Loss: 07/07/2019

Nature of Claim:

TP

Claim No:

0031992215SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKZ4934L**

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)

Engine No:

HRA2225236A

Reg. Date: 25/01/2016 (Man. Year: 2015)

Chassis No:

SJNFEAJ11U1561649

Colour: White

Odometer:

44470 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size:

215/60 R17

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,996.18	1,700.37	2,295.81	57.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,000.00	900.00	47.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,896.18	2,700.37	3,195.81	54.20
Approved Total (Overridden) (S\$)		2,150.00		

(S\$)	5,896.18	2,150.00	3,746.18	63.54
+ GST 7.00/7.00% (S\$)	412.73	150.50	262.23	63.54
Nett Amount (S\$)	6,308.91	2,300.50	4,008.41	63.54
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		2,660.50		

INSPECTION

Date of Assignment: 21/11/2019

Date Inspected: 21/11/2019

Inspected At:

Hock Wah Motor Workshop Pte Ltd (Bedok)
 Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
 Singapore 489977

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Buckled	1,104.80 FL	*1,104.80 FL
2	1		*REAR DOOR STICKER LH	Necessary	35.90 FL	*35.90 FL
3	1		*REAR DOOR LOCK LH	Not Necessary	166.70 FL	*- FL
4	1		*REAR DOOR PROTECTOR LH	Deformed	264.80 FL	*264.80 FL
5	2		*REAR DOOR OUTER CHROME LH	Not Necessary	377.80 FL	*- FL
6	1		*REAR DOOR OUTER HANDLER ASSEMBLY LH	Not Necessary	165.80 FL	*- FL
7	1		*REAR DOOR INNER BRACKET LH	Not Necessary	85.60 FL	*- FL
8	1		*REAR DOOR REGULATOR GEAR WITH MOTOR LH	Not Necessary	487.90 FL	*- FL
9	1		*REAR DOOR TRIMBOARD LH	Not Necessary	1,267.10 FL	*- FL
10	1		*REAR FENDER PROTECTOR LH	Scratched	483.80 FL	*483.80 FL
11	1		*REAR FENDER LH (NPA)	Repair	0.00 FS	*- FS
12	1		*FRONT DOOR LH (NPA)	Repair	0.00 FS	*- FS
13	1		*ROCKER PANEL LH (NPA)	Repair	0.00 FS	*- FS
					Sub Total (S\$)	4,440.20
					- List Item Discount on L Items 10.00/10.00% (S\$)	444.02
					Total Parts (S\$)	3,996.18
						1,889.30
						1,700.37

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	500.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	500.00
3	ANTI-RUST COATING	New	200.00	0.00
Gross Labour Cost (\$\$)			1,900.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >