

ASS. REC. BY:

REF: CS/FC119020231/Ksf3ⁿ²

Special Instruction:

(LWS) SURVIVOR: Kenneth ASSIGNMENT (Office)From (Person): Joanny of FC1 Date/Time: 14.11.19 2.24pm

Estimated Cost: _____ Bill to: _____

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 585D Insured: SH 85312at Workshop m/s Edwin Pothmann Tel: 8799 0066of 385 sin ming DrivePolicy No: _____ Claim No: D19006922 MFS4

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29.10.19
(Client's Record)CA / REV / REP. / REV 24 HRS my H.O.D. Endorsement: _____Date/Time: 14.11.19 2.37pm Person Contacted: Carrie Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLK 585D - X
	SH 85312 - CS31FC115020630/GM/612 DUA - 01/12/2015
19/11/19	@ 17:27 pm revised PA to Joanne via email
27/11	81196.95 Confirmed

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 880k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 1.31% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S/K 5850 Yr Regn: 01, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota c.c. 1798Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 282720 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB3FU903539469Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 29/10/19 D.O.I. 18/11/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 27 NOV 2019

Date/Time, File Pass to?

27/11/19

11 Type

Date/Time, File Return to?

☐ : Prel. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum (1.B): (\$ 1,196.95 P/P)

130
50
50
18
248



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D19006922MFSH

Date: 19 November 2019

Our Ref: CS/FCI19020231/Ksf3

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLK 585D

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/11/2019 at the premises of M/s Esteem Performance Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 3,243.83
Revised Estimate Amount	: S\$ 1,196.95
"Check" Items Amount	: S\$ 395.92
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear & front portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 3 days

Yours faithfully

Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	31-10-2019	Our Ref No. D19006922MFSH
Accident Date	29-10-2019	Claim Type. Third Party
Insured Vehicle	SH8537Z	Third Party Vehicle. SLK585D
Survey Location	385, SIN MING DRIVE (INSIDE VICOM)	
Contact Person.	CARMEN LIM	
Contact No.	65662112/ 87990066	Fax No. 62593326
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 19 November 2019 5:27 pm
To: 'Joanne Yong'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19006922MFSH/1
Attachments: PRELI ADVISE - SLK 585D.pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SLK 585D.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 14 November 2019 2:24 pm
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Joanne Yong' <JoanneYong@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006922MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Thursday, 14 November, 2019 2:22 PM



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLK 585 D

Not Authorized
Repair After Pain

Parts	(a) Cost / List Price Items	\$	1,905.10
	Plus/Less 25%	\$	476.28
	Total of Cost / List	\$	1,428.83
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	245.00
Total Parts Cost		\$	1,673.83
Labour		\$	1,570.00
Total		\$	3,243.83

LKK Auto Consultants hereby notify the Repairer of the following:

- To recovery before/after repair painting
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

LKK

Survey conducted on

18/11/19 at

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Le

Date: 18/11/19



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLK 585 D**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU903539469**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		X
3	Rear bumper clip	10	\$40.00		X
4	Rear bumper side retainer LH	1	\$112.70		X
5	Rear bumper side retainer RH	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		X
7	Rear bumper lower garnish centre	1	\$582.60		✓
8	Rear bumper tow cover	1	\$31.70		X
9	Front number plate	1	\$45.00	S.N	✓
10	Front number plate garnish	1	\$129.00		X
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6258 3561 FAX: 6258 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19020231/Ksf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-11-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8537Z	Veh. Inspected	SLK 585D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006922MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	14/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU903539469	Colour	METALLIC SILVER	
Odometer	282720	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/10/2019	Inspection Date	18/11/2019	
Survey held at	385 SIN MING DRIVE			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 585D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	497.50	-
10	REAR BUMPER CLIP	NOT NECESSARY	40.00	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	398.90	-
1	REAR BUMPER LOWER GARNISH CENTRE	DENTED / CRACKED	582.60	582.60
1	REAR BUMPER TOW COVER	SERVICEABLE	31.70	-
1	FRONT NUMBER PLATE GARNISH	SERVICEABLE	129.00	-
	LESS 25% DISCOUNT		-476.28	-145.65
			1,428.82	436.95
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
1	FRONT NUMBER PLATE (SN)	BENT	45.00	45.00
			245.00	45.00
LABOUR				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,END PANEL,TAILDOOR).INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		600.00	300.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,END PANEL,TAILDOOR).		600.00	400.00
	TO CHECK WIRING.		50.00	15.00
	TO REMOVE & REFIT REVERSE SENSOR.	NOT NECESSARY	120.00	-
	TO TUFF COAT.	NOT NECESSARY	50.00	-
	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
			1,570.00	715.00
GRAND TOTAL			3,243.82	1,196.95
RECOMMENDED COST OF REPAIRS				1,196.95

Report Ref No. CS/FCI19020231/Ksf3n2



Report Ref No. CS/FCI19020231/Ksf3n2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.