Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19020234/KDA3Q2

Date: 03/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SHD498G Insured Vehicle No: SKK6749X

Vehicle No:

Date of Loss: ΤP 05/11/2019 Nature of Claim: Claim No: 3467099155SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHD498G Reg No:

RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR Engine No: Make & Model: M9R8839C003104

17/11/2017 (Man. Year: 2016) Reg. Date: Chassis No: VF1ABL15AUC283432

Colour: Metallic White/Red Odometer: 234767 km

1995 cc **Engine Capacity:** Market Value/New Car

N/A Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Sailun 8 mm Rear Left Side: Giti 7 mm Front Right Side: Rear Right Side: Giti 7 mm Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,454.35	3,264.12	7,190.23	68.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,510.00	1,010.00	13,500.00	93.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,964.35	4,274.12	20,690.23	82.88
+ GST 7.00/7.00% (S\$)	1,747.50	299.19	1,448.31	82.88
Nett Amount (S\$)	26,711.85	4,573.31	22,138.54	82.88
+ Car Rental (3.0 x S	\$103.60/day) (S\$)	310.80		
+ Doo	/Search Fee (S\$)	7.49		

INSPECTION

Date of Assignment: 07/11/2019

Trans-cab Auto Services Pte Ltd Date Inspected: 07/11/2019 Inspected At:

Nett Liability (S\$)

No 2 Ang Mo Kio Street 63

Singapore 569111

4,891.60

Estimated Period of Repair: 2.5 days

Adjuster: KENNETH KONG Manager: CHAN JIA LE Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented / Distorted	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*-FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*-FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*-FL
6	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*-FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*-FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*-FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*-FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*-FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	*-FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	313.10 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*-FL
17	1		*TAILLAMP LH	Serviceable	401.40 FL	*-FL
18	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
19	1		*BOOT REAR	Bent	1,677.20 FL	*1,677.20 FL
20	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*-FL
24	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
25	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
26	1		*BOOT STRUT LH	Serviceable	145.10 FL	*-FL
27	1		*BOOT STRUT RH	Serviceable	145.10 FL	*-FL
28	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
29	1		*BOOT HINGE RH	Repair	253.80 FL	*- FL
30	2		*BOOT RUBBER PLUG	Serviceable	139.90 FL	*-FL
31	2		*BOOT BUFFER	Serviceable	26.80 FL	*- FL
32	1		*BOOT LOCK LINKAGE	Serviceable	20.60 FL	*-FL
33	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
34	1		*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	*-FL
35	1		*BOOT SWITCH	Serviceable	113.00 FL	*-FL
36	1		*BOOT LOCK	Repair	246.60 FL	*-FL
37	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
38	1		*EXHAUST CAP REAR	Serviceable	125.40 FL	*-FL
39	1		*SET PARKING AID	Serviceable	700.00 FS	*-FS
40	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
41	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
42	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
43	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
44	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
45	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
46	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
47	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
48	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
49	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
50	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
51	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
52	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
53	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
			Report was unsubmitted during			

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS
55	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS
56	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
57	1		*REAR BUMPER PROTECTOR	No such part	100.00 FS	*-FS
58	1		*EXHAUST MOUNTING REAR	Serviceable	16.00 FS	*-FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	11,451.26	3,601.80
- List Item Discount on L Items 10.00/10.00% (S\$)			996.91	337.68		
				Total Parts (S\$)	10,454.35	3,264.12
			Report was unsubmitted during	his print-out.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items			-		
1	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00		
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00		
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00		
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00		
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00		
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00		
7	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	6,000.00	400.00		
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00		
9	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00		
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00		
11	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00		
12	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00		
13	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00		
14	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00		
	Gross Labou	14,510.00	1,010.00			
	Panort was unsubmitted durin	na this print-out				
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >