

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Oct 2020 16:23		01 Oct 2020 17:34 Edit Adj Rpt	S\$3,248.40 Edit Estimates	S\$3,248.40 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LOGISTIX PTE LTD, Co. Reg. No.: -		
Main Claimant:	WATARU TOMIKAWA, ID: -		
Vehicle Reg. No.:	SLU4447R	Date of Loss:	07/11/2019 00:00 - :59 [23 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D205342/C02/LEWLC	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SMC5843G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close, 408605 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jenny Lew]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/10/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU4447R (SNM19D205342/C02/LEWLC)
[SMC5843G]
TP
WATARU TOMIKAWA
Nov 7 2019 12:00AM
[LOGISTIX PTE LTD]
Trans Eurokars Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/10/20 11:00	Odometer Reading	Load JPG	☒
2	02/10/20 11:00	Chassis Number	Load JPG	☒
3	02/10/20 11:00	General View	Load JPG	☒
4	02/10/20 11:00	General View	Load JPG	☒
5	02/10/20 11:00	General View	Load JPG	☒
6	02/10/20 11:00	General View	Load JPG	☒
7	02/10/20 11:00	General View	Load JPG	☒
8	02/10/20 11:00	General View	Load JPG	☒
9	02/10/20 11:00	General View	Load JPG	☒
10	02/10/20 11:00	General View	Load JPG	☒
11	02/10/20 11:00	General View	Load JPG	☒
12	02/10/20 11:00	General View	Load JPG	☒
13	02/10/20 11:00	General View	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI19020248/GYD3S2**Date:** 07/10/2020**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No:

Claimant Vehicle No : SLU4447R **Insured Vehicle No :** SMC5843G

Date of Loss: 07/11/2019 Nature of Claim: TP Claim No: SNM19D205342/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU4447R**

Make & Model: MAZDA 3, 1.5 (A) Engine No: P520486659

Reg. Date: 01/12/2017 (Man. Year: 2017) Chassis No: JM6BN22A8J0194498

Colour: Blue Odometer: 26572 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,139.70	1,298.40	841.30	39.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	1,950.00	1,810.00	48.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,899.70	3,248.40	2,651.30	44.94
+ GST 7.00/7.00% (\$\$)	412.98	227.39	185.59	44.94
Nett Amount (\$\$)	6,312.68	3,475.79	2,836.89	44.94

INSPECTION

Date of Assignment: 01/10/2020

Date Inspected: 19/11/2019 Inspected At: Trans Eurokars Pte Ltd (Ubi)
5 Ubi Close
Singapore 408605

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

10/7/2020

Adjuster Report

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$569.60 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2020)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU4447R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,128.60 F	*1,128.60 F
2	1		*BRACKET CENTER	*Check	5.40 F	*- F
3	1		*REAR REINFORCEMENT	*Check	564.20 F	*- F
4	2		*RETAINER CENTER, SENSOR	Necessary	36.40 F	*36.40 F
5	1		*SENSOR CENTER, ULTRASONIC	Not Necessary	181.70 F	*- F
6	3		*TAPE PORTECTOR, SENSOR	Necessary	25.80 F	*25.80 F
7	4		*FASTENER, REAR BUMPER	Necessary	12.00 F	*12.00 F
8	2		*CLIP, REAR BUMPER	Necessary	6.80 F	*6.80 F
9	4		*GROMMET, REAR BUMPER	Necessary	10.80 F	*10.80 F
10	2		*GROMMET, REAR BUMPER	Necessary	6.00 F	*6.00 F
11	4		*RIVET, REAR BUMPER	Necessary	18.00 F	*18.00 F
12	1		*GASKET LHS, TAILLAMP	Necessary	22.00 F	*22.00 F
13	1		*GASKET RHS, TAILLAMP	Necessary	22.00 F	*22.00 F
14	1		*SUNDRIES	Necessary	100.00 FS	*10.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,139.70	1,298.40
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	New	1,320.00	660.00
2	TO RESPRAY FRONT BUMPER AND FRONT REINFORCEMENT.	New	1,260.00	630.00
3	TO TRANSFER REVERSE SENSORS.	New	330.00	330.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	New	250.00	0.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	250.00	150.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	350.00	180.00
7	TO SUPPLY BODY COATING. (NPA)	New	0.00	0.00
Gross Labour Cost (\$\$)			3,760.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >