

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119020268/KTD3E2

Date: 20/05/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN16702319033

Claimant Vehicle
No : SLH3711CInsured
Vehicle No : XD9590Z

Date of Loss: 23/10/2019

Nature of
Claim: TPClaim
No: SNM19D205049-
XD9590Z-BEN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH3711C

Make & Model: NISSAN SYLPHY, 1.6 (A)

Engine No: HR16993496B

Reg. Date: 31/10/2016 (Man. Year: 2016)

Chassis No: MNTBBAB17Z0027942

Colour: Metallic Red

Odometer: 76432 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16

Rear Tyre Size:

205/55Z R16

Front Left Side: Hankook 9 mm

Rear Left Side:

Hankook 9 mm

Front Right Side: Hankook 9 mm

Rear Right Side:

Hankook 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	425.00	425.00	0.00	0.00
Miscellaneous Items	142.00	142.00	0.00	0.00
Paintwork Materials	195.37	195.37	0.00	0.00
Labour	184.80	100.80	84.00	45.45
Paintwork Labour	453.60	453.60	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,400.77	1,316.77	84.00	6.00
+ GST 7.00/7.00% (S\$)	98.05	92.17	5.88	6.00
Nett Amount (S\$)	1,498.82	1,408.94	89.88	6.00

INSPECTION

Date of Assignment: 22/11/2019 Present Location:

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 02/12/2019 Inspected At:

S & H Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #07-02, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 May 2020)
Parts:	143	NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH3711C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		315.00 F	*315.00 F
<u>Supplementary #1</u>						
2	1		*LH front door mirror cover	Dented	110.00 F	*110.00 F
Total Parts (S\$)						425.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	Paintwork material	195.37	195.37
<u>Miscellaneous Items</u>				
2	1	Misc	142.00	142.00
Sub Total (\$\$)			337.37	337.37

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Labour for paintwork	New	453.60	453.60
<u>Labour Items</u>				
2	Labour for panel/mechanical	New	184.80	100.80
Gross Labour Cost (\$\$)			638.40	554.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >