# LKK Auto Consultants #01-25 Paya Ubi Industrial Park, 51 Ubi Avenue 1 408933

Insurer Reference: 19/5049/OD Repairer Reference: 022100

Date calculated: 16/04/2020 4:12 PM

Full Report Registration: SLH3711C Printed: 16/04/2020 4:12 PM

## **Summary Information**

Claim

Location: Singapore (SG) Work Provider: China Taiping Insurance

(Singapore) Pte Ltd

Printed by: Claim Reference: KK LAU 19/5049/OD Currency: Date of Incident: Hire Car Start:

Hire Car End:

SGD 23/10/19

Estimated Repair Time: Actual Repair Days:

### **Vehicle Details**

Vehicle

Manufacturer: NISSAN

Model: SYLPHY (B17T)
Sub Model: BASE MODEL
Model Sheet Number: 71 PT 01
Registration: SLH3711C

VIN number: Odometer: **Model Specs** 

TWO COAT METALLIC PREPARE OFF VEHICLE


#### **Vehicle Condition**

#### **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

### **Damage Areas**

All



# Labour

Time Base 10 WU/h		Price = 42.00 SGD/h	
Description	•	WU	Price SGD
R + R LEFT SIDE FLASHER LAMP	:	2.0	8.40
R + R L/OUTSIDE MIRROR INCLUDES: R + R FRONT DOOR TRIM	:	2.0	8.40
L/F WING REPAIR	10.	.0*	42.00
LEFT FRONT DOOR REPAIR	10.	.0*	42.00
Labour Cost			100.80
·	2.40 2	4.0	100.80
	R + R LEFT SIDE FLASHER LAMP R + R L/OUTSIDE MIRROR INCLUDES: R + R FRONT DOOR TRIM L/F WING REPAIR LEFT FRONT DOOR REPAIR	R + R LEFT SIDE FLASHER LAMP R + R L/OUTSIDE MIRROR INCLUDES: R + R FRONT DOOR TRIM L/F WING REPAIR  LEFT FRONT DOOR REPAIR  Labour Cost Panel / Mechanical Labour  Panel / Mechanical Labour	DescriptionWUR + R LEFT SIDE FLASHER LAMP2.0R + R L/OUTSIDE MIRROR2.0INCLUDES: R + R FRONT DOOR TRIML/F WING REPAIR10.0*LEFT FRONT DOOR REPAIR10.0*Labour Cost Panel / Mechanical LabourHrs 2.40WU 24.0

## **Paint**

Pailit	0.000000	=
Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	L/DOOR MIRROR HSG NEW PART PAINT K1R	3.0
	L/F WING REPAIR PAINTING >50%	17.0
	LEFT FRONT DOOR REPAIR PAINTING >50%	27.0
	FRONT BUMPER SURFACE PAINT PLAST.	11.0
	BONNET SURFACE PAINT	8.0
	L/R DOOR SURFACE PAINT	7.0
	L/OUTER DOOR SILL SURFACE PAINT	5.0

# **Paint Material Per Part**

Code	Description	Price SGD
1745	L/DOOR MIRROR HSG NEW PART PAINT K1R	2.46
0741	L/F WING REPAIR PAINTING >50%	16.59
1481	LEFT FRONT DOOR REPAIR PAINTING >50%	38.71
0281	FRONT BUMPER SURFACE PAINT PLAST.	52.70
0471	BONNET SURFACE PAINT	21.17
1781	L/R DOOR SURFACE PAINT	19.42
2101	L/OUTER DOOR SILL SURFACE PAINT	6.72

Labour Cost - Paint		Hrs	WU	<b>Price SGD</b>
Factor	42.00 SGD/h			
Time Paint			78.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.50	5.0	21.00
Total	10 WU/h	10.80	108.0	453.60

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	2.46
Repair Painting	55.30
Surface-/Blend Paint	47.31
Surface Painting Plastic	52.70
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	195.37

# **Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01 Price SGD
1737	L/DOOR MIRROR	96302 3ST0C		280.00
1745	L/DOOR MIRROR HSG	K6374 3RA0A		110.00
0707	L/SIDE REPEATER LAMP	26160 8990A		35.00
f: OEM Parts n: Non-OEM Parts u: Used parts	Savings Subtotal Fixed Sundry Parts	Price		0.00 425.00 100.00
	Total			525.00

## **Extras**

Code	Description	Price SGD
1000	Audatex fees Audatex fees	42.00*
	Total Extras	42.00

#### Final Calculation

	SGD	SGD
Parts	425.00	
Fixed Sundry Parts Price	100.00	
Total Parts		525.00
Labour Time Base 10 WU/h		
Total 24.0 WU X 42.00 SGD/h	100.80	
Total of Labour		100.80
Total Of Extras		42.00
Paint Work Time Base 10 WU/h		
Labour Cost 108.0 WU X 42.00 SGD/h	453.60	
Material Cost	195.37	
Total Paint Including Material		648.97
Repair Cost Excludes GST		1,316.77
GST (+7.0%)		92.17
Repair Cost Included GST		1,408.94

#### Comments

\* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS

### **Assessment Note**

No assessment notes entered.