

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19020271/GKA3Q2

Date: 07/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800077015

Claimant
Vehicle No : SLS4176H **Insured Vehicle No :** SMC2473K

Date of Loss: 12/11/2019 Nature of Claim: TP Claim No: 8280289060SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS4176H	Engine No:	CZC161756
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI (A)	Chassis No:	WVWZZZAUZH119316
Reg. Date:	24/08/2017 (Man. Year: 2016)	Odometer:	18572 km
Colour:	Silver		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,710.50	5,171.72	3,538.78	40.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,110.00	8,350.00	5,760.00	40.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	22,820.50	13,521.72	9,298.78	40.75
+ GST 7.00/7.00% (\$\$)	1,597.44	946.52	650.92	40.75
Nett Amount (\$\$)	24,417.94	14,468.24	9,949.70	40.75
+ Car Rental (9.0 x S\$80.00/day + 7.00% GST) (\$\$)		770.40		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		15,240.64		

INSPECTION

Date of Assignment: 20/11/2019

Date Inspected: 20/11/2019 Inspected At:

1 KAMPONG AMPAT OFF
MACPHERSON ROAD
REPAIRER: VOLKSWAGEN GROUP
SINGAPORE PTE LTD

Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID	Buckled	1,853.05 FS	*1,853.05 FS
2	2		*1K WINDOW ADHESIVE	Necessary	99.76 FS	*99.76 FS
3	1		*ADHESIVE REMOVER	Necessary	115.74 FS	*115.74 FS
4	1		*PRIMER	Necessary	25.92 FS	*25.92 FS
5	2		*APPLICATOR	Necessary	18.96 FS	*18.96 FS
6	1		*ACTIVATOR FOR PRECOATED W	Necessary	24.00 FS	*24.00 FS
7	2		*GROMMET	Not Necessary	28.58 FS	*- FS
8	1		*OPER MECHAH WITH MICRO SW	Not Necessary	1,760.35 FS	*- FS
9	1		*INSCRIPTION BRIGHT CHROME GOLF	Necessary	66.63 FS	*66.63 FS
10	1		*GASKET WEATHERSTRIP	Twisted	238.16 FS	*238.16 FS
11	1		*HOOD LATCH SATIN BLACK LOCK	Not Necessary	359.59 FS	*- FS
12	1		*STRIKER PLATE LATCH	Not Necessary	49.44 FS	*- FS
13	1		*ADDITIONAL BRAKE LIGHT WI	Necessary	155.54 FS	*155.54 FS
14	1		*COVER FOR BUMPER PRIMED REAR BUMPER	Deformed	1,080.14 FS	*1,080.14 FS
15	1		*REAR DIFFUSOR SATIN BLACK	Cut	277.23 FS	*277.23 FS
16	1		*SENSOR BRACKET	Necessary	13.21 FS	*13.21 FS
17	1		*SENSOR BRACKET	Necessary	13.21 FS	*13.21 FS
18	1		*SENSOR BRACKET	Necessary	13.21 FS	*13.21 FS
19	1		*SENSOR BRACKET	Necessary	13.21 FS	*13.21 FS
20	1		*SENSOR PRIMED	Not Necessary	164.62 FS	*- FS
21	1		*SEAL RING SATIN BLACK	Not Necessary	1.18 FS	*- FS
22	1		*2K-PLASTIC ADHESIVE	Necessary	74.29 FS	*74.29 FS
23	1		*BONDING AGENT FOR PLASTIC	Necessary	56.90 FS	*56.90 FS
24	4		*RIVET	Necessary	4.36 FS	*4.36 FS
25	1		*BUMPER REINFORCEMENT	Not Necessary	572.31 FS	*- FS
26	1		*ATTACHMENT STRIP RR CTR BRACKET	Necessary	59.89 FS	*59.89 FS
27	1		*GUIDE PIECE LHR TAILLIGHT BRACKET	Not Necessary	34.51 FS	*- FS
28	1		*GUIDE PIECE RHR TAILLIGHT BRACKET	Not Necessary	34.51 FS	*- FS
29	1		*GUIDE PIECE LHR SIDE BRACKET	Not Necessary	34.51 FS	*- FS
30	1		*GUIDE PIECE RHR SIDE BRACKET	Not Necessary	34.51 FS	*- FS
31	1		*REFLECTOR LHR	Not Necessary	68.93 FS	*- FS
32	1		*REFLECTOR RHR	Not Necessary	68.93 FS	*- FS
33	2		*LICENSE PLATE LIGHT	Not Necessary	74.38 FS	*- FS
34	1		*TAILLIGHT LHR INNER	Scratched	252.43 FS	*252.43 FS
35	1		*TAILLIGHT WITH REAR FOG L RHR INNER	Not Necessary	252.43 FS	*- FS
36	1		*END PLATE	Buckled	112.33 FS	*112.33 FS
37	1		*INOX -SRPAY	Necessary	62.88 FS	*62.88 FS
38	1		*2K-BODY ADHESIVE	Necessary	398.47 FS	*398.47 FS
39	1		*SEALANT CAN BE SPRAYED	Necessary	62.20 FS	*62.20 FS
40	1		*NUMBER PLATE	Bent	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **8,710.50** **5,171.72**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	5,880.00	3,360.00
2	TRANSFER BOOTLID MECHANISM	New	840.00	420.00
3	R&R REAR WINDSCREEN	New	840.00	840.00
4	R&R LUGGAGE COMPARTMENT	New	840.00	420.00
5	CHECK WATER LEAK	New	150.00	150.00
6	SPRAY PAINTING	New	4,800.00	2,400.00
7	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
8	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
Gross Labour Cost (\$\$)			14,110.00	8,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >