

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19020293/AEA3Q2

Date: 08/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100169804

Claimant
Vehicle No : SGV6663Z **Insured Vehicle No :** GBB6703G

Date of Loss: 13/11/2019 Nature of Claim: TP Claim No: 6270127380SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV6663Z		
Make & Model:	TOYOTA ESTIMA, 2.4 AERAS (A)	Engine No:	2AZF033057
Reg. Date:	02/07/2007 (Man. Year: 2007)	Chassis No:	ACR500037081
Colour:	Silver	Odometer:	196303 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,029.12	2,825.37	1,203.75	29.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	730.00	1,470.00	66.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,229.12	3,555.37	2,673.75	42.92
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	6,229.12	2,800.00	3,429.12	55.05
+ GST 7.00/7.00% (S\$)	436.04	196.00	240.04	55.05
Nett Amount (S\$)	6,665.16	2,996.00	3,669.16	55.05
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,403.45		

INSPECTION

Date of Assignment: 13/11/2019

Date Inspected: 13/11/2019 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	110.00 FL	*65.00 FL
2	1		*HEADLAMP (HID) RH	Cracked	1,985.50 FL	*1,985.50 FL
3	1		*FRONT FENDER RH	Repair	720.00 FL	*- FL
4	1		*FRONT FENDER EMBLEM VVT-I	Necessary	90.00 FL	*90.00 FL
5	1		*FRONT FENDER INNER COWLING	Not Necessary	280.00 FL	*- FL
6	1		*FRONT BUMPER	Deformed	1,600.00 FS	*1,200.00 FS
7	1		*SET FRONT BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
8	1		*SET FRONT FENDER INNER COWLING CLIPS	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,825.50	3,360.50
- List Item Discount on L Items 25.00/25.00% (\$)	796.38	535.13
Total Parts (\$)	4,029.12	2,825.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,000.00	300.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	400.00
3	TUFF COAT	New	120.00	0.00
4	WIRING CHECK	New	80.00	30.00
Gross Labour Cost (\$\$)			2,200.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >