Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

CC3/III19020310/R1GS3Q2 Our File No:

Date: 22/09/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SKT2993K Insured Vehicle No: SHC3055L

Vehicle No:

Date of Loss: Nature of Claim: TP 11/11/2019 Claim No: MCT19110259

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SKT2993K** Reg No:

KIA FORTE K3, 1.6 (A) Make & Model: Engine No: G4FGFH776524 Chassis No: Reg. Date: 29/05/2015 (Man. Year: 2015) KNAFX411MF5448499 Odometer: 113002 km

Colour: Grey

**Engine Capacity:** 1591 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Front Left Side: Roadstone 6 mm Rear Left Side: Roadstone 6 mm Front Right Side: Rear Right Side: Roadstone 6 mm Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,885.00	1,607.00	278.00	14.75
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,390.00	1,350.00	1,040.00	43.51
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	4,275.00	2,957.00	1,318.00	30.83
	+ GST 7.00/7.00% (S\$)	299.25	206.99	92.26	30.83
	Nett Amount (S\$)	4,574.25	3,163.99	1,410.26	30.83
	. O Dt-l (0 0 00400 00/d		204.00		

+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$) 321.00

> **Nett Liability (S\$)** 3.484.99

**INSPECTION** 

Date of Assignment: 20/07/2020

Cycle & Carriage KIA Pte Ltd (Pandan Date Inspected: 20/07/2020 Inspected At:

Gardens)

209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Sep 2020)

Parts: 143 KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKT2993K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Donairer's

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts

NO.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*COVER -RR BUMPER ,UPR	Deformed	234.00 FS	*234.00 FS
3	1		*COVER -RR BUMPER	Deformed	768.00 FS	*768.00 FS
4	1		*COVER -RR BPR UNDER	Not Necessary	42.00 FS	*- FS
5	1		*BEAM -RR BUMPER	Damaged	365.00 FS	*365.00 FS
6	1		*BRACKET -RR BEAM LWR MTG	Not Necessary	5.00 FS	*- FS
7	1		*BRACKET -RR BEAM LWR CTR	Not Necessary	5.00 FS	*- FS
8	1		*BRACKET -RR BEAM LWR MTG	Not Necessary	5.00 FS	*- FS
9	1		*BRACKET -RR RAIL UPR MTG ,LH	Not Necessary	4.00 FS	*- FS
10	1		*BRACKET -RR RAIL UPR MTG ,RH	Not Necessary	4.00 FS	*- FS
11	1		*STAY -RR BUMPER LH	Not Necessary	75.00 FS	*- FS
12	1		*STAY -RR BUMPER RH	Not Necessary	75.00 FS	*- FS
13	1		*BRACKET -RR BUMPER SIDE MTG ,LH	Not Necessary	33.00 FS	*- FS
14	1		*REPLACE REVERSE SENSOR	Not Working	220.00 FS	*220.00 FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	1,885.00	1,607.00

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO RENEW REAR BUMPER ,REAR BUMPER LOWER & AFFECTED AREA	New	1,100.00	550.00
2	PAINT WORK ON REAR BUMPER PANEL	New	840.00	420.00
3	TO REMOVE & INSTALL REAR PARKING ASSIST	New	150.00	120.00
4	TO APPLY BODY SEALANT	New	40.00	0.00
5	CHECK ELECTRICAL SYSTEM	New	80.00	80.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	180.00	180.00
	Gross Labo	2,390.00	1,350.00	
	Report was unsubmitted duri	ing this print-out.		

< END OF ESTIMATES >