



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Malakar Rina	Cust No/Name /Malakar Rina
3 CARMEN TERRACE	Reg No/Reg Date SKT2993K / 29/05/201
459682	Date In/Mileage / 0
Contact No Mobile: 96345034	Chassis No KNAFX411MF5448499
	Engine No G4FGFH776524
	Make/Model KIA/FORTE K3 1.6 A EX W/ LED & D.BR
	Colour/Trim 4SS / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CSM00081	Cash	15/11/2019/ 09:35	QUK	282 / Kevin Leong	61940				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	TO RENEW REAR BUMPER, REAR BUMPER LOWER & AFFECTED AREA					550	1100.00		
E PNT98000	PAINT WORK ON REAR BUMPER PANEL					420	840.00		
E PNT88000	TO REMOVE & INSTALL REAR PARKING ASSIST					120	150.00		
M SUNDRY	TO APPLY BODY SEALANT					NN	40.00		
A 54900099	CHECK ELECTRICAL SYSTEM						80.00		
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST						180.00		
	USING HI-SCAN PRO TEST					20	50.00		
M SUNDRY	SUNDRIES								
M COVER-RR BUMPER, UPR	de					1.00	234.00	00.00	234.00
M COVER-RR BUMPER	de					1.00	768.00	00.00	768.00
M COVER-RR BPR UNDER?						1.00	42.00	00.00	NN 42.00 X
M BEAM-RR BUMPER						1.00	365.00	00.00	DAM 365.00 ✓
M BRACKET-RR BEAM LWR MTG						1.00	5.00	00.00	NN 5.00 X
M BRACKET-RR BEAM LWR, CTR						1.00	5.00	00.00	NN 5.00 X
M BRACKET-RR BEAM LWR MTG						1.00	5.00	00.00	NN 5.00 X
M BRACKET-RR RAIL UPR MTG, LH						1.00	4.00	00.00	NN 4.00 X
M BRACKET-RR RAIL UPR MTG, RH						1.00	4.00	00.00	NN 4.00 X
M STAY-RR BUMPER LH						1.00	75.00	00.00	NN 75.00 X
M STAY-RR BUMPER RH						1.00	75.00	00.00	NN 75.00 X
M BRACKET-RR BUMPER SIDE MTG, LH						1.00	33.00	00.00	NN 33.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

SURVEYOR NAME: RASUL - 4p 90000568

SURVEYOR SIGNATURE: [Signature]

DATE: 20/07/2020 @ 1110

REMARKS: 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Date: 1.00 234.00 00.00
 1.00 768.00 00.00
 1.00 42.00 00.00
 1.00 365.00 00.00
 1.00 5.00 00.00
 1.00 5.00 00.00
 1.00 5.00 00.00
 1.00 4.00 00.00
 1.00 4.00 00.00
 1.00 75.00 00.00
 1.00 75.00 00.00
 1.00 33.00 00.00

SURVEYOR NAME: RASUL - 4p 200w68
 SURVEYOR SIGNATURE: [Signature]
 DATE: 20/07/2020 @ 1110
 REMARKS: 3 days

Confirm & accepted by

Reay before paint

7% GST on **Nett** 4,055.00
 4055.00 283.85

Total Payable 4,338.85

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.