

ASS. REC. BY:

REF:

es/FCI19020314/Kydb

N2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

355pm @ 15/11/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SHD 2872

Insured:

SH 6297D

at Workshop m/s

Translab

Tel:

62876666

of

NO. 2 Amk St - 63

Policy No:

Claim No:

D19007233 MPST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/11/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:11pm @ 15/11/19

Person Contacted:

zhennet

Vehicle: IN/OUT

Date/Time	Action/Instruction	Signature
	SHD 2872 - CC3 / FCI 14021129 / Kyb12	DVA: 28/7/2014
	SH 6297D - CC3 / FCI 3011929 / Cgk3	DVA: 29/10/2013
22/11/19	Sent Prel: by email	

ASS. REC. BY:

REF: FCZ/Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

1 1/2 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: S140 2877Yr Regn: 03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Merault101704 c.c. 1995Colour: White / Red

A/C: Insured / Std / NI / NA

Sp. Reading: 402379

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABL 15 AUC 28 2201Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

215/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Giti

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 9/11/19D.O.I. 18/11/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
6/5/19

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to11 Sep @ 1200h (Red \$25,766-53, 95%)

RECEIVED 20 NOV 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

26/11/19 TypistDays Of Repair: 1 1/2 dayResurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + PS. \$

Fees

Others

TOTAL

350

Report Format:

Lump Sum I.B.I. (\$

\$1200f



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007233MFSH

Date: 22 Nov 2019

Our Ref: CS/FCI19020314/Kyd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD287Z .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/11/2019 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>26,966.53</u> .
Revised Estimate Amount	: S\$ <u>1,479.74</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at the o/s front.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	15-11-2019	Our Ref No. D19007233MFSH
Accident Date	09-11-2019	Claim Type. Third Party
Insured Vehicle	SH6297D	Third Party Vehicle. SHD287Z
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Yvonne Wong (LKK Auto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, November 22, 2019 4:28 PM
To: Yvonne Wong (LKK Auto)
Cc: 'Jasmine Tan'
Subject: FW: VEHICLE NO: SHD287Z DOA: 09/11/2019 -- AAD1911-113
Attachments: SHD287Z ESTIMATE.pdf

Dear Yvonne

Amount confirmed \$ 1,200 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Yvonne Wong (LKK Auto) [mailto:yvonnewong@lkkauto.com]
Sent: Friday, 22 November, 2019 4:17 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: jasminetan@transcab.com.sg
Subject: VEHICLE NO: SHD287Z DOA: 09/11/2019

Hi Wai Yin

I check and confirm is L/S \$1200.00 @ 1.5 days repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, November 22, 2019 3:42 PM
To: 'CWS Motor Claims'
Cc: 'Joanne Yong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19007233MFSH/1
Attachments: SHD287Z DOA 09112019 REVERT.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SHD287Z
Date of survey : 18/11/2019
Number of days : 1.5 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, November 15, 2019 4:30 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007233MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Friday, 15 November 2019 3:55 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007233MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD287Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Nov 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002735
Chassis No.:	VF1ABL15AUC282201
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	04 Mar 2016
First Registration Date:	04 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Mar 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	03 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,633.00
COE Rebate Amount:	\$21,322.00
Total Rebate Amount:	\$36,320.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Nov 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 287Z**AAD1911-113**

1	BONNET HINGE RH	\$	R	237.40	}	X
1	BONNET LOCK	\$	R	152.80		
1	BONNET CABLE	\$	Sh	55.20		
1	BONNET CABLE COVER	\$	Sh	80.60		
1	BONNET SEAL OUTER	\$	Sh	83.20		
1	BONNET SEAL INNER	\$	Sh	70.10		
1	LOWER ARM RH L70Y	\$	Sh	192.70		
1	KNUCKLE ARM RH L70Y	\$	Sh	481.50		
1	ABSORBER FRT RH L70Y	\$	Sh	203.50		
1	DRIVESHAFT RH	\$	7	1,355.70		
1	STABILIZER BAR FRT	\$	Sh	427.90		
1	WIPER RESERVOIR MOTOR	\$	Sh	82.60		
1	WIPER RESERVOIR	\$	Sh	179.60		
1	WIPER RESERVOIR NECK	\$	Sh	29.30		
TOTAL		\$		12,640.07		
10%		\$		1,264.01		
		\$		11,376.06		

Special Nett

1	BUMPER CLIP FRT	\$	Sh	66.00	}	X
1	BUMPER BRACKET CLIP FRT RH	\$	Sh	12.00		
1	BUMPER SUPPORT CLIP FRT RH	\$	Sh	10.50		
1	BUMPER GRILLE LOWER CLIP	\$	Sh	69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Sh	70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	Sh	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	Sh	30.00		
1	WHEELARCH CLIP FRT RH	\$	Sh	30.50		
1	FRONT RIGHT TYRE	\$	Sh	300.00		
1	FRONT RIGHT TYRE RIM	\$	Sh	380.00		
1	FRONT RIGHT TYRE RIM COVER	\$	Sh	50.00		
1SET	Front licence plate with holder	\$	Sh	80.00		
1SET	RADIATOR GRILLE SCREW	\$	Sh	16.00		
1SET	RADIATOR GRILLE FRAME CLIP	\$	Sh	52.00		
6	BONNET INSULATOR CLIP L70Y	\$	Sh	7.30		
2	BONNET CABLE COVER SCREW L70Y	\$	Sh	10.85		

Trans-cab Auto Services Pte Ltd**AAD1911-113**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 287Z

2	BONNET CABLE CLIP L70Y	\$	<i>nn</i> 6.31 <i>X</i>
---	------------------------	----	-------------------------

TOTAL	\$	1,210.47
--------------	-----------	-----------------

TOTAL PARTS	\$	12,586.53
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	<i>4401</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>101</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	<i>2001</i>
To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 287Z**AAD1911-113**

To remove and refit interior fittings, trimmings,
garnish, fittings and other, to enable repair.

\$

un 380.00 X

Labour charge to mount and dismount vehicle
on jig bench, to facilitate repair.

\$

un 380.00 X**TOTAL \$ 14,380.00****Over All Total \$ 26,966.53****LUMP SUM (REPAIR DAY)**~~20~~ DAYS*1 1/2 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 287Z**AAD1911-113**

Not Notarized
11 Sep 2016

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 287Z

VF1ABL15AUC282201

RENAULT

LATITUDE

9.11.19

FCIL

4/3/2016

	PART		LIST	
1	BUMPER COVER FRT	\$	<i>mb cm</i> 747.20	✓
1	BUMPER SPOILER FRT	\$	<i>sn</i> 344.70	X
1	BUMPER ABSORBER FRT	\$	<i>sn</i> 394.68	X
1	BUMPER RETAINER FRT RH	\$	<i>dis</i> 101.40	✓
1	BUMPER SUPPORT FRT	\$	<i>sn</i> 10.70	}
1	BUMPER UNDERTRAY FRT	\$	<i>sn</i> 292.50	
1	BUMPER GRILLE LOWER FRT	\$	<i>sn</i> 147.00	
1	BUMPER FOG LAMP GRILLE RH	\$	<i>sn</i> 207.21	
1	BUMPER BEAM FRT	\$	<i>R</i> 663.70	
1	HEADLAMP RH	\$	<i>sn</i> 743.60	
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 128.30	
1	FENDER PANEL FRT RH	\$	<i>R</i> 437.10	
1	WHEELARCH FRT RH	\$	<i>sn</i> 191.40	
1	FENDER BRACKET LOWER RH	\$	<i>sn</i> 11.80	
1	FENDER BRACKET FRT RH	\$	<i>sn</i> 106.40	
1	FENDER INSULATOR RH	\$	<i>sn</i> 66.30	
1	TOW COVER FRT	\$	<i>sn</i> 60.90	
1	FRONT BRACE PANEL	\$	<i>R</i> 177.22	
1	RADIATOR GRILLE	\$	<i>sn</i> 969.90	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>sn</i> 225.36	}
1	RADIATOR GRILLE FRAME	\$	<i>sn</i> 686.00	
1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 592.70	
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 41.60	
1	BONNET	\$	<i>R</i> 1,312.70	
1	BONNET INSULATOR	\$	<i>sn</i> 294.30	}
1	BONNET STRUT RH	\$	<i>sn</i> 53.30	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 287Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	MTG CRACKED	747.20	747.20
1	BUMPER SPOILER FRT	SERVICEABLE	344.70	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT RH	DISTORTED	101.40	101.40
1	BUMPER SUPPORT FRT	SERVICEABLE	10.70	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	292.50	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	147.00	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	663.70	-
1	HEADLAMP RH	SERVICEABLE	743.60	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	128.30	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	437.10	-
1	WHEELARCH FRT RH	SERVICEABLE	191.40	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	11.80	-
1	FENDER BRACKET FRT RH	SERVICEABLE	106.40	-
1	FENDER INSULATOR RH	SERVICEABLE	66.30	-
1	TOW COVER FRT	SERVICEABLE	60.90	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	RADIATOR GRILLE	SERVICEABLE	969.90	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	686.00	-
1	FRAME FULL SUPPORT PANEL	TO REPAIR SEE LABOUR	592.70	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	41.60	-
1	BONNET	TO REPAIR SEE LABOUR	1,312.70	-
1	BONNET INSULATOR	SERVICEABLE	294.30	-
1	BONNET STRUT RH	SERVICEABLE	53.30	-

Report Ref No. CS/FCI19020314/Kyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	237.40	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	152.80	-
1	BONNET CABLE	SERVICEABLE	55.20	-
1	BONNET CABLE COVER	SERVICEABLE	80.60	-
1	BONNET SEAL OUTER	SERVICEABLE	83.20	-
1	BONNET SEAL INNER	SERVICEABLE	70.10	-
1	LOWER ARM RH L70Y	SERVICEABLE	192.70	-
1	KNUCKLE ARM RH L70Y	SERVICEABLE	481.50	-
1	ABSORBER FRT RH L70Y	SERVICEABLE	203.50	-
1	DRIVESHAFT RH	TO REPAIR SEE LABOUR	1,355.70	-
1	STABILIZER BAR FRT	SERVICEABLE	427.90	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	82.60	-
1	WIPER RESERVOIR	SERVICEABLE	179.60	-
1	WIPER RESERVOIR NECK	SERVICEABLE	29.30	-
	LESS 10% DISCOUNT		-1,264.01	-84.86
			11,376.06	763.74
SPECIAL NETT ITEMS				
1	BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
1	FRONT RIGHT TYRE (SN)	SERVICEABLE	300.00	-
1	FRONT RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	FRONT RIGHT TYRE RIM COVER (SN)	SERVICEABLE	50.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	SET RADIATOR GRILLE SCREW (SN)	SERVICEABLE	16.00	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-

Report Ref No. CS/FCI19020314/Kyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET CABLE COVER SCREW L70Y (SN)	NOT NECESSARY	10.85	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
			1,210.46	66.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,HEADLAMP PANEL FRT RH,FENDER PANEL FRT RH,FRONT BRACE PANEL,FRAME FULL SUPPORT PANEL,FRAME FULL SUPPORT BRACKET,BONNET,BONNET HINGE RH,BONNET LOCK AND DRIVESHAFT RH.		6,000.00	200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			14,380.00	650.00
	GRAND TOTAL		26,966.52	1,479.74

Report Ref No. CS/FCI19020314/Kyd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00
---	--	--	----------

Report Ref No. CS/FC19020314/Kyd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.