

REF: CS/INC/19020359/ETd3n2

ASS. REC. BY:


Star

ASSIGNMENT

From _____ Date _____
 Estimated Cost _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No. _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Vol: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMD 1010P Yr Regn: 29/4/19
 Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Volvo XC40 TS R-Design C.C. 1969
 Colour: White A/C: Insured / Std / NI / NA
 Sp Reading: 12489 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: YV 1X 216 ACK 2125-742
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/50R19
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Pirelli
 Front: R/Bal. 6 mm L/Bal. 6 mm D.O.I. 25/10/19
 Rear: R/Bal. 6 mm L/Bal. 6 mm D.O.I. 18/11/19
 Survey held at Wearnes 2.13pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
27/11/19	Finalize Confil \$4396.23, 3 days (Richmond) (Red: \$6763.17, 60%)
RECEIVED 27 NOV 2019	
	Re-open indicate *Note: File pass to Huey Yon 27/11/2019
	condition. put not advised, parts number plate. 17/1/2020

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report
Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Wheel and (\$)

Survey Fee:

Transportation:

S + RS \$

Piston

Valve

250

Rep. Form:

Lump Sum: TP 4396.23

Also reopen ref only, 1st close date 28/11/19

SERVICE TAX INVOICE

0 - N00001	SL: NTUC INCOME INSURANCE CO-OPERATIVE	GST Reg.No:M28920628X
NTUC INCOME INSURANCE CO-OPERATIVE		Inv.No. . : B&P 7017238 Page 1
73 Bras Basah		Inv.date. : 28/11/2019
#05-01		WIP No. . : 44450
NTUC Trade Union House		Veh.In/Out: 18/11/2019 22/11/2019
Singapore 189556		*Tel.No. . :

Closed by : Derek Oh Siong Wee
 Svc Consultant : ACC
 Remarks : Mr Lim Chin Siang, K

Reg.No. . : SMD1010P
 Reg.date .. : 29/04/2019
 Mileage ... : 12,489
 Chassis No: YV1XZ16ACK2125742


Parts/Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER,REAR	0		1200.00	0		1,200.00	S
	BRACKET,REAR LOWER SPOILER,							
	REAR SKID PLATE,REAR SENSOR,ETC							
800	TO PUTTY SPRAY PAINT ON REAR	0		700.00	0		700.00	S
	BUMPER,ETC							
280	TO CHECK WIRING INCLUDE	0		480.00	0		480.00	S
	RESETTING OF ALL ELECTRICAL							
	MODULES							
031663160	BUMPER COVER REAR AL	1.0	EA	1169.90	10		1,052.91	S
039848189	BUMPER PAD REAR LH A	1.0	EA	497.80	10		448.02	S
031407965	PROTECTING PLATE REA	1.0	EA	443.55	10		399.20	S
030640541	BUMPER CLIP GREEN S6	10.0	EA	4.80	10		43.20	S
000986116	SIX PT SOCKET SCREW	10.0	EA	2.70	10		24.30	S
000987282	EXPANDING NUT XC40 1	10.0	EA	5.40	10		48.60	S

Gross Total. 4,396.23

Labour Total 2,380.00
 Parts Total 2,016.23
 Package Total 0.00

Net..... 4,396.23
 GST @ 7.0% 307.74
 Total..... 4,703.97
 Paid..... 0.00
 Please Pay.. 4,703.97

GST: S=StdRated; O=OutOfScope; Z=ZeroRated
 Enquiries must be lodged within 14 days from the invoice date
 This is a computer generated invoice. No signature is required.





Sample

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 2743Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	CCTV SOLUTION (KOW 3008HD)	DAMAGED	680.00	680.00
1	DOOR ACCESS ACCESSORIES SET INCLUDED	NOT ADVISED	100.00	-
			780.00	680.00
GRAND TOTAL			780.00	680.00
RECOMMENDED COST OF REPLACE				680.00

Report Ref No. CS/FC14018890/Kgbu2-1

*NOTE: THE ABOVE ITEM SUBMITTED BY THE CLAIMANT, SURVEYOR CONFIRMED DAMAGES CONSISTENT WITH THE SAME ACCIDENT. PRICE IN ORDER (SEE INVOICE ENCLOSED)

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020359/Etd3n2

73 BRAS BASAH ROAD

Date: 20-01-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: HELENA TAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDL 7722T	Veh. Inspected	SMD 1010P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1068626-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	18/11/2019

2. Vehicle Particulars & Condition

Make & Model	VOLVO XC40 T5 R-DESIGN	c.c	1969
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	YV1XZ16ACK2125742	Colour	WHITE
Odometer	12489 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R19	PIRELLI	6 mm
L/H Front Tyre	235/50 R19	PIRELLI	6 mm
R/H Rear Tyre	235/50 R19	PIRELLI	6 mm
L/H Rear Tyre	235/50 R19	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/10/2019	Inspect Date / Time	18/11/2019 (02:13 PM)
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 1010P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR AL (SN)	CUT	1,169.90	1,052.91
1	BUMPER PAD REAR LH A (SN)	BROKEN	497.80	448.02
1	BUMPER PAD REAR RH A (SN)	NOT NECESSARY	497.80	-
1	BUMPER BRACKET REAR (SN)	NOT NECESSARY	40.90	-
1	BUMPER BRACKET REAR (SN)	NOT NECESSARY	40.90	-
10	SCREW (SN)	NOT NECESSARY	27.00	-
1	TOW COVER REAR XC40 (SN)	NOT NECESSARY	73.90	-
1	PROTECTING PLATE REA (SN)	CUT	443.55	399.20
10	BUMPER CLIP GREEN S6 (SN)	NECESSARY	48.00	43.20
10	SPRING NUT ST4 8*1 X (SN)	NOT NECESSARY	26.00	-
10	SIX PT SOCKET SCREW (SN)	NECESSARY	27.00	24.30
10	SIX POINT SOCKET SCR (SN)	NOT NECESSARY	26.00	-
10	EXPANDING NUT XC40 1 (SN)	NECESSARY	54.00	48.60
1	BUMPER REFLECTOR RH (SN)	NOT NECESSARY	79.30	-
1	BUMPER REFLECTOR LH (SN)	NOT NECESSARY	79.30	-
1	BUMPER RAIL (BEAM) R (SN)	NOT NECESSARY	1,022.30	-
1	CROSS MEMBER REAR XC (SN)	NOT NECESSARY	220.10	-
1	GUIDE MOULDING REAR (SN)	NOT NECESSARY	74.20	-
2	INNER PANEL BRACKET (SN)	NOT NECESSARY	85.20	-
1	REINFORCEMENT (SN)	NOT NECESSARY	47.70	-
1	REINFORCEMENT (SN)	NOT NECESSARY	47.70	-
1	REAR SECTION (SN)	TO REPAIR SEE LABOUR	723.40	-
1	PROTECTING PLATE REA (SN)	REPEATED	443.55	-
1	END PIPE LH R-D XC40 (SN)	NOT NECESSARY	369.75	-
1	END PIPE RH R-D XC40 (SN)	NOT NECESSARY	369.75	-
1	EXTERIOR ADHESIVE GL (SN)	NOT NECESSARY	284.40	-
1	REAR NUMBER PLATE (SN)	NOT ADVISED	60.00	-
			6,879.40	2,016.23



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REPLACE REAR BUMPER,REAR BRACKET,REAR LOWER SPOILER,REAR SKID PLATE,REAR SENSOR,ETC.INCLUSIVE OF THE REPAIR OF REAR SECTION. TO PUTTY SPRAY PAINT ON REAR BUMPER,ETC. TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		2,400.00 1,400.00 480.00 4,280.00	1,200.00 700.00 480.00 2,380.00
	GRAND TOTAL		11,159.40	4,396.23
RECOMMENDED COST OF REPAIRS (CONFIRMED)				4,396.23

Report Ref No. CS/INC19020359/Etd3n2

***NOTE: THE ABOVE ITEM SUBMITTED BY THE CLAIMANT, SURVEYOR CONFIRMED DAMAGES CONSISTENT WITH THE SAME ACCIDENT. PRICE IN ORDER (SEE INVOICE ENCLOSED)**

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.