

ACT. REC. BY

Conveyor: Steve

REF: 03/INC/19020363/Eqd3¹²

Special Instruction:

ASSIGNMENT (Office)

From (Person): Hazalysa Bt Ibrahim

of

INC

Date/Time: 18/11/19 @ 10:02am

Estimated Cost:

Bill to:

OD/FP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 2836Y

Insured:

PCS664X

at Workshop m/s

Motorway

Tel:

0571 9642

of

1094 Lower Delta Road

Policy No:

Claim No:

MT/1070807-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/11/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:23am @ 18/11/19

Person Contacted:

Annie

Vehicle: IN/OUT

Date/Time	Action/Instruction	Initials
	GBD 2836Y - NA / INC 19019938 / 24	DA: 10/11/19
	PCS664X - NA / INC 19019938 / 24	DA: 10/11/19

ASS. REC. BY:

Steve

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G8D 2836Y Yr Regn: 26/8/14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ssangyong Actyon C.C. 1998Colour: White A/C: Insured / Std / NI / NASp. Reading: 80748 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KPA0A IET SEP 198 H2Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / Rim orTyre Size: F: 225/75R16R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Firm 29

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 10/11/19

Rear

R/Bal. 5 mmL/Bal. 5 mmD.O.I. 18/11/19 11:58amSurvey held at MotorwayDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV-67K * 22/11/19 Finalize conf. \$3350; 4 days (Annie)
	(Red to 3663.10, 52%)

RECEIVED 22 NOV 2019

Date/Time, File Pass to?

☐ : Prell. Report1) 22/11/19 turner☐ : Final Report

Date/Time, File Return to?

2) _____

Pop. Format: 7PLump Sum / UIC: 3350Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

250

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Monday, 18 November 2019 10:02 AM
To: Admin-D (LKKAuto); assignments
Cc: Susan Ting; Hazalya Binte Ibrahim
Subject: TP CASES FARMED OUT TO LKK ON 18/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1071241-002	CB7507M	CT AUTO PTE LTD	10 BUKOH STREET #01-31 WEST CONNECT BUILDING SINGAPORE 627564	Daniel Tan/Cady Lee / 9353 3333	13:00-14:30	SUJ3362P	08/11/19	owner waiting/6266-6727
2	Eng Huey Huey	MT/1071557-001	5FE222D	HIN LUNG WORKSHOP	BLK 1008 #01-20 BUKIT MERAH LANE 3 SINGAPORE 159722	Anna / 6858 3000	10:00-12:00	FV1933P	13/11/19	
3	Helena Tan	MT/1070807-002	GBD2836Y	MOTORWAY CAR CARE CENTRE PTE LTD	1094 LOWER DELTA ROAD MOTORWAY BUILDING SINGAPORE 169205	Annie Tew / 6571 9642		PC5664X	10/11/19	
4	Chryllis Quah	MT/1071066-002	GBE9864P	SIN SHENG ENGINEERING SERVICES	NO 8 TUAS AVENUE 18, #05-00 SINGAPORE 638892	Susan / 68639595		YM7508S	07/11/19	68636477
5	Azhari	MT/1069720-002	SLT5498S	WEARNES AUTOMOTIVE PTE LTD	249 ALEXANDRA ROAD SINGAPORE 159935	Derek Oh / 9818 72176	10:00-12:00	SLB290B	02/11/19	6430 4895
6	Helena Tan	MT/1068626-002	SMD1010P	WEARNES AUTOMOTIVE PTE LTD	249 ALEXANDRA ROAD SINGAPORE 159935	Derek Oh / 9818 72176	10:00-12:00	SDL7722T	25/10/19	6430 4895

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim

Admin Assistant

Motor Department

T +65 6430 7902

www.income.com.sg

income

made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

in with you

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Steve Chen (LKK Auto)

From: Tew Ai Nee <ainee@motorway.com.sg>
Sent: Friday, November 22, 2019 9:50 AM
To: Steve Chen (LKK Auto)
Subject: RE: FINALIZE GBD2836Y

Dear Steven,

Confirm the COR.

Thanks & Regards
Ainee

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Friday, 22 November, 2019 9:35 AM
To: Tew Ai Nee <ainee@motorway.com.sg>
Subject: FINALIZE GBD2836Y

Dear Ai Nee,

Kindly refer our finalize \$3350 (L/S, before GST). 4 repair days.

Kindly confirm

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants
Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tew Ai Nee [mailto:ainee@motorway.com.sg]
Sent: Friday, November 22, 2019 8:27 AM
To: Steve Chen (LKK Auto)
Subject: RE: FINALIZE GBD2836Y

Dear Steve,

We do lump-sum repairs.

Thanks & Regards
Ainee

From: Steve Chen (LKK Auto) [mailto:SteveChen@lkkauto.com]
Sent: Thursday, 21 November, 2019 6:35 PM

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	927C

Vehicle Details

Vehicle No.:	GBD2836Y
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Nov 2019
Vehicle Make:	SSANGYONG
Vehicle Model:	ACTYON SPORTS D/CAB 2.0AT 2WD D/AB ABS
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	67196022591811
Chassis No.:	KPADA1ETSEP198162
Maximum Power Output:	-
Open Market Value:	\$21,610.00
Original Registration Date:	26 Aug 2014
First Registration Date:	26 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$22,254.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	25 Aug 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$54,009.00
COE Rebate Amount:	\$25,755.00
Total Rebate Amount:	\$25,755.00

The information contained herein is correct as at 18 Nov 2019

OK



高嶺摩多貿易公司

KAOLIN MOTOR TRADING CO.

24 HOURS TOWING SERVICES

ANG MO KIO CENTRAL POST OFFICE PO BOX 676 SINGAPORE 915606

TEL : 9651 8877 / 6452 0716

Company Registration No : 21645200K

**CASH SALE
JOB ORDER**

No. 900115

Messrs Motorway car & Boat
Car centre

Date 10/11/19

Vehicle No. ABD 28364 Model S/S Pickup

Destination Gingc Ferry wh 3461

Time In 1930 Time Out 2005 Amount \$ 60

Remarks _____

- | | |
|---|--|
| ☐ Change Spare Tyre / Jumpstart | ☐ Loaded With Goods |
| ☐ Basement / Multi Carpark | ☐ Dismantle Shaft / Brake / Equipment |
| ☒ Accident | ☐ Open Door |
| ☐ Using King Dolly (Extra Trailer) | ☐ Crane up / Winch out |

Driver

Received By

bizSAFE



1094 Lower Delta Road Motorway Building Singapore 169205
Main +65.6468 2200 | Fax +65.6273 5535

NTUC INCOME
MOTOR CLAIMS DEPARTMENT
75 BRAS BASAH ROAD
NTUC INCOME CENTRE
SINGAPORE 189557
ATTN TO: MOTOR CLAIMS DEPT

ESTIMATES

VEHICLE NO. : GBD2836Y
CHASSIS NO : KPADA1ETSEP198162
MAKE / MODEL : SSANGYONG / ACTYON SPORTS D/CAB 2.0AT 2WD D/AB ABS
DATE OF ACCIDENT : 10.11.2019 @ 1700HRS

YOUR INSURED VEHICLE NUMBER : PC5664X

	<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>List Price</u>	<u>Total List Price</u>
1	FRONT BUMPER / OK	1	\$ 1,150.00	\$ 1,150.00
2	FRONT BUMPER RETAINER LH / OK	1	\$ 89.00	\$ 89.00
3	FRONT HEADLAMP LH X NN	1	\$ 1,500.00	\$ 1,500.00
4	FRONT FENDER LH / DD	1	\$ 580.00	\$ 580.00
5	FRONT FENDER UNDER-DUST COVER LH / OR	1	\$ 190.00	\$ 190.00
6	FRONT FOGLAMP LH / M13	1	\$ 250.00	\$ 250.00
Total				\$ 3,759.00
LESS 10%				\$ 375.90
Total Spart Part				\$ 3,383.10

2259
-1073
2033-10

SPECIAL NETT ITEMS

1	FRONT BUMPER CLIPS / MC	1	40	\$ 30	40.00
2	FRONT FENDER UNDER-DUST COVER CLIPS / MC	1	40	\$ 20	40.00
3	TOWING / MC	1	60	\$	60.00
TOTAL				\$	140.00 110

LABOUR CHARGES

1	TO DISMANTLE FRONT DAMAGE PARTS, CUT AND WELD FRONT SUPPORT PANEL, KNOCK, STRAIGHTEN AND RESHAPE O/S FRONT CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.	\$	1,200.00	800
2	TO PUTTY & SPRAY PAINTING ON FRONT AFFECTED AREAS	\$	1,350.00	900
3	TO REMOVE, REARRANGE ELECTRICAL WIRING, CHECK LIGHTING & RESET HEADLAMP FOCUSING	\$	180.00	100
4	TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT TO REPLACED PARTS.	\$	180.00	30
5	TO CARRY OUT DIAGNOSTIC TEST	\$	400.00	200

2030

6 COMPUTERIZED ALIGNMENT

LABOUR PER DAY - \$400

SPRAY PAINT PER PORTION - \$450

	\$	180.00 X
TOTAL LABOUR	\$	3,490.00
TOTAL	\$	7,013.10
7% GST	\$	490.92
GRAND TOTAL	\$	7,504.02

Prepared By : -

ANNIE TEW

Motor Claims

TEL: 6571 9642 FAX : 6278 5535

EMAIL: ainee@motorway.com.sg

[Signature]
19/11/19

Steve (LKK) with Mr L 18/11/19, 11.45 am
8322 8813 4 days

P/P
By Refe spy

- Let the Consultants hence notify
the Rep of the following:
- Resurvey before/after spray painting
 - Identify damaged part(s) during resurvey
 - All prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2033-10
N- 110
L - 2030
4173-10
L/S - 3338.48
= 3350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT				
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS/INC19020363/Eqd3n2		
73 BRAS BASAH ROAD		Date: 26-11-2019		
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
ATTN: HELENA TAN		Code: INC		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 5664X	Veh. Inspected	GBD 2836Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1070807-002	Excess (\$)	0.00	
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	18/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	SSANGYONG ACTYON	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KPADA1ETSEP198162	Colour	WHITE	
Odometer	80748 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/75 R16C	FIRENZA	5 mm	
L/H Front Tyre	225/75 R16C	FIRENZA	5 mm	
R/H Rear Tyre	225/75 R16C	FIRENZA	5 mm	
L/H Rear Tyre	225/75 R16C	FIRENZA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/11/2019	Inspect Date / Time	18/11/2019 (11:38 AM)	
Survey held at	MOTORWAY CAR CARE CENTRE PTE LTD 1094 LOWER DELTA ROAD MOTORWAY BUILDING . SINGAPORE 169205			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 2836Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BROKEN	1,150.00	1,150.00
1	FRONT BUMPER RETAINER LH	BROKEN	89.00	89.00
1	FRONT HEADLAMP LH	NOT NECESSARY	1,500.00	-
1	FRONT FENDER LH	DENTED	580.00	580.00
1	FRONT FENDER UNDER-DUST COVER LH	BROKEN	190.00	190.00
1	FRONT FOGLAMP LH	MISSING	250.00	250.00
	LESS 10% DISCOUNT		-375.90	-225.90
			3,383.10	2,033.10
SPECIAL NETT ITEMS				
1	FRONT BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
1	FRONT FENDER UNDER-DUST COVER CLIPS (SN)	NECESSARY	40.00	20.00
			80.00	50.00
LABOUR				
	TOWING.		60.00	60.00
	TO DISMANTLE FRONT DAMAGE PARTS,CUT AND WELD FRONT SUPPORT PANEL,KNOCK,STRAIGHTEN AND RESHAPE O/S FRONT CHASSIS FRAME AND REPLACE RECOMMENDED PARTS.		1,200.00	800.00
	TO PUTTY & SPRAY PAINTING ON FRONT AFFECTED AREAS.		1,350.00	900.00
	TO REMOVE,REARRANGE ELECTRICAL WIRING,CHECK LIGHTING & RESET HEADLAMP FOCUSING.		180.00	100.00
	TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS.		180.00	30.00
	TO CARRY OUT DIAGNOSTIC TEST.		400.00	200.00
	COMPUTEZED ALIGNMENT.	NOT NECESSARY	180.00	-
			3,550.00	2,090.00
GRAND TOTAL			7,013.10	4,173.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,350.00



Report Ref No. CS/INC19020363/Eqd3n2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.