

ASS. REC. BY:

REF: CS/FCI 19020366/Kt f3

Special Instruction:

Surveyor Kenneth

ASSIGNMENT (Office)

From (Person): Merinda Chia San Son of FCI

Date/Time: 18.11.19 D.M.P.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKX 30614

Insured: SHC 00192

at Workshop m/s Chung Hae

Tel: 67556142

of B1C 1019 Yishun Ind Rte A # 01-572

Policy No:

Claim No: D19 W1253 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 15.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 18.11.19 1.02p.m

Person Contacted:

June

H.O.D. Endorsement:

Vehicle: IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>SKX 30614 - X</u>
	<u>SHC 00192 - X</u>
<u>19/11 @ 1:58pm</u>	<u>informed pending estimate via email.</u>
<u>4/12</u>	<u>Part by Part \$5740.52 Cred: 1616.33; 210%</u>

ASS. REC. BY:

REF:

176/1
F62

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

Q55K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKX 3061Y Yr Regn: 12, 15

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz c.c. 1498

Colour:

M. Black A/C: Insured / Std / Nil / NA

Sp. Reading

97589 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

JHMGK 58506 X 201077

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: F:

185/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

S mm

L/Bal.

S mm

D.O.A.

13/11/19

Rear

R/Bal.

6 mm

L/Bal.

6 mm

D.O.L.

18/11/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to
Est not ready

RECEIVED 04 DEC 2019

Date/Time, File Pass to?

11 4/12 TUPST

Date/Time, File Return to?

2



: Prell. Report



: Final Report

Days Of Repair: 11

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Furnish

Others

TOTAL

150

50

50 + 50

41

341

Report Format:

TP

Lump Sum / I.B. (\$

5740.52

MOTOR SURVEY ASSIGNMENT

Date	15-11-2019	Our Ref No. D19007253MFSH
Accident Date	15-11-2019	Claim Type. Third Party
Insured Vehicle	SHC0019L	Third Party Vehicle. SKX3061Y
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 19 November 2019 1:58 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR
Cc: 'Merina Chia'
Subject: RE: SURVEY ASSESSMENT - D19007253MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKX 3061Y on 18/11/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 18 November 2019 1:02 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19007253MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Monday, 18 November, 2019 12:00 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007253MFSH/1

Dear Sir/Mdm,

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	981C
Vehicle Details	
Vehicle No.:	SKX3061Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Nov 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15B31020283
Chassis No.:	JHMGK5850GX201077
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$15,479.00
Original Registration Date:	03 Dec 2015
First Registration Date:	03 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$10,479.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Dec 2025
PARF Rebate Amount:	\$7,859.00
Intended COE Rebate Details	
COE Expiry Date:	02 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$33,864.00
Total Rebate Amount:	\$41,723.00

The information contained herein is correct as at 15 Nov 2019

OK

1/11 Attn: Kenneth

Cheng Hoe Motor Pte Ltd

8B, 1019, Yindan Industrial Park A #01-374/382, Singapore 368761
TEL: 67356142 (YIS) FAX: 67357719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO: 201001158E

SKX3061Y
TP/EC

M/S: MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES1992263/WS

Date: 18 Nov 2019

Policy No: D18MTPV01019405

Veh Reg No: SKX3061Y

Make/Model: HONDA HONDA JAZZ

1.5 VTIR CVT ABS

D/AIRBAG 2WD

Chassis No: JHMGK5850GX201077

Engine No: L15B31020283

Reg. Date: 03/12/2015

WS Ref: TP/EC

Claim Type: Third Party

Accident Date: 15/11/2019

TP Veh Reg No: SHC19L

Not Notified

1.131, 4.131, 8.7

11 days

85740.52

Estimate Repair Cost to Vehicle No: SKX3061Y

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 REAR BUMPER	492.50	1 PC	492.50	✓
2 REAR BUMPER SIDE RETAINERS	16.50	2 PCS	33.00	✓
3 REAR BUMPER LH REFLECTOR GARNISH	14.80	1 PC	14.80	7 X
4 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
5 REAR TAILGATE	814.20	1 PC	814.20	✓
6 TAILGATE INNER LOCK	131.80	1 PC	131.80	✓
7 TAILGATE INNER RUBBER	92.30	1 PC	92.30	✓
8 TAILGATE INNER BOARD	95.00	1 PC	95.00	7 X
9 TAILGATE EMBLEM (JAZZ)	35.00	1 PC	35.00	✓
10 TAILGATE CENTRE CHROME MOULDING	223.60	1 PC	223.60	7 X
11 REAR WINDSCREEN GLASS MOULDING	131.80	1 PC	131.80	✓
12 TAILLAMP	237.40	2 PCS	474.80	✓
13 REAR CENTRE PANEL	314.00	1 PC	314.00	✓
14 REAR CENTRE PANEL INNER TOP GARNISH	70.60	1 PC	70.60	✓
15 REAR SPARE TYRE COMPARTMENT	837.00	1 PC	837.00	7 X
16 REAR SPARE TYRE TOP BOARD	198.00	1 PC	198.00	✓
17 REAR EXHAUST PIPE	430.16	1 PC	430.16	✓
			4,411.96	
		Less 20%	882.39	3,529.57
Special Net				
18 REVERSE CAMERA	200.00	1 PC	200.00	7 X
19 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	40.00	✓
20 REVERSE SENSORS (4 PCS)	280.00	1 SET	280.00	200.00
			520.00	520.00

Labour

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-174/182, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chm@chenghoe.com.sg
GST: 2019011581 RCH NO: 2010011581

M/S: MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department

Estimate No: ES1992263/WS
Date: 18 Nov 2019
Policy No: D18MTPV01019405
Veh Reg No: SKX3061Y
Make/Model: HONDA HONDA JAZZ
1.5 VTIR CVT ABS
D/AIRBAG 2WD
Chassis No: JHMGK5850GX201077
Engine No: L15B31020283
Reg. Date: 03/12/2015

WS Ref: TP/FC
Claim Type: Third Party
Accident Date: 15/11/2019
IP Veh Reg No: SHC19L

Estimate Repair Cost to Vehicle No :SKX3061Y

Description	U/Price	Quantity	List Price	Amount
			SS	SS
21 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
22 REMOVE & REFIX REAR BUMPER ASSY, TAIL LAMPS, TAILGATE & ATTACHMENT, SPOILER, TO STRAIGHTEN, KNOCK & REPAIR REAR RH CHASSIS, CUT, WELD & RENEW REAR END PANEL, REAR SPARE TYRE COMPARTMENT, REPAIR REAR BOTH FENDERS & REALIGN THE SAME	1,400.00	1 LA	1,400.00	1200
23 REMOVE & REFIX REAR GARNISH, SEAT, ETC	80.00	1 LA	80.00	✓
24 REMOVE & REFIX REAR EXHAUST PIPE & REPAIR CENTRE PIPE & CHECK LEAKING	60.00	1 LA	60.00	✓
25 REMOVE & REFIX REVERSE CAMERA & CHECK SYSTEM	50.00	1 LA	50.00	✓
26 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR BOTH FENDERS, REAR RH CHASSIS, REAR PANEL, TAILGATE, REAR BUMPER	1,300.00	1 LA	1,300.00	1100
27 RUSTPROOFING	80.00	1 LA	80.00	✓
			3,090.00	3,090.00
			Total	SS 7,139.57
			Add GST @ 7%	499.77
			Total Amount Payable	SS 7,639.34

Parts \$3241.56
Add Supp \$271.60
20%
\$3513.16
202.63
\$2810.52
240 SN
2690
\$5740.52 ✓ de

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Supp 1

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES1992263/WS

Date: 29 Nov 2019

Policy No: D18MTPV01019405

Veh Reg No: SKX3061Y

Make/Model: HONDA HONDA JAZZ
1.5 VTIR CVT ABS
D/AIRBAG 2WD

Chassis No: JHMGK5850GX201077

Engine No: L15B31020283

Reg. Date: 03/12/2015

WS Ref: TP/FC

Claim Type: Third Party

Accident Date: 15/11/2019

TP Veh Reg No: SHC19L

Estimate Repair Cost to Vehicle No :SKX3061Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 REAR TOOL BOX	117.50	1 PC	CM 117.50	—
2 REAR SMART KEY SENSOR	85.60	1 PC	CM 85.60	—
3 REAR SMART KEY ANTENNA	68.50	1 PC	CM 68.50	—
			271.60	
	Less 20%		54.32	217.28
Total				S\$ 217.28
GST Amount				S\$ 15.21
Total Amount Payable				S\$ 232.49

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19020366/Ktf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-12-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 19L	Veh. Inspected	SKX 3061Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19007253MFSH	Excess (\$)	0.00
	Assign From	MERINA CHIA SAN SAN	Assign Date	18/11/2019
2. Vehicle Particulars & Condition				
	Make & Model	HONDA JAZZ (A)	c.c	1498
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JHMGK5850GX201077	Colour	METALLIC BLACK
	Odometer	97589	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/55 R16	DUNLOP	8 mm
	L/H Front Tyre	185/55 R16	DUNLOP	8 mm
	R/H Rear Tyre	185/55 R16	DUNLOP	6 mm
	L/H Rear Tyre	185/55 R16	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/11/2019	Inspection Date	18/11/2019
	Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 3061Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BENT	492.50	492.50
2	REAR BUMPER SIDE RETAINERS @\$16.50	DISTORTED	33.00	33.00
1	REAR BUMPER LH REFLECTOR GARNISH	SERVICEABLE	14.80	-
6	REAR BUMPER CLIPS @\$3.90	NECESSARY	23.40	23.40
1	REAR TAILGATE	BENT	814.20	814.20
1	TAILGATE INNER LOCK	DENTED	131.80	131.80
1	TAILGATE INNER RUBBER	DISTORTED / DENTED	92.30	92.30
1	TAILGATE INNER BOARD	SERVICEABLE	95.00	-
1	TAILGATE EMBLEM (JAZZ)	NECESSARY	35.00	35.00
1	TAILGATE CENTRE CHROME MOULDING	SERVICEABLE	223.60	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	131.80	131.80
2	TAILLAMPS @\$237.40	CUT	474.80	474.80
1	REAR CENTRE PANEL	BENT	314.00	314.00
1	REAR CENTRE PANEL INNER TOP GARNISH	MTG DISTORTED	70.60	70.60
1	REAR SPARE TYRE COMPARTMENT	TO REPAIR SEE LABOUR	837.00	-
1	REAR SPARE TYRE TOP BOARD	DENTED	198.00	198.00
1	REAR EXHAUST PIPE	BENT	430.16	430.16
1	REAR TOOL BOX (ADDITIONAL)	CRACKED	117.50	117.50
1	REAR SMART KEY SENSOR (ADDITIONAL)	CRACKED	85.60	85.60
1	REAR SMART KEY ANTENNA (ADDITIONAL)	CRACKED	68.50	68.50
	LESS 20% DISCOUNT		-936.71	-702.64
			3,746.85	2,810.52
SPECIAL NETT ITEMS				
1	REVERSE CAMERA (SN)	SERVICEABLE	200.00	-
1	ROLL REAR WINDSCREEN GLASS GUM (SN)	NECESSARY	40.00	40.00
1	SET REVERSE SENSORS (4PCS)(SN)	SHORTED	280.00	200.00
			520.00	240.00
LABOUR				
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		120.00	120.00

Report Ref No. CS/FCI19020366/Ktf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, SPOILER, TO STRAIGHTEN, KNOCK & REPAIR REAR RH CHASSIS, CUT, WELD & RENEW REAR END PANEL, REAR SPARE TYRE COMPARTMENT, REPAIR REAR BOTH FENDERS & REALIGN THE SAME.		1,400.00	1,200.00
	REMOVE & REFIX REAR GARNISH, SEAT, ETC.		80.00	80.00
	REMOVE & REFIX REAR EXHAUST PIPE & REPAIR CENTRE PIPE & CHECK LEAKING.		60.00	60.00
	REMOVE & REFIX REVERSE CAMERA & CHECK SYSTEM.		50.00	50.00
	PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR BOTH FENDERS, REAR RH CHASSIS, REAR PANEL, TAILGATE, REAR BUMPER.		1,300.00	1,100.00
	RUST[PROOFING.		80.00	80.00
			3,090.00	2,690.00
GRAND TOTAL			7,356.85	5,740.52
RECOMMENDED COST OF REPAIRS				5,740.52

Report Ref No. CS/FCI19020366/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.