

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19020375/ABA3Q2

**Date:** 30/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** GBD7619A **Insured Vehicle No :** SBC2690E

**Date of Loss:** 12/11/2019 **Nature of Claim:** TP **Claim No:** 6483577992SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD7619A	Engine No:	YD25358127A
Make & Model:	NISSAN NV350, 2.5 (A)	Chassis No:	JN1MC2E26Z0003525
Reg. Date:	14/04/2015 (Man. Year: 2014)	Odometer:	136741 km
Colour:	Grey		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,217.20	3,731.29	2,485.91	39.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	1,880.00	2,270.00	54.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,367.20</b>	<b>5,611.29</b>	<b>4,755.91</b>	<b>45.87</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,500.00</b>		
<b>Nett Amount (\$\$)</b>	<b>10,367.20</b>	<b>4,500.00</b>	<b>5,867.20</b>	<b>56.59</b>
<b>+ Loss of Use (6.0 x S\$100.00/day) (\$\$)</b>		600.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>5,107.45</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>5,100.00</b>		

### INSPECTION

Date of Assignment: 14/11/2019

Date Inspected: 14/11/2019 Inspected At:

Hua Meng Spray Painting Workshop (HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 6.0 days

---

**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,998.40 FL	*1,742.00 FL
2	2		*REAR TAILGATE HINGES	Not Necessary	119.20 FL	*- FL
3	1		*REAR TAILGATE UPPER LOCK	Damaged	356.10 FL	*356.10 FL
4	1		*REAR TAILGATE LOWER LOCK	Not Necessary	196.40 FL	*- FL
5	2		*REAR TAILGATE SHOCK ABSORBER	Not Necessary	475.00 FL	*- FL
6	2		*REAR TAILGATE SIDE LOCK	Not Necessary	121.20 FL	*- FL
7	2		*REAR TAILGATE INNER SIDE LOCK	Not Necessary	101.20 FL	*- FL
8	1		*REAR TAILGATE INNER BOARD	Not Necessary	242.00 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Cut	154.90 FL	*154.90 FL
10	1		*REAR TAILGATE CENTRE EMBLEM	Necessary	87.00 FL	*87.00 FL
11	1		*REAR TAILGATE HANDLE	Not Necessary	589.30 FL	*- FL
12	1		*REAR TAILGATE NV 350 EMBLEM	Necessary	121.00 FL	*121.00 FL
13	1		*REAR TAILGATE 70 STICKER	Necessary	26.73 FS	*10.00 FS
14	1		*REAR TAILGATE 8 PAX STICKER	Necessary	26.73 FS	*10.00 FS
15	1		*REAR END PANEL	Repair	270.80 FL	*- FL
16	1		*REAR END PANEL TOP ALUM	Not Necessary	109.00 FL	*- FL
17	1		*REAR BUMPER	Deformed	733.90 FL	*733.90 FL
18	1		*REAR STEP PANEL	Bent	178.60 FL	*178.60 FL
19	2		*REAR LAMP	Cracked	494.60 FL	*494.60 FL
20	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
21	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,852.06</b>	<b>4,118.10</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	634.86	386.81
<b>Total Parts (\$\$)</b>	<b>6,217.20</b>	<b>3,731.29</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO SUPPLY REAR END PANEL SEALANT	New	200.00	0.00
2	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	50.00
3	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	120.00
4	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	50.00
5	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	750.00
6	RESPRAY PAINTING	New	1,500.00	750.00
7	TUFF KOTE	New	150.00	80.00
8	REMOVE AND REINSTALL UPHOLSTERY	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,150.00</b>	<b>1,880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >