

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020380/ABA3Q2

Date: 27/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : GBF8481L **Insured Vehicle No :** SMH4377R

Date of Loss: 09/11/2019 Nature of Claim: TP Claim No: 9580210248SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF8481L	Engine No:	K9KC400D056310
Make & Model:	NISSAN NV200, 1.5 (A)	Chassis No:	VSKYBAM20Z0138931
Reg. Date:	29/03/2017 (Man. Year: 2016)	Odometer:	49499 km
Colour:	Silver		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14C	Rear Tyre Size:	175/70 R14C
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,780.66	3,472.97	4,307.69	55.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,360.00	1,510.00	1,850.00	55.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,140.66	4,982.97	6,157.69	55.27
+ GST 7.00/7.00% (S\$)	779.85	348.81	431.04	55.27
Nett Amount (S\$)	11,920.51	5,331.78	6,588.73	55.27
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,833.78		
Global Sum Settlement (S\$)		5,800.00		

INSPECTION

Date of Assignment: 18/11/2019

Date Inspected: 18/11/2019 Inspected At:

Comfortdelgro Engineering Pte Ltd
(HQ)
205 BRADDELL ROAD
Singapore 579701

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHR DOOR	Dented	1,983.96 F	*1,545.00 FL
2	1		*LHR DOOR HINGE LOWER	Not Necessary	147.81 F	*- FL
3	1		*LHR DOOR HINGE UPPER	Not Necessary	147.81 F	*- FL
4	1		*LHR DOOR CHECKER	Not Necessary	141.75 F	*- FL
5	1		*RHR DOOR	Dented	1,352.70 F	*1,165.00 FL
6	1		*RHR DOOR HINGE LOWER	Not Necessary	147.81 F	*- FL
7	1		*RHR DOOR HINGE UPPER	Not Necessary	147.81 F	*- FL
8	1		*RHR DOOR CHECKER	Not Necessary	141.75 F	*- FL
9	1		*REAR DOOR WEATHERSTRIP	Not Necessary	150.66 F	*- FL
10	1		*REAR DOOR LOCK LH	Not Necessary	188.73 F	*- FL
11	1		*REAR DOOR LOCK RH	Not Necessary	188.73 F	*- FL
12	1		*NUMBER PLATE LAMP GARNISH	Not Necessary	475.20 F	*- FL
13	1		*REAR BUMPER	Deformed	946.00 F	*624.80 FL
14	10		*REAR BUMPER CLIPS	Necessary	56.10 F	*56.10 FL
15	2		*REAR BUMPER SIDE BRACKET	Not Necessary	105.60 F	*- FL
16	1		*REAR END PANEL OUTER	Repair	255.75 F	*- FL
17	2		*REAR BUMPER REFLECTOR LAMP	Not Necessary	170.50 F	*- FL
18	1		*TAIL LAMP	N/S Cracked	598.84 F	*299.42 FL
19	1		*EMBLEM	Necessary	216.15 F	*55.30 FL
20	1		*NV 200 WORDING	Necessary	187.00 F	*79.90 FL
21	1		*70KM/H	Necessary	15.00 FS	*15.00 FS
22	1		*6 PAX STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,780.66	3,855.52
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	382.55
Total Parts (\$)	7,780.66	3,472.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKET & ETC	New	100.00	30.00
2	TO REMOVE & REINSTALL REAR DOOR GLASS LH &RH	New	180.00	120.00
3	TO DISMANTLE AND TRANSFER REAR BACK DOOR FITTINGS AND MECHANISM TO NEW DOOR /FACILITATE REPAIR	New	480.00	160.00
4	CUT & WELD REAR END PANEL OUTER ,KNOCK & REPAIR INNER END PANEL ,FLOOR PANEL ,BOTH SIDE PANEL AND AFFECTED AREA	New	1,400.00	600.00
5	TO SPRAY PAINT REAR BOTH DOOR ,END PANEL OUTER ,INNER END PANEL ,FLOOR PANEL ,BOTH SIDE PANEL AND AFFECTED AREA	New	1,200.00	600.00
			Gross Labour Cost (S\$)	3,360.00
				1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >