

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19020406/AKA3Q2

Date: 15/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SLQ5935M

Insured Vehicle No : SLR5533J

Date of Loss: 17/11/2019

Nature of Claim: TP

Claim No: 3814017472SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ5935M**

Make & Model: BMW 640I, 3.0 (A)

Engine No: 09328459N55B30A

Reg. Date: 19/04/2013 (Man. Year: 2013)

Chassis No: WBA6A02020DZ11571

Colour: Red

Odometer: 62660 km

Engine Capacity: 2979 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19

Rear Tyre Size:

245/40 R19

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 7,722.00 | 6,529.50 | 1,192.50 | 15.44 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,500.00 | 780.00 | 720.00 | 48.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 9,222.00 | 7,309.50 | 1,912.50 | 20.74 |
| + GST 7.00/7.00% (S\$) | 645.54 | 511.67 | 133.87 | 20.74 |
| Nett Amount (S\$) | 9,867.54 | 7,821.17 | 2,046.37 | 20.74 |
| + Loss of Use (4.0 x S\$120.00/day) (S\$) | | 480.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 8,303.17 | | |
| Global Sum Settlement (S\$) | | 8,300.00 | | |

INSPECTION

Date of Assignment: 19/11/2019

Date Inspected: 19/11/2019 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 1,928.00 FL | *1,928.00 FL |
| 2 | 1 | | *SET FRONT BUMPER CLIPS | Necessary | 50.00 FL | *50.00 FL |
| 3 | 1 | | *FRONT BUMPER SIDE HOLDER-RH | Necessary | 98.00 FL | *98.00 FL |
| 4 | 1 | | *FRONT BUMPER NOZZLE COVER | Missing | 68.00 FL | *68.00 FL |
| 5 | 1 | | *FRONT BUMPER NOZZLE PUMP | Cracked | 298.00 FL | *298.00 FL |
| 6 | 1 | | *FRONT BUMPER REINFORCEMENT | Not Necessary | 686.00 FL | *- FL |
| 7 | 1 | | *FRONT BUMPER SPONGE | Not Necessary | 225.00 FL | *- FL |
| 8 | 1 | | *FRONT BUMPER SENSOR | Damaged | 358.00 FL | *358.00 FL |
| 9 | 1 | | *FRONT BUMPER LAMP -RH | Not Necessary | 289.00 FL | *- FL |
| 10 | 1 | | *FRONT BUMPER LAMP COVER-RH | Not Necessary | 125.00 FL | *- FL |
| 11 | 1 | | *HEAD LAMP -RH | Cut | 4,366.00 FL | *4,366.00 FL |
| 12 | 1 | | *BMW LOGO | Necessary | 89.00 FL | *89.00 FL |

F=Franchise part. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 8,580.00 | 7,255.00 |
| - List Item Discount on L Items 10.00/10.00% (\$\$) | 858.00 | 725.50 |
| Total Parts (\$\$) | 7,722.00 | 6,529.50 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TO KNOCKING & PULL OUT FRONT RH PORTION & RENEW ABOVE PARTS | New | 700.00 | 400.00 |
| 2 | TO PUTTY & SPRAY UP PAINT WORKS | New | 600.00 | 250.00 |
| 3 | TO CHECK WIRING | New | 50.00 | 30.00 |
| 4 | TO PERFORM DIANOGSTIC TEST | New | 150.00 | 100.00 |
| Gross Labour Cost (\$\$) | | | 1,500.00 | 780.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >