

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020410/KKA3Q2

Date: 27/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : GBH4856E **Insured Vehicle No :** SLH2592K

Date of Loss: 06/11/2019 Nature of Claim: TP Claim No: 8682601061SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4856E	Engine No:	1KD2806094
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 4DR (A)	Chassis No:	JTFHT02P000243058
Reg. Date:	18/06/2018 (Man. Year: 2018)	Odometer:	37019 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,281.90	1,281.90	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	530.00	270.00	33.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,081.90	1,811.90	270.00	12.97
+ GST 7.00/7.00% (S\$)	145.73	126.83	18.90	12.97
Nett Amount (S\$)	2,227.63	1,938.73	288.90	12.97
+ Car Rental (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		2,186.73		

INSPECTION

Date of Assignment: 03/12/2019

Date Inspected: 03/12/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	498.10 FL	*498.10 FL
2	1		*FRONT BUMPER RH RETAINER	Distorted	149.00 FL	*149.00 FL
3	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	304.00 FL	*304.00 FL
5	1		*RH HEADLAMP	Cut	737.10 FL	*737.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,709.20	1,709.20
- List Item Discount on L Items 25.00/25.00% (\$)	427.30	427.30
Total Parts (\$)	1,281.90	1,281.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER, HEADLAMP ,FRT BUMPER REINFORCEMENT & REALIGN THE SAME	New	400.00	250.00
2	PUTTY & RESPRAY ON FRT BUMPER ,REINFORCEMENT	New	400.00	280.00
Gross Labour Cost (\$\$)			800.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >