



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909		NAME : Mr Lim Teng Shuen, Emil ADDRESS : 24 Lim Tai See Walk Singapore 267792 TEL : 91277330Mr		WIP : 55167 EXCESS : DATE : 18-Nov-19	
ATTN : MOTOR CLAIMS FAX :					
VEH NO :	SMM8278R	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BP2SAAK1100825	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA3 BP	DATE REG.:	16-Jul-19	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES	
1	FRONT BUMPER <i>de /</i>	1	✓ MBCKA-50-031EBB	\$ 867.30
2	RETAINER RHS ?	1	MBCKA-50-0T0A	\$ 20.50
3	GUIDE RHS ?	1	MBCKA-50-A20B	\$ 68.20
4	RETAINER SIDE RHS, GRILLT OP ?	1	MBDGF-50-0T6B	\$ 11.00
5	COVER RHS, FOGLAMP X	1	MBCKB-50-C11A	\$ 89.30
6	BRACKET RHS, MODULE ?	1	MBCKA-50-153C	\$ 81.20
7	MONITOR BLIND RHS ?	1	MB0J8-67-Y30B	\$ 1,800.70
8	RETAINER CENTER LHS, SENSOR X	1	MB0M5-67-UC5	\$ 4.60
9	RETAINER CENTER RHS, SENSOR X } photo 2..	1	MB0M6-67-UC5	\$ 4.60
10	BRACKET CENTER, SENSOR X	2	MB0J8-67-UC6	\$ 46.80
11	CLIP, FRONT BUMPER <i>na /</i>	10	✓ MC274-50-133	\$ 37.00
12	FASTENER, FRONT BUMPER <i>na /</i>	2	✓ MB45A-56-146A	\$ 6.00
13	RUBBER SEAL, FRONT BUMPER <i>na /</i>	2	✓ MBCKA-50-2G1A	\$ 4.80
14	RUBBER SEAL, FRONT BUMPER <i>na /</i>	2	✓ MBDWH-50-2G1	\$ 14.60
15	GROMMET, FRONT BUMPER <i>na /</i>	2	✓ MN243-50-0Z1	\$ 10.40
16	RIVET, FRONT BUMPER <i>na /</i>	6	✓ MS515-51-833	\$ 24.00
17	RIVET, FRONT BUMPER <i>na /</i>	8	✓ MBCKA-50-355A	\$ 44.00
18	RIVET, FRONT BUMPER <i>na /</i>	8	✓ MTK21-50-355	\$ 73.60
19	RUBBER SEAL, FRONT BUMPER <i>na /</i>	2	✓ MBDGF-50-2G2	\$ 5.60
20	FASTENER, FRONT BUMPER <i>na /</i>	2	✓ MGD7A-50-EA1	\$ 6.40
21	GROMMET, FRONT BUMPER <i>na /</i>	1	✓ MBCKA-50-0U5	\$ 2.50
22	GROMMET, FRONT BUMPER <i>na /</i>	1	✓ MBCKA-50-0T5	\$ 2.50
23	TAPE PROTECTOR, SENSOR <i>na /</i>	3	✓ MBCKA-50-EM1	\$ 14.10
24	CHROME RHS <i>na /</i>	1	✓ MBCKA-50-7J0C	\$ 298.00
25	FRONT GRILLE X	1	MBCKB-50-711	\$ 527.40
26	CLIP, FRONT GRILLE <i>na /</i>	2	✓ MG46L-50-EB1	\$ 9.40
27	CLIP, FRONT GRILLE <i>na /</i>	1	✓ MGSH7-50-EB1	\$ 9.10
28	GROMMET, FRONT GRILLE <i>na /</i>	4	✓ MBCKA-50-ES1B	\$ 14.80
29	GRILLE TOP <i>na /</i>	1	✓ MBCKB-50-7E0D2M	\$ 690.80
30	FASTENER, GRILLE TOP <i>na /</i>	3	✓ MGD7A-50-EA1	\$ 9.60
31	RIVET, GRILLE TOP <i>na /</i>	4	✓ MBCKA-50-355A	\$ 22.00

32	RIVET, GRILLE TOP	ne /	10	MTK21-50-355		\$ 92.00
33	RIVET, GRILLE TOP	ne /	16	MSS15-51-833		\$ 64.00
34	CLIP, GRILLE TOP	ne /	2	MBCKA-56-145A		\$ 12.80
35	FRONT FENDER RHS	st /	1	MBCJH-52-110		\$ 415.90
36	STAY RHS, FENDER	ne /	1	MBCJH-52-140		\$ 39.90
37	MUDGUARD RR RHS	de / ?	1	MBCJH-56-130D		\$ 185.90
38	MUDGUARD FRT RHS	de /	1	MBCJH-56-13Y		\$ 201.10
39	FASTENER, MUDGUARD	ne /	15	MB45A-56-146A		\$ 45.00
40	WEATHERSTRIP, BONNET	X	1	MBCJH-56-770		\$ 55.90
41	HEADLAMP RHS	sea /	1	MBCLH-51-030B		\$ 3,655.10
42	BRACKET RHS, HEADLAMP	?	1	MBCKA-50-150A		\$ 56.20
43	CLIP, HEADLAMP	X	5	MBCKA-56-145A		\$ 32.00
44	WASHER TANK	?	1	MBCKA-67-481		\$ 51.50
45	FUNNEL, WASHER TANK	X	1	MBCKA-67-484		\$ 30.60
46	GROMME, WASHER TANK	X	1	MBCKB-67-491		\$ 4.70
47	TANK, SUB-RADIATOR	X	1	MPAF1-15-351		\$ 55.40
48	PIPE, WASHER TANK	X	1	MBCKA-67-501		TBA
49	RADIATOR COOLANT	X	5			\$ 72.00
TOTAL PARTS						\$ 9,890.80
TOTAL PARTS COST						\$ 9,890.80

Labour Description

1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER RH. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1320	\$ 1,320.00
2		TO RESPRAY FRONT BUMPER, BONNET, FRONT FENDER RH, FRONT DOOR RH AND REAR DOOR RH.	1890	\$ 3,180.00
3	MZ-BR-WHEEL	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT X	\$ 560.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	100	\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7		TO SUPPLY BRILA PREMIUM COATING.	NETT 300	\$ 500.00
8	MZ-BR-SUNDRI	SUNDRIES.	NETT 20	\$ 100.00
TOTAL LABOUR			\$ -	\$ 6,480.00
TOTAL PARTS			\$ -	\$ 9,890.80
TOTAL			\$ -	\$ 16,370.80
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ -	
GST 7%			\$ -	\$ -

GRAND TOTAL

\$

-

\$

-

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

Pasul

Hp 90010068

5 days

19/11/19 @ 1140

EXCESS: TBA

REVERT

Recovery before print

**TRANS EUROKARS PTE LTD****SUPPLEMENTARY ESTIMATE COST OF REPAIRS (2)**

CHINA TAIPING INSURANCE P/L		NAME :	Mr Lim Teng Shuen, Emil	WIP :	56167
3 ANSON ROAD		ADDRESS :	24 Lim Tai See Walk	EXCESS :	
#16-00 SPRINGLEAF TOWER			Singapore 267792	DATE:	18-Nov-19
SINGAPORE 079909					
ATTN. :	MOTOR CLAIMS	TEL :	91277330Mr		
FAX :					
VEH NO :	SMM8278R	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BP2SAAK1100825	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA3 BP	DATE REG.:	16-Jul-19	POLICY NO. :	

NATURE OF WORKS**Parts Description**

NO	QTY	REVISED	PRICES
1	LABEL CAUTION <i>per</i> 1	MPE01-15-031	\$ 3.50
2	LABEL CAUTION <i>per</i> 1	MKF49-61-439	\$ 3.50
TOTAL PARTS			\$ 7.00
TOTAL PARTS COST			\$ 7.00

Labour Description

1			
TOTAL LABOUR		\$ -	\$ -
TOTAL PARTS		\$ -	\$ 7.00
TOTAL		\$ -	\$ 7.00
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ -	
GST 7%		\$ -	\$ -
GRAND TOTAL		\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD_____
Authorised Signature



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Lim Teng Shuen, Emil ADDRESS : 24 Lim Tai See Walk Singapore 267792 TEL : 91277330Mr		WIP : 56167 EXCESS : \$ 500.00 DATE: 18-Nov-19	
VEH NO :	SMM8278R	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6BP2SAAK1100825	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA3 BP	DATE REG.:	16-Jul-19	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	FRONT BUMPER MBCKA-50-031EBB	\$ 867.30	\$ 867.30
2	1	RETAINER RHS MBCKA-50-0T0A		\$ 20.50
3	1	GUIDE RHS MBCKA-50-A20B	\$ 68.20	\$ 68.20
4	1	RETAINER SIDE RHS, GRILLT OP MBDGF-50-0T6B	\$ 11.00	\$ 11.00
5	1	COVER RHS, FOGLAMP MBCKB-50-C11A		\$ 89.30
6	1	BRACKET RHS, MODULE MBCKA-50-153C		\$ 81.20
7	1	MONITOR BLIND RHS MB0J8-67-Y30B		\$ 1,800.70
8	1	RETAINER CENTER LHS, SENSOR MB0M5-67-UC5	\$ 4.60	\$ 4.60
9	1	RETAINER CENTER RHS, SENSOR MB0M6-67-UC5	\$ 4.60	\$ 4.60
10	2	BRACKET CENTER, SENSOR MB0J8-67-UC6	\$ 46.80	\$ 46.80
11	10	CLIP, FRONT BUMPER MC274-50-133	\$ 37.00	\$ 37.00
12	2	FASTENER, FRONT BUMPER MB45A-56-146A	\$ 6.00	\$ 6.00
13	2	RUBBER SEAL, FRONT BUMPER MBCKA-50-2G1A	\$ 4.80	\$ 4.80
14	2	RUBBER SEAL, FRONT BUMPER MBDWH-50-2G1	\$ 14.60	\$ 14.60
15	2	GROMMET, FRONT BUMPER MN243-50-0Z1	\$ 10.40	\$ 10.40
16	6	RIVET, FRONT BUMPER MS51S-51-833	\$ 24.00	\$ 24.00
17	8	RIVET, FRONT BUMPER MBCKA-50-355A	\$ 44.00	\$ 44.00
18	8	RIVET, FRONT BUMPER MTK21-50-355	\$ 73.60	\$ 73.60
19	2	RUBBER SEAL, FRONT BUMPER MBDGF-50-2G2	\$ 5.60	\$ 5.60
20	2	FASTENER, FRONT BUMPER MGD7A-50-EA1	\$ 6.40	\$ 6.40
21	1	GROMMET, FRONT BUMPER MBCKA-50-0U5	\$ 2.50	\$ 2.50
22	1	GROMMET, FRONT BUMPER MBCKA-50-0T5	\$ 2.50	\$ 2.50
23	3	TAPE PROTECTOR, SENSOR MBCKA-50-EM1	\$ 14.10	\$ 14.10
24	1	CHROME RHS MBCKA-50-7J0C	\$ 298.00	\$ 298.00
25	1	FRONT GRILLE MBCKB-50-711		\$ 527.40
26	2	CLIP, FRONT GRILLE MG46L-50-EB1	\$ 9.40	\$ 9.40
27	1	CLIP, FRONT GRILLE MGSH7-50-EB1	\$ 9.10	\$ 9.10
28	4	GROMMET, FRONT GRILLE MBCKA-50-ES1B	\$ 14.80	\$ 14.80
29	1	GRILLE TOP MBCKB-50-7E0D2M	\$ 690.80	\$ 690.80
30	3	FASTENER, GRILLE TOP MGD7A-50-EA1	\$ 9.60	\$ 9.60
31	4	RIVET, GRILLE TOP MBCKA-50-355A	\$ 22.00	\$ 22.00

32	RIVET, GRILLE TOP	10	MTK21-50-355	\$ 92.00	\$ 92.00
33	RIVET, GRILLE TOP	16	MS51S-51-833	\$ 64.00	\$ 64.00
34	CLIP, GRILLE TOP	2	MBCKA-56-145A	\$ 12.80	\$ 12.80
35	FRONT FENDER RHS	1	MBCJH-52-110	\$ 415.90	\$ 415.90
36	STAY RHS, FENDER	1	MBCJH-52-140	\$ 39.90	\$ 39.90
37	MUDGUARD RR RHS	1	MBCJH-56-130D	\$ 185.90	\$ 185.90
38	MUDGUARD FRT RHS	1	MBCJH-56-13Y	\$ 201.10	\$ 201.10
39	FASTENER, MUDGUARD	15	MB45A-56-146A	\$ 45.00	\$ 45.00
40	WEATHERSTRIP, BONNET	1	MBCJH-56-770		\$ 55.90
41	HEADLAMP RHS	1	MBCLH-51-030B	\$ 3,655.10	\$ 3,655.10
42	BRACKET RHS, HEADLAMP	1	MBCKA-50-150A	\$ 56.20	\$ 56.20
43	CLIP, HEADLAMP	5	MBCKA-56-145A		\$ 32.00
44	WASHER TANK	1	MBCKA-67-481	\$ 51.50	\$ 51.50
45	FUNNEL, WASHER TANK	1	MBCKA-67-484		\$ 30.60
46	GROMME, WASHER TANK	1	MBCKB-67-491		\$ 4.70
47	TANK, SUB-RADIATOR	1	MPAF1-15-351	\$ 55.40	\$ 55.40
48	PIPE, WASHER TANK	1	MBCKA-67-501		TBA
49	RADIATOR COOLANT	5			\$ 72.00
SUPPLEMENTARY ITEMS					
1	LABEL, CAUTION	1	MPE01-15-031	\$ 3.50	\$ 3.50
2	LABEL, CAUTION	1	MKF49-61-439	\$ 3.50	\$ 3.50
TOTAL PARTS COST				\$ 7,183.50	\$ 9,890.80

Labour Description

Labour Description				
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER RH. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,320.00	\$ 1,320.00
2		TO RESPRAY FRONT BUMPER, BONNET AND FRONT FENDER RH.	\$ 1,890.00	\$ 3,150.00
3	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		\$ 560.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 100.00	\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
7		TO SUPPLY BRILA PREMIUM COATING.	\$ 300.00	\$ 500.00
8	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
			TOTAL LABOUR	\$ 3,960.00 \$ 6,480.00
			TOTAL PARTS	\$ 7,183.50 \$ 9,890.80
			TOTAL	\$ 11,143.50 \$ 16,370.80
			LESS EXCESS	\$ 500.00 \$ -
			TOTAL AFTER EXCESS	\$ 10,643.50
			GST 7%	\$ 745.05 \$ -
			GRAND TOTAL	\$ 11,388.55 \$ -
REMARKS:				

REMARKS:

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 13 December 2019 10:09 AM
To: catherinechua@eurokars.com.sg; Rasul (LKKAuto); SUR
Cc: jess.francis@eurokars.com.sg; CS A Team; Admin A
Subject: RE: SMM8278R - FINALIZATION OF COR

Dear Catherine,

Confirmed COR: \$11,143.50 before excess of \$500.00 and GST @ 5 repair days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg <catherinechua@eurokars.com.sg>
Sent: Friday, 13 December 2019 9:30 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: jess.francis@eurokars.com.sg; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: SMM8278R - FINALIZATION OF COR

Dear Rasul

Our COR computation with before-paint photos is attached for your agreement.

COR: \$11143.50 before excess of \$500.00 and before GST

5 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards



Driving luxury experiences since 1985

Catherine Chua

Insurance Claims Executive

23 Leng Kee Road Singapore 159095

T: (65) 6603 6128 **D:** (65) 6603 6121 **F:** (65) 6476 7417

E: catherinechua@mazda.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <mazdacanon@mazda.com.sg>
Sent: 13 December 2019 8:50 AM

To: Catherine Chua <catherinechua@eurokars.com.sg>

Subject: Attached Image

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Nov 2019		19 Nov 2019 15:54 Edit Adj Rpt	S\$11,143.50 Edit Estimates	S\$11,143.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: LIM TENG SHUEN EMIL , ID: S9513365G			[Created by insurer]						
Vehicle Reg. No.: SMM8278R		Date of Loss: 14/11/2019 21:00 - :59	[3 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type: OD / SNM19D205447C01/BT		Policy/Cover Note No.: DMCPN3054201900 (Comprehensive)							
		Excess: S\$500.00							
Repairer: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru, 609042 West Coast - Tel: 6331 0680									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 28/11/2019]									
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
• CHINA_TAIPIING (20/11/2019): Alert - Adj Mandate Approved (S\$12927.50) - SMM8278R - Claim Handler: Ben Tang									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

***SMM8278R (SNM19D205447C01/BT)
OD**

[LIM TENG SHUEN EMIL]

Trans Eurokars Pte Ltd - Tanjong Penjuru

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser					
Photos/Images								3 per page						
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print				
1	13/12/19 10:05	General View							Load PDF					
2	13/12/19 10:05	Reinspection Photo							Load PDF					
Documentation								1 per page						
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print				
1	20/11/19 11:34	Singapore Accident Statement							Load PDF					
2	20/11/19 11:35	ESTIMATES							Load PDF					
3	20/11/19 11:45	PRELIMINARY ADVICE							Load PDF					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print				
1	07/01/20 09:12	SUPPLEMENTARY							Load PDF					

DOCUMENTS CHECKLIST

Reset | Save | Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119020419/R1VD3S2

Date: 07/01/2020

REFERENCE

Insured/Claimant: LIM TENG SHUEN EMIL Policy No: DMCPSN3054201900
Date of Loss: 14/11/2019 Nature of Claim: OD Claim No: SNM19D205447C01/BT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM8278R
Make & Model: MAZDA 3, 1.5 5DR M-HYBRID ASTINA (A) Engine No: P520613329
Reg. Date: 16/07/2019 (Man. Year: 2019) Chassis No: JM6BP2SAAK1100825
Colour: Grey Odometer: 5718 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$81,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R18 Rear Tyre Size: 215/45 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,997.80	7,203.50	2,794.30	27.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,380.00	3,940.00	2,440.00	38.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,377.80	11,143.50	5,234.30	31.96
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	15,877.80	10,643.50	5,234.30	32.97
+ GST 7.00/7.00% (S\$)	1,111.45	745.05	366.40	32.97
Nett Amount (S\$)	16,989.25	11,388.55	5,600.70	32.97

INSPECTION

Date of Assignment: 19/11/2019

Date Inspected: 19/11/2019 Inspected At:

27A Tanjong Penjur
Singapore 609042
Repairer: Trans Eurokars Pte Ltd

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2020)

Parts: 143 MAZDA 3 1.5 5DR M-HYBRID ASTINA (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMM8278R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	867.30 F	*867.30 F
2	1		*RETAINER RHS	Serviceable	20.50 F	*- F
3	1		*GUIDE RHS	Cracked	68.20 F	*68.20 F
4	1		*RETAINER SIDE RHS, GRILL OP	Necessary	11.00 F	*11.00 F
5	1		*COVER RHS, FOGLAMP	Serviceable	89.30 F	*- F
6	1		*BRACKET RHS, MODULE	Serviceable	81.20 F	*- F
7	1		*MONITOR BLIND RHS	Serviceable	1,800.70 F	*- F
8	1		*RETAINER CENTER LHS, SENSOR	Necessary	4.60 F	*4.60 F
9	1		*RETAINER CENTER RHS, SENSOR	Necessary	4.60 F	*4.60 F
10	2		*BRACKET CENTER, SENSOR	Cracked	46.80 F	*46.80 F
11	10		*CLIP, FRONT BUMPER	Necessary	37.00 F	*37.00 F
12	2		*FASTENER, FRONT BUMPER	Necessary	6.00 F	*6.00 F
13	2		*RUBBER SEAL, FRONT BUMPER	Necessary	4.80 F	*4.80 F
14	2		*RUBBER SEAL, FRONT BUMPER	Necessary	14.60 F	*14.60 F
15	2		*GROMMET, FRONT BUMPER	Necessary	10.40 F	*10.40 F
16	6		*RIVET, FRONT BUMPER	Necessary	24.00 F	*24.00 F
17	8		*RIVET, FRONT BUMPER	Necessary	44.00 F	*44.00 F
18	8		*RIVET, FRONT BUMPER	Necessary	73.60 F	*73.60 F
19	2		*RUBBER SEAL, FRONT BUMPER	Necessary	5.60 F	*5.60 F
20	2		*FASTENER, FRONT BUMPER	Necessary	6.40 F	*6.40 F
21	1		*GROMMET, FRONT BUMPER	Necessary	2.50 F	*2.50 F
22	1		*GROMMET, FRONT BUMPER	Necessary	2.50 F	*2.50 F
23	3		*TAPE PROTECTOR, SENSOR	Necessary	14.10 F	*14.10 F
24	1		*CHROME RHS	Cracked	298.00 F	*298.00 F
25	1		*FRONT GRILLE	Serviceable	527.40 F	*- F
26	2		*CLIP, FRONT GRILLE	Necessary	9.40 F	*9.40 F
27	1		*CLIP, FRONT GRILLE	Necessary	9.10 F	*9.10 F
28	4		*GROMMET, FRONT GRILLE	Necessary	14.80 F	*14.80 F
29	1		*GRILLE TOP	Scratched	690.80 F	*690.80 F
30	3		*FASTENER, GRILLE TOP	Necessary	9.60 F	*9.60 F
31	4		*RIVET, GRILLE TOP	Necessary	22.00 F	*22.00 F
32	10		*RIVET, GRILLE TOP	Necessary	92.00 F	*92.00 F
33	16		*RIVET, GRILLE TOP	Necessary	64.00 F	*64.00 F
34	2		*CLIP, GRILLE TOP	Necessary	12.80 F	*12.80 F
35	1		*FRONT FENDER RHS	Bent	415.90 F	*415.90 F
36	1		*STAY RHS, FENDER	Necessary	39.90 F	*39.90 F
37	1		*MUDGUARD RR RHS	Cut	185.90 F	*185.90 F
38	1		*MUDGUARD FRT RHS	Deformed	201.10 F	*201.10 F
39	15		*FASTENER, MUDGUARD	Necessary	45.00 F	*45.00 F
40	1		*WEATHERSTRIP, BONNET	Serviceable	55.90 F	*- F
41	1		*HEADLAMP RHS	Scratched	3,655.10 F	*3,655.10 F
42	1		*BRACKET RHS, HEADLAMP	Cracked	56.20 F	*56.20 F
43	5		*CLIP, HEADLAMP	Serviceable	32.00 F	*- F
44	1		*WASHER TANK	Deformed	51.50 F	*51.50 F
45	1		*FUNNEL, WASHER TANK	Serviceable	30.60 F	*- F
46	1		*GROMMET, WASHER TANK	Serviceable	4.70 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TANK, SUB-RADIATOR	Deformed	55.40 F	*55.40 F
48	1		*PIPE, WASHER TANK (NPA)	Serviceable	0.00 F	*- F
49	5		*RADIATOR COOLANT	Serviceable	72.00 F	*- F
50	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
51	1		*LABEL CAUTION	Necessary	3.50 F	*3.50 F
52	1		*LABEL CAUTION	Necessary	3.50 F	*3.50 F

F=Franchise part. S=SpcNett.

Total Parts (S\$)	9,997.80	7,203.50
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER AND FRONT FENDER RH. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	New	1,320.00	1,320.00
2	TO RESPRAY FRONT BUMPER, BONNET, FRONT FENDER RH, FRONT DOOR RH AND REAR DOOR RH.	New	3,150.00	1,890.00
3	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	New	560.00	0.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	New	250.00	100.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	250.00	150.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	350.00	180.00
7	TO SUPPLY BRILA PREMIUM COATING.	New	500.00	300.00
Gross Labour Cost (S\$)			6,380.00	3,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >