



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L		NAME : Mr Lim Teng Shuen, Emil		WIP : 55167	
3 ANSON ROAD		ADDRESS : 24 Lim Tai See Walk		EXCESS :	
#16-00 SPRINGLEAF TOWER		Singapore 267792		DATE: 18-Nov-19	
SINGAPORE 079909		TEL : 91277330Mr			
ATTN : MOTOR CLAIMS		FAX :			
VEH NO :		SMM8278R	DATE IN :	CONTACT PERSON :	Jess 63957874
CHASSIS NO :		JM6BP2SAAK1100825	MILEAGE :	TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :		MAZDA3 BP	DATE REG.: 16-Jul-19	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER <i>de</i>	1	MBCKA-50-031EBB		\$ 867.30
2	RETAINER RHS ?	1	MBCKA-50-0TOA		\$ 20.50
3	GUIDE RHS ?	1	MBCKA-50-A20B		\$ 68.20
4	RETAINER SIDE RHS, GRILLT OP ?	1	MBDGF-50-0T6B		\$ 11.00
5	COVER RHS, FOGLEAMP <i>X</i>	1	MBCKB-50-C11A		\$ 89.30
6	BRACKET RHS, MODULE ?	1	MBCKA-50-153C		\$ 81.20
7	MONITOR BLIND RHS ?	1	MB0J8-67-Y30B		\$ 1,800.70
8	RETAINER CENTER LHS, SENSOR <i>X</i>	1	MB0M5-67-UC5		\$ 4.60
9	RETAINER CENTER RHS, SENSOR <i>X</i>	1	MB0M6-67-UC5		\$ 4.60
10	BRACKET CENTER, SENSOR <i>X</i>	2	MB0J8-67-UC6		\$ 46.80
11	CLIP, FRONT BUMPER <i>na</i>	10	MC274-50-133		\$ 37.00
12	FASTENER, FRONT BUMPER <i>na</i>	2	MB45A-56-146A		\$ 6.00
13	RUBBER SEAL, FRONT BUMPER <i>na</i>	2	MBCKA-50-2G1A		\$ 4.80
14	RUBBER SEAL, FRONT BUMPER <i>na</i>	2	MBDWH-50-2G1		\$ 14.60
15	GROMMET, FRONT BUMPER <i>na</i>	2	MN243-50-0Z1		\$ 10.40
16	RIVET, FRONT BUMPER <i>na</i>	6	MS51S-51-833		\$ 24.00
17	RIVET, FRONT BUMPER <i>na</i>	8	MBCKA-50-355A		\$ 44.00
18	RIVET, FRONT BUMPER <i>na</i>	8	MTK21-50-355		\$ 73.60
19	RUBBER SEAL, FRONT BUMPER <i>na</i>	2	MBDGF-50-2G2		\$ 5.60
20	FASTENER, FRONT BUMPER <i>na</i>	2	MGD7A-50-EA1		\$ 6.40
21	GROMMET, FRONT BUMPER <i>na</i>	1	MBCKA-50-0U5		\$ 2.50
22	GROMMET, FRONT BUMPER <i>na</i>	1	MBCKA-50-0T5		\$ 2.50
23	TAPE PROTECTOR, SENSOR <i>na</i>	3	MBCKA-50-EM1		\$ 14.10
24	CHROME RHS <i>na</i>	1	MBCKA-50-7J0C		\$ 298.00
25	FRONT GRILLE <i>X</i>	1	MBCKB-50-711		\$ 527.40
26	CLIP, FRONT GRILLE <i>na</i>	2	MG46L-50-EB1		\$ 9.40
27	CLIP, FRONT GRILLE <i>na</i>	1	MGSH7-50-EB1		\$ 9.10
28	GROMMET, FRONT GRILLE <i>na</i>	4	MBCKA-50-ES1B		\$ 14.80
29	GRILLE TOP <i>na</i>	1	MBCKB-50-7E0D2M		\$ 690.80
30	FASTENER, GRILLE TOP <i>na</i>	3	MGD7A-50-EA1		\$ 9.60
31	RIVET, GRILLE TOP <i>na</i>	4	MBCKA-50-355A		\$ 22.00

32	RIVET, GRILLE TOP	ne /	10	MTK21-50-355		\$ 92.00
33	RIVET, GRILLE TOP	ne /	16	MS51S-51-833		\$ 64.00
34	CLIP, GRILLE TOP	ne /	2	MBCKA-56-145A		\$ 12.80
35	FRONT FENDER RHS	lt /	1	MBCJH-52-110		\$ 415.90
36	STAY RHS, FENDER	ne /	1	MBCJH-52-140		\$ 39.90
37	MUDGUARD RR RHS	port ?	1	MBCJH-56-130D		\$ 185.90
38	MUDGUARD FRT RHS	de /	1	MBCJH-56-13Y		\$ 201.10
39	FASTENER, MUDGUARD	ne /	15	MB45A-56-146A		\$ 45.00
40	WEATHERSTRIP, BONNET	X	1	MBCJH-56-770		\$ 55.90
41	HEADLAMP RHS	glt /	1	MBCJH-51-030B		\$ 3,655.10
42	BRACKET RHS, HEADLAMP	?	1	MBCKA-50-150A		\$ 56.20
43	CLIP, HEADLAMP	X	5	MBCKA-56-145A		\$ 32.00
44	WASHER TANK	?	1	MBCKA-67-481		\$ 51.50
45	FUNNEL, WASHER TANK	X	1	MBCKA-67-484		\$ 30.60
46	GROMME, WASHER TANK	X	1	MBCKB-67-491		\$ 4.70
47	TANK, SUB-RADIATOR	X	1	MPAF1-15-351		\$ 55.40
48	PIPE, WASHER TANK	X	1	MBCKA-67-501		TBA
49	RADIATOR COOLANT	X	5			\$ 72.00

TOTAL PARTS

\$ 9,890.80

TOTAL PARTS COST

\$ 9,890.80

Labour Description

1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER RH. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1320	\$ 1,320.00
2		TO RESPRAY FRONT BUMPER, BONNET, FRONT FENDER RH, FRONT DOOR RH AND REAR DOOR RH.	1890	\$ 3,150.00
3	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	NETT X	\$ 560.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION	100	\$ 250.00
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
7		TO SUPPLY BRILA PREMIUM COATING	NETT 300	\$ 500.00
8	MZ-BR-SUNDRI	SUNDRIES.	NETT 20	\$ 100.00

TOTAL LABOUR	\$ -	\$ 6,480.00
TOTAL PARTS	\$ -	\$ 9,890.80
TOTAL	\$ -	\$ 16,370.80
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -

GRAND TOTAL

\$

\$

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorized Signature

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pasul

Hp 90010068

5 days

19/11/19 @ 1140

EXCESS: TBA

REVERT

Resurvey before paint