



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 8177M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	BUCKLED / DISTORTED	1,889.70	1,380.00
1	REAR BUMPER RETAINER	DISTORTED	86.20	86.20
1	REAR BUMPER LAMP	SERVICEABLE	175.90	-
1	TOWING COVER	MISSING	102.00	62.00
	LESS 25% DISCOUNT		-563.45	-382.05
			1,690.35	1,146.15
	<b><u>LABOUR</u></b>			
	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS.		500.00	300.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		580.00	400.00
	TO INSTALL REVERSE SENSORS.		420.00	60.00
			1,500.00	760.00
<b>GRAND TOTAL</b>			<b>3,190.35</b>	<b>1,906.15</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,500.00</b>

Report Ref No. CS/FCI19020463/Kyd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.