



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19020463/Kyd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-04-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 6228R	Veh. Inspected	SLC 8177M
Policy No.		Coverage (\$)	0.00
Claim No.	D19007164MFSH	Excess (\$)	0.00
Assign From	JASON TEA	Assign Date	19/11/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE (A)	c.c	2493
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	AGH300057356	Colour	METALLIC BLACK
Odometer	286473	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50Z R18	KAPSEN	4 mm
L/H Front Tyre	235/50Z R18	KAPSEN	4 mm
R/H Rear Tyre	235/50Z R18	DAVANTI	5 mm
L/H Rear Tyre	235/50Z R18	DAVANTI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/11/2019	Inspection Date	19/11/2019
Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**