

ASS. REC. BY:

REF:

LPC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMK8011D Yr Regn: 2019, AprilType: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante C.C. 1591Colour: Black A/C: Insured / Std / NI / NASp. Reading: 8845 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH0841CMK4 8.93412Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 27/4/20Survey held at CYS WLDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / F.B. / C

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

SDE 8136R



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR NURLIZAWATI BINTE RAMLAN
BLK. 694A WOODLANDS DRIVE 62
#04-16 SINGAPORE 731694

POLICY NO : THIRD PARTY CLAIM
YOUR REF : GBE 5192 X (LONPAC)
OUR REF : TP 6098
VEHICLE NO : SMK 8011 D
MAKE/MODEL : HYUNDAI AVANTE
DATE OF ACCIDENT : 12.11.19

SURVEY BY

DATE : 13.11.19

- 1 PC FRONT DOOR RH
- 1 PC FRONT DOOR STICKER RH
- 1 PC FRONT DOOR OUTER HANDLE RH
- PC REAR DOOR RH
- PC REAR DOOR STICKER RH

S\$ 1,831.20 *del*
24.00 *del*
69.00 *RY*
1,775.00 *del*
24.00 *del*

S\$ 3,723.20
LESS 20% 744.64

S\$ 2,978.56

TO CHECK WIRING FUNCTION

S\$ 30.00 ✓

TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL

80.00 *30*

LABOUR CHARGES

500.00 *400.*

TO PUTTY AND SPRAY PAINTING CHARGES

600.00 *400*

S\$ 4,188.56

SIN DOLLARS: FOUR THOUSAND ONE HUNDRED EIGHTY-EIGHT AND CENTS FIFTY-SIX ONLY

Y OUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

Taufik 93415749
- WP
27/11/19
Resurvey before paint
for
taufik@kanto.com
04 days

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: