

INS. CASE OWNER:

CC⁶ / LPC1902 0483, AddressLKK:
IDAC:

Surveyor:

Jalan

DOI:

18/11/19

Date / Time:

18/11/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YP 3401B

Name of Insured:

SMRT RELOCATORS Pte

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

14/11/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: MATIVANAN DHEVA

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

18/11/19/05/00649

Policy No.:

18VL05001024

Make / Model:

Isuzu

Place of Accident:

Home Ave

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SG 809P



INSRS:

WSP:

Tel:

Liability:

RMKS:

WMT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

19/2/2020 FILE PAS TO TYPE MANDATE

9/3/2020 FILE PAS TO HAIL TO LOSER

* LIA search date is different to OIA.

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	SS (days) Reduction:	Confirm by:	
FINAL SETTLEMENT Date/Time: 6/3/2020 Confirm with Suky:		Email ☐ Call ☐	
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: N/C	If NO or B 28, Ass. Lia:	
Repair Cost: (w/6%)	SS 10165.00	02 reversed hit auto TP veh	
Loss of Rental (LOR):	SS - (days)		
Loss of Use (LOU):	SS 480.00 (\$ 60 x 8 days)		
Loss of Income (LOI):	SS - (\$ x days)		
LOR only ☐ LOU only ☒	LOR + LOU ☐ LOR + LO ☐ [Tick only one]		
GIA/LTA Search	SS 2.00		
Medical:	SS -	1) Claim status: Normal/Reject/Private Settle	
Disbursement:	SS - (e.g. Tow/ Independent)	2) Report Format: TP	
Legal Cost	SS -	3) Survey fee: 2400	
Total:	SS 10647.00	Global Sum SS:	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	SS 10647.00	Name 1: New Hoch Tech Motor Pte Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT
9/3/2020

ASS. REC. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLJ 8097 Yr Regn: 2016 NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Vezel C.C. 1496Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 47606 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11203180Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 18/11/19Survey held at NHTDes. of Damages Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Con Pac.</u>
	<u>LI - \$9500 (red \$11785.80 / 55%)</u>
	<u>MV:</u>
	<u>PV:</u>
	<u>Nett:</u>

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + PS. \$1

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ WASH (\$)

Report Format: _____

Lump Sum / LB: (\$)



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Adrian - LKK
Lampac - NPL

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP Lampac
Jia le.

14/11/2019

Accident date: 14/11/2019

Estimated repair cost for vehicle no: SLJ809P HONDA VEZEL 1.5 X A '16

CHASSIS: RU11203180

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet Distorted.		\$892.30 ✓
2	2	Front Bonnet Hinge Bent	\$48.50	\$97.00 ✓
3	1	Front Bonnet Lock Damaged		\$97.80 ✓
4	1	Front Bonnet Insulator crimped.		\$122.30 ✓
5	8	Front Bonnet Insulator Clip New	\$6.50	\$52.00 ✓ 30
6	2	Front Bonnet Inner Side Rubber New	\$37.50	\$75.00 +
7	2	Front Bonnet Inner Centre Rubber New	\$23.00	\$46.00 +
8	2	Front Head Lamp cracked	\$1,852	\$3,704 ✓
9	2	Front Head Lamp Lower Bracket Cracked.	\$35.00	\$70.00 ✓
10	1	Front Bumper Deformed		\$801.70 ✓
11	10	Front Bumper Clip New	\$6.50	\$65.00 30
12	2	Front Bumper Side Retainer New	\$27.10	\$54.20 ✓
13	1	Front Bumper Number Plate New		\$50.00 +
14	1	Front Bumper Centre Lower Garnish New		\$96.80 +
15	1	Front Bumper Reinforcement Bent		\$321.00 ✓
16	2	Front Bumper Reinforcement Top Cover 2 NP	\$24.20	\$48.40 +
17	4	Front Bumper Reinforcement Top Cover Clip New	\$6.50	\$26.00 +
18	1	Front Bumper Towing Cover New		\$15.70 +
19	1	Front Bumper Lower Spoiler New		\$351.00 +
20	2	Front Bumper Fog Lamp 2 NP	\$327.70	\$655.40 +
21	2	Front Bumper Fog Lamp Cover New	\$45.00	\$90.00 +
22	1	Front Grille Outer Cover crimped.		\$385.00 ✓
23	1	Front Grille Inner crimped		\$351.80 ✓
24	1	Front Grille Top Bracket crimped		\$38.70 ✓
25	1	Front Grille Chrome bent		\$75.00 ✓
26	8	Front Grille Clip New	\$6.50	\$52.00 10
27	1	Front Support Panel Buckled		\$576.20 ✓
28	1	Front Support Panel Top Cover Deformed		\$85.30 ✓

29	10	Front Support Panel Top Cover Clip	<i>xlec</i>	\$6.50	\$65.00 10
30	2	Front Support Panel Side Air Duct Cover	<i>NH NH</i>		\$77.50 X
31	8	Front Support Panel Side Air Duct Cover Clip	<i>NH NH</i>	\$6.50	\$52.00 X
32	2	Front Horn	<i>NH NH</i>	\$40.10	\$80.20 X
33	1	Front Air-Con Condenser	<i>Bent</i>		\$750.10 ✓
34	1	Front Air-Con Condenser Fan Motor Assy	<i>NH NH</i>		\$474.80 X
35	1	Front Radiator	<i>Dented</i>		\$1,250.60 ✓
36	1	Front Radiator Fan Motor Assy	<i>Cracked</i>		\$480.90 ✓
37	2	Front Fender	}	\$580.00	\$1,160.00 +
38	2	Front Fender Cowling		\$130.80	\$261.60 +
39	16	Front Fender Cowling Clip		\$6.50	\$104.00 +
40	2	Front Fender Cowling Protector		\$153.00	\$306.00 +
41	1	Front Wiper Garnish			\$240.70 +
42	1	Front Wiper Garnish Rubber			\$95.50 +
43	4	Front Wiper Garnish Clip		\$6.50	\$26.00 +
44	1	Front Radar Sensor	<i>cracked.</i>		\$2,455.00 1850
45	1	Front Fuse Box & Fuse Assy	<i>NH NH</i>		\$980.60 X
46	1	Front Air Cleaner Hose	}		\$75.00 +
47	1	Front Air Cleaner Air Duct			\$77.50 +

12083.9
9667.12

Subtotal :- \$16,905.80

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas

~~\$380.00~~ 120

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 50

Towing fee

2260

~~\$150.00~~ 60

Panel beating

~~\$1,800.00~~ 1000

Spray painting

~~\$1,800.00~~ 1000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$4,380.00

Total:- \$21,285.80

9.5K
07 Days

Total 11927.12 22688.68%
c/s: 9.5K
06 Days.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 911Z

Vehicle Details

Vehicle No.: SLJ809P
Vehicle to be Exported: No
Intended Deregistration Date: 14 Nov 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: L15B4403180
Chassis No.: RU11203180
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$22,548.00
Original Registration Date: 28 Nov 2016
First Registration Date: 28 Nov 2016
Transfer Count: 0
Actual ARF Paid: \$13,568.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Nov 2026
PARF Rebate Amount: \$10,176.00

Intended COE Rebate Details

COE Expiry Date: 27 Nov 2026
COE Category: A - Car up to 1600cc & 97kW
(130bhp)
COE Period(Years): 10
QP Paid: \$50,951.00
COE Rebate Amount: \$35,849.00
Total Rebate Amount: \$46,025.00

The information contained herein is correct as at 14 Nov 2019

OK

Shu Pei (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 20 November 2019 4:07 PM
To: Shu Pei (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving YP3401B (OI : LPC - TBA) AND SLJ809P (TP : LKK REF - CC6/LPC19020483/Adb3) on 14.11.2019 [External General]
Attachments: 20112019160246.pdf

Lonpac External - General

Our Ref : 18/19/19/VC05/022649


Dear Shu Pei,

Attached copy of insured's report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 20 November 2019 3:47 pm
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Jia Le (LKK Auto)
Subject: Direct Settlement - Accident Involving YP3401B (OI : LPC - TBA) AND SLJ809P (TP : LKK REF - CC6/LPC19020483/Adb3) on 14.11.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SLJ 809P at M/s New Hock Teck Motor Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. SLJ809P and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 14 day of 11 20 19.

Signature	:	
Name	:	<u>Bialink Rent-A-Car Pte Ltd</u>
ID No.	:	<u>2004029117</u>
Address	:	<u>No 18 Ubi Road 4 #01-11</u> <u>Ubi Car Mall S(408616)</u>
Witness Signature	:	
Witness Name	:	<u>Chew Yue Yin</u>
Witness ID	:	<u>S8826618H</u>
Witness Address	:	<u>1 Kaki Bukit Avenue 6 #01-43</u> <u>Singapore 417883</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC6/LPC19020483/Ada3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 20-03-2020	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 3401B	Veh. Inspected	SLJ 809P	
Policy No.	Z18VC05001034	Coverage (\$)	0.00	
Claim No.	18/19/19/VC05/022649	Excess (\$)	0.00	
Assign From		Assign Date	18/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11203180	Colour	SILVER	
Odometer	47606	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/11/2019	Inspection Date	18/11/2019	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 809P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	DISTORTED	892.30	892.30
2	FRONT BONNET HINGE @ \$48.50	BENT	97.00	97.00
1	FRONT BONNET LOCK	DAMAGED	97.80	97.80
1	FRONT BONNET INSULATOR	CRUMPLED	122.30	122.30
8	FRONT BONNET INSULATOR CLIP @\$6.50	NECESSARY	52.00	30.00
2	FRONT BONNET INNER SIDE RUBBER @ \$37.50	NOT NECESSARY	75.00	-
2	FRONT BONNET INNER CENTRE RUBBER @ \$23.00	NOT NECESSARY	46.00	-
2	FRONT HEAD LAMP @ \$1852.00	CRACKED	3,704.00	3,704.00
2	FRONT HEAD LAMP LOWER BRACKET @ \$35.00	CRACKED	70.00	70.00
1	FRONT BUMPER	DEFORMED	801.70	801.70
10	FRONT BUMPER CLIP @ \$6.50	NECESSARY	65.00	30.00
2	FRONT BUMPER SIDE RETAINER @ \$27.10	NECESSARY	54.20	54.20
1	FRONT BUMPER NUMBER PLATE	NOT NECESSARY	50.00	-
1	FRONT BUMPER CENTRE LOWER GARNISH	NOT NECESSARY	96.80	-
1	FRONT BUMPER REINFORCEMENT	BENT	321.00	321.00
2	FRONT BUMPER REINFORCEMENT TOP COVER @\$24.20	NOT NECESSARY	48.40	-
4	FRONT BUMPER REINFORCEMENT TOP COVER CLIP @ \$6.50	NOT NECESSARY	26.00	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	15.70	-
1	FRONT BUMPER LOWER SPOILER	NOT NECESSARY	351.00	-
2	FRONT BUMPER FOG LAMP @ \$327.70	NOT NECESSARY	655.40	-
2	FRONT BUMPER FOG LAMP COVER @ \$45.00	NOT NECESSARY	90.00	-
1	FRONT GRILLE OUTER COVER	CRACKED	385.00	385.00
1	FRONT GRILLE INNER	CRACKED	351.80	351.80
1	FRONT GRILLE TOP BRACKET	CRACKED	38.70	38.70
1	FRONT GRILLE CHROME	CUT	75.00	75.00
8	FRONT GRILLE CLIP @ \$6.50	NECESSARY	52.00	10.00
1	FRONT SUPPORT PANEL	BUCKLED	576.20	576.20
1	FRONT SUPPORT PANEL TOP COVER	DEFORMED	85.30	85.30
10	FRONT SUPPORT PANEL TOP COVER CLIP @ \$6.50	NECESSARY	65.00	10.00
2	FRONT SUPPORT PANEL SIDE AIR DUCT COVER	NOT NECESSARY	77.50	-

Report Ref No. CC6/LPC19020483/Ada3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
8	FRONT SUPPORT PANEL SIDE AIR DUCT COVER CLIP @ \$6.50	NOT NECESSARY	52.00	-
2	FRONT HORN @ \$40.10	NOT NECESSARY	80.20	-
1	FRONT AIR-CON CONDENSER	BENT	750.10	750.10
1	FRONT AIR-CON CONDENSER FAN MOTOR ASSY	NOT NECESSARY	474.80	-
1	FRONT RADIATOR	DENTED	1,250.60	1,250.60
1	FRONT RADIATOR FAN MOTOR ASSY	CRACKED	480.90	480.90
2	FRONT FENDER @ \$580.00	NOT NECESSARY	1,160.00	-
2	FRONT FENDER COWLING @ \$130.80	NOT NECESSARY	261.60	-
16	FRONT FENDER COWLING CLIP @ \$6.50	NOT NECESSARY	104.00	-
2	FRONT FENDER COWLING PROTECTOR @ \$153.00	NOT NECESSARY	306.00	-
1	FRONT WIPER GARNISH	NOT NECESSARY	240.70	-
1	FRONT WIPER GARNISH RUBBER	NOT NECESSARY	95.50	-
4	FRONT WIPER GARNISH CLIP @ \$6.50	NOT NECESSARY	26.00	-
1	FRONT RADAR SENSOR	CRACKED	2,455.00	1,850.00
1	FRONT FUSE BOX & FUSE ASSY	NOT NECESSARY	980.60	-
1	FRONT AIR CLEANER HOSE	NOT NECESSARY	75.00	-
1	FRONT AIR CLEANER AIR DUCT	NOT NECESSARY	77.50	-
	LESS 20% DISCOUNT		-	-2,416.78
			18,308.60	9,667.12
	LABOUR			
	TO REMOVE & REFIT AIR-CON CONDENSER, RADIATOR, FAN MOTOR & TOP UP GAS.		380.00	120.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	50.00
	TOWING FEE.		150.00	60.00
	PANEL BEATING.		1,800.00	1,000.00
	SPRAY PAINTING.		1,800.00	1,000.00
			4,380.00	2,260.00
	GRAND TOTAL		22,688.60	11,927.12
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,500.00

Report Ref No. CC6/LPC19020483/Ada3s2



Report Ref No. CC6/LPC19020483/Ada3s2

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.