



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. AC2003985
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
SINGAPORE 189556
ATTN: MUHAMMAD AIRWAN

INV Date 18/05/2020
Reference CS/INC19020493/Gtd3n2
Code INC



PROFESSIONAL SERVICE FEE

Vehicle No. SMG 4160D
Insured Veh. SJS 3089G
Claim No. MT/1071932-001
Policy No.
Accident Date 15/11/2019
Inspection Date 19/11/2019

Description	Total
Damage Assessment	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020493/Gtd3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 18-05-2020



ATTN: MUHAMMAD AIRWAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJS 3089G	Veh. Inspected	SMG 4160D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1071932-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	19/11/2019

2. Vehicle Particulars & Condition

Make & Model	RENAULT GRAND SCENIC IV 1.5	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	VF1RFA00761665863	Colour	WHITE
Odometer	86914 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R20	GOODYEAR	6 mm
L/H Front Tyre	195/55 R20	GOODYEAR	6 mm
R/H Rear Tyre	195/55 R20	GOODYEAR	6 mm
L/H Rear Tyre	195/55 R20	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/11/2019	Inspect Date / Time	19/11/2019 (03:30 PM)
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 4160D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER UPPER	CUT	1,650.00	1,281.32
1	REAR BUMPER LOWER	CUT	752.00	480.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	85.00	-
2	REAR BUMPER SIDE RETAINER @\$85.00	NOT NECESSARY	170.00	-
1	REAR BUMPER REFLECTOR O/S	NOT NECESSARY	186.00	-
1	REAR BUMPER LOWER MOULDING	NOT NECESSARY	551.00	-
1	REAR BUMPER INNER PAD	NOT NECESSARY	345.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	769.00	-
2	REAR BUMPER SIDE SUPPORT @\$154.00	NOT NECESSARY	308.00	-
2	REAR BUMPER CENTRE SUPPORT @\$147.00	NOT NECESSARY	294.00	-
2	REAR BUMPER SIDE COVER @\$484.00	NOT NECESSARY	968.00	-
1	REAR BUMPER LOWER COWLING	NOT NECESSARY	337.00	-
1	REAR FENDER INNER COWLING O/S	NOT NECESSARY	243.00	-
1	REAR FENDER SPLASH GUARD O/S	NOT NECESSARY	56.00	-
1	REAR FENDER AIR VENT O/S	NOT NECESSARY	216.00	-
1	REAR WHEEL BEARING O/S	NOT NECESSARY	396.00	-
1	REAR KNUCKLE O/S	NOT NECESSARY	573.00	-
1	REAR SHOCK ABSORBER O/S	NOT NECESSARY	499.00	-
1	REAR SHOCK ABSORBER TOP MOUNT O/S	NOT NECESSARY	85.00	-
	LESS 10% DISCOUNT		-848.30	-176.13
			7,634.70	1,585.19
<u>SPECIAL NETT ITEMS</u>				
8	REAR FENDER INNER COWLING CLIPS O/S @\$6.50 (SN)	NOT NECESSARY	52.00	-
10	REAR BUMPER CLIPS @\$6.50 (SN)	NECESSARY	65.00	40.00
2	REVERSE SENSOR @\$280.00 (SN)	NOT NECESSARY	560.00	-
1	REAR ALLOY WHEEL 20" O/S (LOCAL REPAIR)(SN)	SCRATCHED	550.00	100.00
1	REAR TYRE 20" O/S (SN)	NOT NECESSARY	380.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			1,657.00	140.00

Report Ref No. CS/INC19020493/Gtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.		1,000.00	200.00
	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS.	NOT NECESSARY	50.00	-
	TO REMOVE AND REFIT O/S REAR TYRE & RIM.TO PERFORM TYRE BALANCING.		50.00	20.00
	TO REMOVE AND REFIT O/S REAR UNDERCARRIAGE FOR REPLACEMENT OF PARTS.	NOT NECESSARY	200.00	-
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY REAR BUMPER,END PANEL,O/S REAR FENDER AND OTHER AFFECTED AREA/PANEL.		800.00	200.00
	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR.	NOT NECESSARY	100.00	-
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.		100.00	60.00
			2,300.00	480.00
GRAND TOTAL			11,591.70	2,205.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,750.00

Report Ref No. CS/INC19020493/Gtd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 4160D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 4160D

RE-INSPECTION

