

Assignment

ASS. REC. BY:

REF: CS/INC19020499/0td3

Special Instructions:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Hazalysa B/ lbunhim

of

INC

Date/Time: 9:52am @ 10/11/19

Estimated Cost:

Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 3281A

Insured:

SLN 9343K

at Workshop m/s

800n Huck Motor

Tel:

65425119

of

10 Amk Ind. Park 24 #01-05/06

Policy No:

Claim No:

MP/1071949-001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/11/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:59am @ 10/11/19

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction

10/11/19

SHC 3281A - CC4/11/19023367/7116312 DOA: 6/12/2017

SLN 93431-X

ASSIGNMENT

02 2027 March

2019 March

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No. _____
 at Workshop no. _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GDS / PR: _____ Consistent? : Yes or No
 Est. Repairs: 10 days Res.: Yes or No
 Claim Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SHC 3281A**
 Type: M Car / M Cycle / Bus / Van / Lorry / Truck Prime Mover /
 Truck / Trailer or
 Make: **Toyota Prius** Ch: **1798**
 Color: **Blue** Age: Insured / Std / NI / NA
 Sp Reading: **72275** I/Callo: Insured / Std / NI / NA
 Eng No: **2ZR2B95295**
 Ch No: **JTDKB3Fu403078827**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Mod: Nil / Shim / STD A/Rim or
 Tyre Size: F: **195/65 R15**
 R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Devanti**

Front _____ Rear _____
 R/Bal: **S** mm R/Bal: **S** mm
 L/Bal: **S** mm L/Bal: **S** mm
 D.O.A: **16/11/2019** D.O.I: **19/11/2019**
 Survey held at **Chunni AMC** **11.45**

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front y Rr

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

NTUC 8LR 37804 SLN 9343K

07/01/2020

Invoice 2/5 19500/- with 10 days of rev
(Red: 26283.28 : 57%)

RECEIVED 08 JAN 2020

Date/Time, File Print 147



Prof. Report

0 **Hi Typist**



Final Report

Date/Time, File Print 147

Days Of Repair: **10**

Resurvey No. of Trip: **2**

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Week end (\$)

Survey Fee:

Transportation

\$ = 175.00

Phone

Other

TOTAL

For **Form 147**

Temp **07/01/2020**

TP

19500/-

Nivitha (LKK Auto)

From: Hazalya Binte Ibrahim <hazalya.ibrahim@income.com.sg>
Sent: Tuesday, 19 November 2019 3:26 PM
To: Admin-D (LKKAuto); assignments
Cc: Hazalya Binte Ibrahim
Subject: RE: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Re-send with details.

Thank you.

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Operations, Motor & Personal Lines (PL)
www.income.com.sg

income
more affluent



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

From: Hazalya Binte Ibrahim
Sent: Tuesday, 19 November 2019 9:52 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Alice Low <alice.lowkc@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 19/11/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1071694-002	SLR1040R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SJP7344J	16/11/19	
2	Eng Huey Huey	MT/1071605-001	SLD8452M	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SJN6985B	15/11/19	
3	Serene Lim	MT/1071721-001	SLF9471R	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		PC601K	15/11/19	
4	Azhari	MT/1071695-002	SLL3057L	LION CITY RENTALS PTE LTD	60 JALAN LAM HUAT #04-01 CARROS CENTRE SINGAPORE 737869	S.T.Sim / 97422188		SLZ3659B	15/11/19	
5	Eng Huey Huey	MT/1071993-001	SLA1405J	OPTIMA WERKZ PTE LTD	9A SERANGOON NORTH AVE 5	Sharon Ten / 6481 1522		SJU5625K	17/11/19	avoid 1PM - 2PM
6	Wo Jessie	MT/1071949-001	SHC3281A	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SLN9343K	16/11/19	65425119 or 6542 7162
7	Quek Swee Keng	MT/1071863-002	SHD3009R	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SMK5648L	16/11/19	65425119 or 6542 7162
8	Quek Swee Keng	MT/1071765-002	SHA7757D	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SIN48232	16/11/19	65425119 or 6542 7162
9	Serene Lim	MT/1070016-002	EW3366U	TROPICAL SUCCESS AUTO CARE	BLK 5032 #01-299/303 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569535	Calvin / 64817773		SLG4655E	05/11/19	
10	Muhammad Airwan	MT/1071969-001	YP9666P	WENG KEE MOTOR	BLK 1019 #01-366 YISHUN INDUSTRIAL PARK A	Victor Wong Qi Zhi / 6854 1273 / 8182 1895		SLG9527G	07/11/19	
11	Jeff Lin	MT/1071637-002	SGK775G	AT AUTO CONSULTANT	BLK 01 SIN MING INDUSTRIAL ESTATE	Alan Tan / 83868989		SKD8863Y	15/11/19	

Warmest Regards

Hazalya Bte Ibrahim
Admin Assistant
Motor Department
T +65 6430 7902
www.income.com.sg



in with
you

At Income, we are 'In with You' on Performance, Growth,
Innovation and Impact. These attributes reflect what we promise
as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 18/11/2019 09:37
 Date Of Accident 16/11/2019 12:50
 Exact Location Of Accident TPE > CHANGI AIRPORT B4 KPE EXIT 7A
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC3281A
Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No

Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer TOYOTA
 Model PRIUS HYBRID 4G

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number MCOM0015

Cover Note Number

Driver

Name of Driver FOO MENG TONG
 NRIC No S1638838F
 Date Of Birth 01/01/1967
 Occupation OUTDOOR
 Date Of Driving Pass 24/01/1986
 Driving Experience 33 YEARS AND 9 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-90621429
 Fax Number
 Contact Number
 EMail Address FOOMENGTONG64@GMAIL.COM

Address BLK 134 VERVALE STREET
#10-722

Postcode 540134

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 4

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: -

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLN9343K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver YONG JING WEN

NRIC/Passport Number

Contact Number 97307906

Address

Postcode

Insurance Company Name

Nature Of Damage FRONT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKZ682P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PANG WEI SHYANG
NRIC/Passport Number	S8570435D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT AND REAR
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SLS3780U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	FOO MENG TONG
NRIC/Passport Number	S1638838F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

(A) SHC 3081 A	
(B) SLN 9343 K	
(C) SKZ 682 P	
(D) SLG 3780 U	

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON: 16 Nov 2019 @ 12:50 hrs @ I

vehicle (A) was driving straight along the above location. Suddenly, veh (C) E-brake in front. I, veh (A) also E-brake and stop few seconds later. Veh (B) from the rear hit vehicle (A) Rear. @ the point of accident, veh (A) No para. veh. C hit veh (A) Rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHC 3281A

MAKE :

MODEL : TOYOTA PRIUS

DATE : 18.11.2019

TEL NO : 6542 5119

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
BONNET <i>Dented</i>			\$ 950.50
INSULATOR, HOOD <i>SVC</i>			\$ 398.10
INSULATOR CLIPS <i>SVC</i>			\$ 3.60
BONNET HINGE (RH) <i>BT</i>			\$ 57.70
BONNET HINGE (LH) <i>BT</i>			\$ 57.70
BONNET LOCK <i>BT</i>			\$ 132.60
RADIATOR GRILLE <i>broken/deformed</i>			\$ 438.00
RADIATOR GRILLE EMBLEM <i>Dented</i>			\$ 88.00
LAMP ASSY, FOG, RH <i>NW</i>			\$ 920.00
LAMP ASSY, FOG, LH <i>NW</i>			\$ 920.00
FRONT BUMPER COVER <i>Dented</i>			\$ 499.90
FRONT BUMPER REINFORCEMENT <i>Dented</i>			\$ 696.40
FRONT BUMPER REINFORCEMENT ABSORBER <i>BT</i>			\$ 115.70
FRONT BUMPER SPONGE <i>form</i>			\$ 78.80
FRONT BUMPER CENTRE GRILLE <i>NW</i>			\$ 301.90
FRONT BUMPER LOWER GRILLE <i>deformed/broken</i>			\$ 166.90
FRONT BUMPER CLIPS <i>NW</i>			\$ 22.00
FRONT BUMPER SIDE RETAINER <i>NW</i>		\$ 77.00	\$ 154.00
ENGINE UNDER COVER (RR) <i>NW</i>			\$ 457.40
FRONT BUMPER TOP GARNISH <i>SVC</i>			\$ 225.40
FRONT BUMPER CENTRE FRAME <i>NW</i>			\$ 236.90
BRACKET, FRONT BUMPER SIDE, RH <i>NW</i>			\$ 82.30
BRACKET, FRONT BUMPER SIDE, LH <i>NW</i>			\$ 82.30
UNIT ASSY, HEADLAMP, RH (LED) <i>mainly broken</i>			\$ 3,455.00
UNIT ASSY, HEADLAMP, LH (LED) <i>mainly broken</i>			\$ 3,455.00
HEAD LAMP PANEL (RH) <i>2 BT/Dented</i>			\$ 240.10
HEAD LAMP PANEL (LH) <i>2 BT/Dented</i>			\$ 240.10
TOP PANEL CENTRE <i>BT/Dented</i>			\$ 364.90
TOP PANELSIDE, LH <i>BT</i>			\$ 145.90
TOP PANEL SIDE, RH <i>BT</i>			\$ 145.90
BRACE PANEL <i>BT</i>			\$ 75.20
RADIATOR ASSY <i>2 BT/punctured</i>			\$ 1,841.80
RADIATOR FAN COWLING ASSY <i>NW</i>			\$ 661.30
RADIATOR TOP HOSE, LH <i>NW</i>			\$ 43.03
RADIATOR TOP HOSE, RH <i>NW</i>			\$ 42.60
RADIATOR BOTTOM MOUNTING <i>NW</i>			\$ 27.50
STAY, RADIATOR SUPPORT, RH <i>NW</i>			\$ 65.70
STAY, RADIATOR SUPPORT, LH <i>NW</i>			\$ 65.70
RADIATOR FAN BLADE (RH) <i>NW</i>			\$ 233.10
RADIATOR FAN BLADE (LH) <i>NW</i>			\$ 233.10
RADIATOR FAN MOTOR (RH) <i>NW</i>			\$ 543.70
RADIATOR FAN MOTOR (LH) <i>NW</i>			\$ 543.70
DEFLECTOR, RADIATOR SIDE, RH <i>deformed SVC</i>			\$ 83.50
DEFLECTOR, RADIATOR SIDE, LH <i>deformed SVC</i>			\$ 77.00
HORN <i>NW</i>		\$ 112.71	\$ 225.42
CLEANER ASSY. AIR <i>deformed</i>			\$ 970.30

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR TRUNK LID COVER <i>1st</i>			\$ 1,126.60	✓
REAR TRUNK LID LOCK <i>NH</i>			\$ 457.90	X
REAR TRUNK LID COVER TRIM BOARD <i>rept NH</i>			\$ 254.40	X
REAR TRUNK LID RUBBER <i>defunct</i>			\$ 365.20	✓
REAR TRUNK LID GLASS (BLACK COLOR) <i>NH</i>			\$ 1,569.70	X
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>rept</i>			\$ 889.70	X
REAR TRUNK LID LOGO (PRIUS) <i>NH</i>			\$ 52.90	✓
REAR TRUNK LID LOGO (HYBRID) <i>NH</i>			\$ 52.90	✓
REAR TRUNK LID LOGO (TOYOTA STAR) <i>NH</i>			\$ 47.00	✓
REAR BUMPER <i>Dented Horn</i>			\$ 458.60	✓
REAR BUMPER RE-INFORCEMENT <i>Dented</i>			\$ 318.80	✓
REAR BUMPER UNDER COVER <i>destroyed / broken</i>			\$ 552.60	✓
REAR BUMPER SIDE RETAINER, RH <i>NH</i>			\$ 112.70	X
REAR BUMPER UNDER SIDE COVER (RH) <i>defunct</i>			\$ 232.00	✓
REAR BUMPER UNDER SIDE CENTRE COVER <i>defunct destroyed / broken</i>			\$ 552.60	✓
REAR BUMPER TOWING COVER <i>destroyed</i>			\$ 82.70	✓
REAR BUMPER CLIPS <i>NH</i>			\$ 22.00	✓
ARM SUB-ASSY, REAR BUMPER, RH <i>1st NH</i>			\$ 139.60	X
ARM SUB-ASSY, REAR BUMPER, LH <i>NH</i>			\$ 139.60	X
SEAL, REAR BUMPER SIDE, RH <i>1st / scratched</i>			\$ 148.40	✓
TAIL LAMP ASSY (UPPER) (LH/RH) <i>crack / wound crack</i>		\$ 557.90	\$ 1,115.80	✓
TAIL LAMP ASSY (LOWER) (LH/RH) <i>crack</i>		\$ 548.40	\$ 1,096.80	✓
REAR END PANEL <i>Dented</i>			\$ 602.10	✓
REAR END PANEL GARNISH <i>NH</i>			\$ 165.80	X
REAR SPARE TYRE PANEL <i>Dented rep</i>			\$ 667.70	mm X
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) <i>NH</i>			\$ 101.40	X
REAR FIBER TOOL BOX <i>NH</i>			\$ 698.00	X
REAR EXHAUST PIPE <i>Dented</i>			\$ 1,163.40	✓
REAR EXHAUST PIPE HANGER <i>NH</i>			\$ 40.70	X
REAR EXHAUST PIPE INSULATOR <i>1st</i>			\$ 314.60	✓
REAR FENDER, RH <i>NH</i>			\$ 836.70	X
REAR FENDER PANEL, ROOF SIDE OUTER, RH <i>rept</i>			\$ 311.00	X
REAR FENDER TRIMBOARD (RH) <i>NH</i>			\$ 725.00	X
REAR FENDER AIR DUCT <i>NH</i>			\$ 165.10	X
REAR CHASSIS MEMBER <i>NH</i>			\$ 1,180.80	X
REAR FLOOR PANEL SIDE (LH) <i>NH</i>			\$ 276.20	X
REAR FLOOR PANEL SIDE (RH) <i>NH</i>			\$ 276.20	X
REAR WINDSCREEN GLASS WITH MOULDING <i>NH</i>			\$ 1,778.30	X
REAR WIRING ASSY <i>NH</i>			\$ 582.40	X
SPOILER SUB-ASSY, REAR <i>NH</i>			\$ 953.70	X
SUB TOTAL			\$ 20,627.60	
LESS 20% <i>25%</i>			\$ 4,125.52	
DISCOUNTED TOTAL			\$ 16,502.08	

830500
622830

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
AIR DUCT <i>broken</i>			\$ 129.40	✓
INLET ASSY, AIR CLEANER <i>SVC</i>			\$ 132.00	X
AIR DUCT CENTRE <i>MM</i>			\$ 94.03	X
CONDENSER ASSY, W/RECEIVER <i>permanently</i>			\$ 1,336.60	✓
FENDER SUB-ASSY, FRONT LH <i>Dented</i>			\$ 945.30	✓
FENDER SUB-ASSY, FRONT RH <i>Dented</i>			\$ 945.30	✓
FRONT FENDER SHIELD, LH <i>MM</i>			\$ 196.60	X
FRONT FENDER SHIELD, RH <i>MM</i>			\$ 196.60	X
FRONT FENDER SHIELD CLIP <i>MM</i>			\$ 38.00	X
FRONT FENDER HYBRID EMBLEM, LH <i>Hec</i>			\$ 53.50	✓
FRONT FENDER HYBRID EMBLEM, RH <i>Hec</i>			\$ 53.50	✓
HYBRID INVERTER SPARE TANK <i>MM</i>			\$ 371.30	X
HYBRID INVERTER BYPASS HOSE (INLET) <i>MM</i>			\$ 42.60	X
HYBRID INVERTER BYPASS HOSE (OUTLET) <i>MM</i>			\$ 29.30	X
HYBRID COOLING PUMP MOTOR <i>MM</i>			\$ 432.20	X
		17702.00		
		13276.50		
SUB TOTAL			\$ 25,861.88	
LESS 20% <i>25%</i>			\$ 5,172.38	
DISCOUNTED TOTAL			\$ 20,689.50	
FRONT NO. PLATE <i>MM</i>			\$ 25.00	NETT ✓
FRONT NO PLATE TRIM COVER <i>MM</i>			\$ 30.00	NETT ✓
FRONT NO. PLATE GARNISH <i>broken</i>			\$ 99.00	NETT ✓
FRONT FENDER ADVERTISEMENT LOGO (LH/RH) <i>Hec</i>		\$ 100.00	\$ 200.00	NETT ✓
		354.00	\$ 354.00	
LABOUR CHARGE				
Panel Beating			\$ 1,000.00	800/-
Spray Painting Charge			\$ 1,000.00	800/-
Wiring Charge			\$ 50.00	30/-
Tuff Kote			\$ 100.00	40/-
Towing Charge			\$ 90.00	MM
Remove/Refill Aircon & Refill Gas			\$ 150.00	80/-
Diagnosis & Resetting To Erase Fault Code			\$ 480.00	MM
		1750.00		
TOTAL LABOUR			\$ 2,870.00	

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR TRUNK LID APPS STICKER <i>Nec</i>			\$ 40.00	NETT ✓
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>Nec</i>			\$ 60.00	NETT ✓
REAR BUMPER REVERSE SENSOR <i>Don</i>			\$ 135.70	NETT ✓
REAR FENDER ADVERTISEMENT LOGO (LH/RH) <i>Nec</i>			\$ 100.00	NETT ✓
REAR WINDSCREEN SEALANT <i>Nec</i>			\$ 46.00	NETT ✓
REAR CAMERA <i>Nec</i>			\$ 500.00	NETT X
		281.70		
			\$ 881.70	
LABOUR CHARGE				
Panel Beating			\$ 2,000.00	1000/-
Spray Painting Charge			\$ 1,500.00	1000/-
Wiring Charge			\$ 50.00	30/-
Tuff Kote			\$ 100.00	40/-
Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
Remove/Refix Reverse Sensor			\$ 80.00	40/-
Remove/Refix Fuel Tank			\$ 150.00	70/-
Remove/Refix Exhaust Pipe			\$ 150.00	60/-
		2330.00		
			\$ 4,300.00	
			\$ 45,597.28	
			45795.68	
		24220.50		
		186.00		
		24406.50		
		19500/-		
19/11/2019 @ 1145hr N/A Antenna 2/ Same 10 days. Ryan LKK Auto				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020499/Dtd3n2

73 BRAS BASAH ROAD

Date: 13-01-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: WO JESSIE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLN 9343K	Veh. Inspected	SHC 3281A
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1071949-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTI IBRAHIM	Assign Date	19/11/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDKB3FU403078827	Colour	BLUE
Odometer	72275 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	5 mm
L/H Front Tyre	195/65 R15	DAVANTI	5 mm
R/H Rear Tyre	195/65 R15	DAVANTI	5 mm
L/H Rear Tyre	195/65 R15	DAVANTI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/11/2019	Inspect Date / Time	19/11/2019 (11:45 AM)
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3281A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	DENTED	950.50	950.50
1	INSULATOR,HOOD	SERVICEABLE	398.10	-
1	INSULATOR CLIPS	SERVICEABLE	3.60	-
1	BONNET HINGE (RH)	BENT	57.70	57.70
1	BONNET HINGE (LH)	BENT	57.70	57.70
1	BONNET LOCK	BENT	132.60	132.60
1	RADIATOR GRILLE	BROKEN / DEFORMED	438.00	438.00
1	RADIATOR GRILLE EMBLEM	DENTED	88.00	88.00
1	LAMP ASSY,FOG,RH	NOT NECESSARY	920.00	-
1	LAMP ASSY,FOG,LH	NOT NECESSARY	920.00	-
1	FRONT BUMPER COVER	DENTED	499.90	499.90
1	FRONT BUMPER REINFORCEMENT	DENTED	696.40	696.40
1	FRONT BUMPER REINFORCEMENT ABSORBER	BENT	115.70	115.70
1	FRONT BUMPER SPONGE	TORN	78.80	78.80
1	FRONT BUMPER CENTRE GRILLE	NOT FITTED	301.90	-
1	FRONT BUMPER LOWER GRILLE	DEFORMED / BROKEN	166.90	166.90
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
2	FRONT BUMPER SIDE RETAINER @\$77.00	NOT NECESSARY	154.00	-
1	ENGINE UNDER COVER (RR)	NOT NECESSARY	457.40	-
1	FRONT BUMPER TOP GARNISH	SERVICEABLE	225.40	-
1	FRONT BUMPER CENTRE FRAME	NOT NECESSARY	236.90	-
1	BRACKET,FRONT BUMPER SIDE,RH	NOT NECESSARY	82.30	-
1	BRACKET,FRONT BUMPER SIDE,LH	NOT NECESSARY	82.30	-
1	UNIT ASSY,HEADLAMP,RH (LED)	MOUNTING BROKEN	3,455.00	3,455.00
1	UNIT ASSY,HEADLAMP,LH (LED)	MOUNTING BROKEN	3,455.00	3,455.00
1	HEAD LAMP PANEL (RH)	BENT / DENTED	240.10	240.10
1	HEAD LAMP PANEL (LH)	BENT / DENTED	240.10	240.10
1	TOP PANEL CENTRE	BENT / DENTED	364.90	364.90



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TOP PANEL SIDE,LH	BENT	145.90	145.90
1	TOP PANEL SIDE,RH	BENT	145.90	145.90
1	BRACE PANEL	BENT	75.20	75.20
1	RADIATOR ASSY	BENT / PUNCTURE	1,841.80	1,841.80
1	RADIATOR FAN COWLING ASSY	NOT NECESSARY	661.30	-
1	RADIATOR TOP HOSE,LH	NOT NECESSARY	43.03	-
1	RADIATOR TOP HOSE,RH	NOT NECESSARY	42.60	-
1	RADIATOR BOTTOM MOUNTING	NOT NECESSARY	27.50	-
1	STAY,RADIATOR SUPPORT,RH	NOT NECESSARY	65.70	-
1	STAY,RADIATOR SUPPORT,LH	NOT NECESSARY	65.70	-
1	RADIATOR FAN BLADE (RH)	NOT NECESSARY	233.10	-
1	RADIATOR FAN BLADE (LH)	NOT NECESSARY	233.10	-
1	RADIATOR FAN MOTOR (RH)	NOT NECESSARY	543.70	-
1	RADIATOR FAN MOTOR (LH)	NOT NECESSARY	543.70	-
1	DEFLECTOR,RADIATOR SIDE,RH	SERVICEABLE	83.50	-
1	DEFLECTOR,RADIATOR SIDE,LH	SERVICEABLE	77.00	-
2	HORN @\$112.71	NOT NECESSARY	225.42	-
1	CLEANER ASSY,AIR	DEFORMED	970.30	970.30
1	AIR DUCT	BROKEN	129.40	129.40
1	INLET ASSY,AIR CLEANER	SERVICEABLE	132.00	-
1	AIR DUCT CENTRE	NOT NECESSARY	94.03	-
1	CONDENSER ASSY,W/RECEIVER	PUNCTURE	1,336.60	1,336.60
1	FENDER SUB-ASSY,FRONT LH	DENTED	945.30	945.30
1	FENDER SUB-ASSY,FRONT RH	DENTED	945.30	945.30
1	FRONT FENDER SHIELD,LH	NOT NECESSARY	196.60	-
1	FRONT FENDER SHIELD,RH	NOT NECESSARY	196.60	-
1	FRONT FENDER SHIELD CLIP	NOT NECESSARY	38.00	-
1	FRONT FENDER HYBRID EMBLEM,LH	NECESSARY	53.50	53.50
1	FRONT FENDER HYBRID EMBLEM,RH	NECESSARY	53.50	53.50
1	HYBRID INVERTER SPARE TANK	NOT NECESSARY	371.30	-
1	HYBRID INVERTER BYPASS HOSE (INLET)	NOT NECESSARY	42.60	-
1	HYBRID INVERTER BYPASS HOSE (OUTLET)	NOT NECESSARY	29.30	-
1	HYBRID COOLING PUMP MOTOR	NOT NECESSARY	432.20	-

Report Ref No. CS/INC19020499/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TRUNK LID COVER	BENT	1,126.60	1,126.60
1	REAR TRUNK LID LOCK	NOT NECESSARY	457.90	-
1	REAR TRUNK LID COVER TRIM BOARD	NOT NECESSARY	254.40	-
1	REAR TRUNK LID RUBBER	DEFORMED	365.20	365.20
1	REAR TRUNK LID GLASS (BLACK COLOR)	NOT NECESSARY	1,569.70	-
1	GARNISH SUB-ASSY BACK DOOR,OUTSIDE	TO REPAIR SEE LABOUR	889.70	-
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	47.00	47.00
1	REAR BUMPER	DENTED / TORN	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	DENTED	318.80	318.80
1	REAR BUMPER UNDER COVER	DISLodge / BROKEN	552.60	552.60
1	REAR BUMPER SIDE RETAINER,RH	NOT NECESSARY	112.70	-
1	REAR BUMPER UNDER SIDE COVER (RH)	DEFORMED	232.00	232.00
1	REAR BUMPER UNDER SIDE CENTRE COVER	DISLodge / BROKEN	552.60	552.60
1	REAR BUMPER TOWING COVER	DISLodge	82.70	82.70
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	ARM SUB-ASSY,REAR BUMPER,RH	NOT NECESSARY	139.60	-
1	ARM SUB-ASSY,REAR BUMPER,LH	NOT NECESSARY	139.60	-
1	SEAL,REAR BUMPER SIDE,RH	BENT / SCRATCHED	148.40	148.40
2	TAIL LAMP ASSY (UPPER)(LH/RH) @\$557.90	CRACKED / MOUNTING CRACKED	1,115.80	1,115.80
2	TAIL LAMP ASSY (LOWER)(LH/RH) @\$548.40	CRACKED	1,096.80	1,096.80
1	REAR END PANEL	DENTED	602.10	602.10
1	REAR END PANEL GARNISH	NOT NECESSARY	165.80	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	667.70	-
1	REAR SPARE TYRE CUSHION)FLR BOARD CENTRE)	NOT NECESSARY	101.40	-
1	REAR FIBER TOOL BOX	NOT NECESSARY	698.00	-
1	REAR EXHAUST PIPE	DENTED	1,163.40	1,163.40

Report Ref No. CS/INC19020499/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST PIPE HANGER	NOT NECESSARY	40.70	-
1	REAR EXHAUST PIPE INSULATOR	BENT	314.60	314.60
1	REAR FENDER,RH	NOT NECESSARY	836.70	-
1	REAR FENDER PANEL,ROOF SIDE OUTER,RH	TO REPAIR SEE LABOUR	311.00	-
1	REAR FENDER TRIMBOARD (RH)	NOT NECESSARY	725.00	-
1	REAR FENDER AIR DUCT	NOT NECESSARY	165.10	-
1	REAR CHASSIS MEMBER	NOT NECESSARY	1,180.80	-
1	REAR FLOOR PANEL SIDE (LH)	NOT NECESSARY	276.20	-
1	REAR FLOOR PANEL SIDE (RH)	NOT NECESSARY	276.20	-
1	REAR WINDSCREEN GLASS WITH MOULDING	NOT NECESSARY	1,778.30	-
1	REAR WIRING ASSY	NOT NECESSARY	582.40	-
1	SPOILER SUB-ASSY,REAR	NOT NECESSARY	953.70	-
1	R/W MLDG (ADDITIONAL)	NECESSARY	54.00	54.00
2	R/W DAM KIT UPPER (75575-48020) @\$42.00 (ADDITIONAL)	NECESSARY	84.00	84.00
1	T/G FIX GLASS MLDG LOWER (ADDITIONAL)	NECESSARY	38.00	38.00
1	T/G FIX GLASS MLDG,RH (ADDITIONAL)	NECESSARY	36.00	36.00
1	T/G FIX GLASS MLDG,LH (ADDITIONAL)	NECESSARY	36.00	36.00
	LESS 20% DISCOUNT		-9,347.50	-
	LESS 25% DISCOUNT		-	-6,563.75
			37,389.98	19,691.25
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE (SN)	BENT	25.00	25.00
1	FRONT NO PLATE TRIM COVER (SN)	BENT	30.00	30.00
1	FRONT NO PLATE GARNISH (SN)	BROKEN	99.00	99.00
2	FRONT FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH)(SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00

Report Ref No. CS/INC19020499/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR CAMERA (SN)	NOT NECESSARY	500.00	-
			1,235.70	635.70
	LABOUR			
	PANEL BEATING, INCLUSIVE OF THE REPAIR OF GARNISH SUB-ASSY BACK DOOR, OUTSIDE, REAR SPARE TYRE PANEL AND REAR FENDER PANEL, ROOF SIDE OUTER, RH.		3,000.00	1,800.00
	SPRAY PAINTING CHARGE.		2,500.00	1,800.00
	WIRING CHARGE.		100.00	60.00
	TUFF KOTE.		200.00	80.00
	TOWING CHARGE.	NOT NECESSARY	90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	DIAGNOSIS & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	40.00
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE/REFIX EXHAUST PIPE.		150.00	60.00
			7,170.00	4,080.00
	GRAND TOTAL		45,795.68	24,406.95
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			19,500.00

Report Ref No. CS/INC19020499/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.