

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 1405L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	BENT	1,700.00	1,450.00
1	REAR TAILGATE INNER LOCK	DENTED	280.00	280.00
1	REAR TAILGATE "TSI" EMBLEM	NECESSARY	110.00	75.00
1	REAR TAILGATE "BLUE MOTION" EMBLEM	NECESSARY	98.00	98.00
1	REAR TAILGATE RUBBER	CUT	380.00	290.00
10	REAR TAILGATE INNER TRIM CLIPS @\$5.80	NECESSARY	58.00	58.00
1	REAR TAILGATE INNER TRIM	DISTORTED	298.00	298.00
1	REAR TAILGATE REVERSE LAMP LH	MTG CRACKED	280.00	220.00
1	REAR WINDSCREEN MOULDING	NECESSARY	141.60	141.60
2	REAR WINDSCREEN STOPPER @\$15.00	NECESSARY	30.00	30.00
1	REAR TAILGATE LOCK CATCH	DISTORTED	149.80	149.80
1	REAR END PANEL	BENT	280.00	280.00
1	REAR END PANEL UPPER COVERING	CRACKED	180.00	180.00
6	REAR END PANEL UPPER COVERING CLIPS @\$7.50	NECESSARY	45.00	45.00
1	REAR LOCK CATCH TOP COVERING	DENTED	34.00	34.00
1	REAR KICK SENSOR	SHORTED	272.00	272.00
1	REAR BUMPER	BUCKLED	1,050.00	1,050.00
1	REAR BUMPER REINFORCEMENT	BENT	540.00	484.00
1	REAR BUMPER UPPER BRACKET CENTER	CRACKED	217.40	217.40
1	REAR BUMPER UPPR BRACKET LH	CRACKED	116.00	116.00
1	REAR BUMPER SIDE BRACKET LH	SERVICEABLE	55.00	-
12	REAR BUMPER CLIPS @\$5.80	NECESSARY	69.60	69.60
1	REAR BUMPER REVERSE SENSOR	SERVICEABLE	205.00	-
1	REAR BUMPER LOWER COVER	DENTED	350.00	320.00
1	FRONT BUMPER SIDE BRACKET LH	SERVICEABLE	55.00	-
10	FRONT BUMPER CLIPS @\$5.80	NECESSARY	58.00	58.00
1	FRONT BUMPER	BUCKLED	1,280.00	1,152.82
1	FRONT BUMPER INNER GUIDE LH	SERVICEABLE	116.00	-
1	FRONT BUMPER PARKING SENSOR	MISSING	205.00	205.00
1	REAR TAIL LAMP LH	SERVICEABLE	250.00	-
1	REAR SPARE TYRE TRAY	SERVICEABLE	330.00	-

Report Ref No. CS/INC19020507/Ksd3e2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	REAR SPARE TYRE PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT BUMPER LOWER GRILLE (ADDITIONAL)	CRACKED	420.00	310.00
	LESS 10% DISCOUNT		-965.34	-788.42
			8,688.06	7,095.80
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	FRONT NUMBER PLATE (SN)	BENT	40.00	40.00
1	REAR NUMBER PLATE + HOLDER (SN)	BENT	80.00	45.00
			200.00	125.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST FRONT & REAR ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL.		1,000.00	800.00
	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC.		150.00	120.00
	LABOUR CHARGES TO REMOVE & REINSTALL REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS & ETC.		100.00	60.00
	LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEMS & ETC.		80.00	40.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, REAR TAILGATE, REAR END PANEL, REAR BUMPER, REAR TYRE PANEL & ETC.		900.00	800.00
	TO DIAGNOSIS FAULTY CODE & RESET MEMORY.	NOT NECESSARY	150.00	-
	TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR ASSY, FRONT BUMPER PARKING SENSOR & ETC.		100.00	100.00
			2,480.00	1,920.00
	GRAND TOTAL		11,368.06	9,140.80

RECOMMENDED COST OF REPAIRS (CONFIRMED)		9,140.80
---	--	----------

Report Ref No. CS/INC19020507/Ksd3e2





Report Ref No. CS/INC19020507/Ksd3e2

**KONG SENG CHEONG** 

**Licensed Appraiser** 

Tu

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser