

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19020513/KGA3Q2

Date: 14/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLK890Y	Insured Vehicle No :	SHA7642B
Date of Loss: 14/11/2019	Nature of Claim: TP	Claim No: MCT19110346

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK890Y		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRR983783
Reg. Date:	15/01/2017 (Man. Year: 2016)	Chassis No:	JTDKB3FU103541653
Colour:	Metallic Pearl White	Odometer:	183001 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,019.89	5,335.60	6,684.29	55.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,060.00	1,650.00	2,410.00	59.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	16,079.89	6,985.60	9,094.29	56.56
+ GST 7.00/7.00% (\$\$)	1,125.59	488.99	636.60	56.56
Nett Amount (\$\$)	17,205.48	7,474.59	9,730.89	56.56
+ Loss of Use (9.0 x S\$69.95/day) (\$\$)		629.55		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		8,111.59		
Global Sum Settlement (\$\$)		8,100.00		

INSPECTION

Date of Assignment:	19/11/2019	
Date Inspected:	19/11/2019 Inspected At:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK890Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS
2	1		*FRONT NUMBER PLATE GARNISH	Cracked	129.00 FL	*129.00 FL
3	1		*FRONT BUMPER	Buckled	450.80 FL	*450.80 FL
4	10		*FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
5	1		*FRONT BUMPER REINFORCEMENT -UPPER	Repair	711.50 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	107.20 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	107.20 FL	*107.20 FL
8	1		*FRONT BUMPER UPPER GRILLE	Cracked	321.90 FL	*321.90 FL
9	1		*FRONT BUMPER LOWER GRILLE	Serviceable	148.60 FL	*- FL
10	1		*FRONT BUMPER EMBLEM	Necessary	87.10 FL	*87.10 FL
11	1		*FRONT BUMPER SPONGE -UPPER	Serviceable	89.81 FL	*- FL
12	1		*REAR WINDSCREEN MOULDING	Not Necessary	97.70 FL	*- FL
13	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FL	*- FL
14	1		*REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
15	1		*REAR BUMPER	Bent	497.50 FL	*497.50 FL
16	10		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
17	1		*REAR BUMPER SIDE RETAINER LH	Distorted	112.70 FL	*112.70 FL
18	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	398.90 FL	*398.90 FL
20	1		*FRONT BUMPER LOWER GARNISH CENTRE	Bent	582.60 FL	*582.60 FL
21	1		*FRONT BUMPER LOWER GARNISH LH	Mtg Cracked	149.70 FL	*149.70 FL
22	1		*FRONT BUMPER LOWER GARNISH RH	Serviceable	149.70 FL	*- FL
23	1		*FRONT BUMPER TOW COVER	Dented	31.70 FL	*31.70 FL
24	1		*FRONT BUMPER UNDER COVER	Cracked	355.20 FL	*355.20 FL
25	4		*FRONT BUMPER UNDER COVER CLIP	Not Necessary	14.00 FL	*- FL
26	1		*TAIL DOOR	Repair	1,122.50 FL	*- FL
27	1		*TAIL DOOR LOCK	Repair	487.70 FL	*- FL
28	1		*TAIL DOOR EMBLEM	Necessary	61.70 FL	*61.70 FL
29	1		*WORDING PRIUS	Necessary	51.90 FL	*51.90 FL
30	1		*WORDING HYBRID	Necessary	55.47 FL	*55.47 FL
31	1		*TAIL DOOR PLATE GARNISH	Cracked	782.50 FL	*782.50 FL
32	1		*TAIL END PANEL	Repair	596.60 FL	*- FL
33	1		*TAIL END PANEL GARNISH	Serviceable	151.60 FL	*- FL
34	10		*TAIL END PANEL GARNISH CLIP	Not Necessary	35.00 FL	*- FL
35	1		*BOOT WEATHERSTRIP	Serviceable	353.10 FL	*- FL
36	1		*SPARE TYRE WELL PANEL	Repair	793.15 FL	*- FL
37	1		*SPARE TYRE BOARD	Serviceable	566.79 FL	*- FL
38	1		*SPARE TYRE COMPARTMENT SPONGE LH	Serviceable	297.67 FL	*- FL
39	1		*SPARE TYRE COMPARTMENT SPONGE RH	Serviceable	297.67 FL	*- FL
40	1		*TAIL LAMP LH -UPPER	Serviceable	498.75 FL	*- FL
41	1		*TAIL LAMP RH -UPPER	Serviceable	498.75 FL	*- FL
42	1		*TAIL LAMP LH -LOWER	Serviceable	511.60 FL	*- FL
43	1		*TAIL LAMP RH -LOWER	Serviceable	511.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*TAILDOOR GLASS	Serviceable	598.70 FL	*- FL
45	1		*TAILDOOR GLASS SEALANT	Not Necessary	50.00 FL	*- FL
46	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
47	1		*HEADLAMP LH	Mtg Broken	2,531.60 FL	*2,531.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,929.86	7,032.47
- List Item Discount on L Items 25.00/25.00% (\$)	3,909.97	1,696.87
Total Parts (\$)	12,019.89	5,335.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER ,TAILDOOR,END PANEL,SPARE TYRE WELL PANEL ,FRONT BUMPER)	New	1,600.00	600.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER ,TAILDOOR,END PANEL,SPARE TYRE WELL PANEL ,FRONT BUMPER)	New	1,400.00	880.00
3	TO CHECK WIRING	New	50.00	40.00
4	TO REMOVE & REFIT REVERSR SENSOR	New	120.00	50.00
5	TO TUFF COAT	New	200.00	0.00
6	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	60.00
7	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	0.00
8	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	0.00
9	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	20.00
10	TO REMOVE & REFIT RADIATOR GLASS TO ASSIT WORK LOAD	New	120.00	0.00
11	TOWING	New	60.00	0.00
Gross Labour Cost (\$\$)			4,060.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >