

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/III19020595/QYD3S2**Date:** 27/02/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	SGU3587K	<b>Insured Vehicle No :</b>	SHB4383M
Date of Loss:	15/11/2019	Nature of Claim:	TP
		Claim No:	MCT19110362

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGU3587K</b>	Engine No:	R18A1731930
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61028462
Reg. Date:	11/05/2007 (Man. Year: 2007)	Odometer:	229066 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,671.36	3,400.80	3,270.56	49.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	2,500.00	1,200.00	32.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,371.36</b>	<b>5,900.80</b>	<b>4,470.56</b>	<b>43.10</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,750.00</b>		
<b>Nett Amount (S\$)</b>	<b>10,371.36</b>	<b>4,750.00</b>	<b>5,621.36</b>	<b>54.20</b>

INSPECTION

Date of Assignment:	19/11/2019	Car Pro Auto (HQ)
Date Inspected:	20/11/2019 Inspected At:	Blk 6 Woodlands Road Unit 399J Yew Tee Ind Estate
Estimated Period of Repair:	6.0 days	Singapore 678008

**Adjuster:** OI SUN PIN**Manager:** YVONNE WONG YIN CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2020)
<b>Parts:</b> M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGU3587K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	595.00 FL	*595.00 FL
2	1		*REAR BUMPER SIDE RETAINER	O/s Broken	28.00 FL	*14.00 FL
3	1		*REAR BUMPER BRACKET	O/s Broken	44.00 FL	*22.00 FL
4	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*30.00 FL
5	2		*TAIL LAMP	Scratched	720.00 FL	*720.00 FL
6	2		*SETS TAIL LAMP CLIPS	Necessary	42.00 FL	*42.00 FL
7	1		*TAIL GATE	Dented	1,026.00 FL	*902.00 FL
8	1		*TAIL GATE LOCK	Serviceable	110.00 FL	*- FL
9	1		*TAIL GATE LOCK STRIKER	Serviceable	35.00 FL	*- FL
10	1		*TAIL GATE WIPER ARM	Serviceable	60.00 FL	*- FL
11	1		*TAIL GATE WIPER BLADE	Serviceable	55.00 FL	*- FL
12	1		*TAIL GATE WIPER MOTOR	Serviceable	288.00 FL	*- FL
13	1		*TAIL GATE WEATHERSTRIP	Broken	120.00 FL	*120.00 FL
14	1		*TAIL GATE HONDA LOGO	Necessary	25.00 FL	*25.00 FL
15	1		*TAIL GATE STREAM LOGO	Necessary	35.00 FL	*35.00 FL
16	1		*TAIL GATE SHOCK ABSORBER LH	Serviceable	120.00 FL	*- FL
17	1		*TAIL GATE STOPPER	Serviceable	10.20 FL	*- FL
18	1		*TAIL GATE INNER TRIM LH	Crushed	160.00 FL	*160.00 FL
19	1		*TAIL GATE LOWER PULL HANDLE	Serviceable	55.00 FL	*- FL
20	1		*TAIL GATE CENTRE GARNISH	Serviceable	80.00 FL	*- FL
21	1		*REAR END PANEL	Dented	308.00 FL	*308.00 FL
22	1		*REAR END PANEL TOP GARNISH	Crushed	118.00 FL	*118.00 FL
23	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FL	*20.00 FL
24	1		*REAR WINDSCREEN	Serviceable	1,025.00 FL	*- FL
25	2		*REAR WINDSCREEN GLASS MOULDING	Necessary	55.00 FL	*55.00 FL
26	2		*REAR WINDSCREEN INNER SEAL	Necessary	30.00 FL	*30.00 FL
27	1		*REAR CHASSIS FRAME	Repair	350.00 FL	*- FL
28	1		*REAR FENDER	Serviceable	795.00 FL	*- FL
29	1		*REAR FENDER INNER TRIM LH	Crushed	440.00 FL	*292.00 FL
30	1		*SET REAR FENDER INNER TRIM CLIPS LH	Necessary	28.00 FL	*28.00 FL
31	1		*EXHAUST ASSY	Bent	542.00 FL	*542.00 FL
32	1		*EXHAUST MOUNTING	Necessary	93.00 FL	*93.00 FL
33	1		*TOWING COVER	Serviceable	95.00 FL	*- FL
34	2		*CARPLATE LAMPS	Serviceable	109.50 FL	*- FL
35	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
36	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*40.00 FS
37	4		*REVERSE SENSOR	Not Necessary	380.00 FS	*- FS
38	1		*NUMBER PLATE W CASING	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>8,201.70</b>	<b>4,231.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	1,530.34	830.20
<b>Total Parts (S\$)</b>	<b>6,671.36</b>	<b>3,400.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAYING OF AFFECTED AREAS, BOOTLID / BUMPER / END PANEL / SPARE TYRE PANEL / FENDERS.	New	1,300.00	1,000.00
2	CARRY OUT BODY CAVITY PRESERVATION.	New	120.00	0.00
3	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING AND REPOSITIONING REPLACEMENT PARTS & PANEL BEAT, REAR FENDER LH/RH, BOOTLID, END PANEL ETC. SPARE TYRE TANK PANEL.	New	1,400.00	1,200.00
4	CHECK WIRING.	New	80.00	30.00
5	REMOVE & REINSTALL REAR WINDSCREEN.	New	150.00	120.00
6	REMOVE & REFIX BOOTLID COMPONENTS.	New	80.00	60.00
7	REMOVE & REINSTALL REVERSE SENSOR.	New	100.00	0.00
8	REMOVE & REINSTALL REAR BOOT UPHOLSTERY.	New	100.00	0.00
9	REMOVE & REFIX EXHAUST.	New	100.00	50.00
10	REMOVE & REINSTALL UPHOLSTERY.	New	120.00	0.00
11	REMOVE & REFIX REAR SEATS AND CUSHION.	New	150.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,700.00</b>	<b>2,500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >