

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19020625/AEA3Q2

Date: 17/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900002666

Claimant
Vehicle No : SKR2154B **Insured Vehicle No :** SMH706B

Date of Loss: 18/11/2019 Nature of Claim: TP Claim No: 0285476469SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR2154B**

Make & Model: CITROEN GRAND C4 PICASSO, 1.6 D EHD ETG6 XENON (A) Engine No: 10JBEX3037570

Reg. Date: 26/01/2015 (Man. Year: 2014) Chassis No: VF73A9HC8EJ700367

Colour: Blue Odometer: 124944 km

Engine Capacity: 1560 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/50R17 Rear Tyre Size: 215/50R17

Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm

Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,647.23	14,264.66	28,382.57	66.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,261.00	3,420.00	4,841.00	58.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,908.23	17,684.66	33,223.57	65.26
Approved Total (Overridden) (S\$)		8,500.00		
Nett Amount (S\$)	50,908.23	8,500.00	42,408.23	83.30
+ Loss of Use (14.0 x S\$83.57/day) (S\$)		1,169.98		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		9,698.98		

INSPECTION

Date of Assignment: 21/11/2019

Date Inspected: 21/11/2019 Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22
Autobay
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGAT	Repair	2,875.30 FL	*- FL
2	1		*TAILGAT OUTER	Deformed	975.60 FL	*975.60 FL
3	1		*TAILGAT OUTER CHROME GARNISH	Cracked	326.70 FL	*326.70 FL
4	1		*TAILGAT LOGO	Necessary	98.70 FL	*98.70 FL
5	1		*TAILGAT CITROEN EMBLEM	Necessary	96.80 FL	*96.80 FL
6	1		*TAILGAT C4 EMBLEM	Necessary	87.20 FL	*87.20 FL
7	1		*TAILGAT EHDI EMBLEM	Necessary	95.60 FL	*95.60 FL
8	1		*TAILGAT PICASSO EMBLEM	Necessary	98.60 FL	*98.60 FL
9	1		*TAILGAT CC EMBLEM	Necessary	55.80 FL	*55.80 FL
10	2		*TAILGATE LAMP	Not Necessary	1,251.20 FL	*- FL
11	2		*TAILGATE LAMP INNER SEALER	Not Necessary	77.40 FL	*- FL
12	2		*TAILGAT STOPPER	Not Necessary	99.60 FL	*- FL
13	1		*TAILGATE INNER LOCK	Not Necessary	325.00 FL	*- FL
14	1		*TAILGATE AUTOLOCK ACTUATOR	Not Necessary	489.00 FL	*- FL
15	1		*TAILGAT LOCK CATCH	Not Necessary	121.50 FL	*- FL
16	1		*TAILGAT WEATHERSTRIP	Not Necessary	275.60 FL	*- FL
17	2		*TAILGAT HINGES	Not Necessary	225.00 FL	*- FL
18	2		*TAILGAT ABSORBERS	Not Necessary	464.80 FL	*- FL
19	1		*TAILGAT INNER TRIM	Not Necessary	676.50 FL	*- FL
20	2		*TAILGAT SIDE INNERTRMS	Not Necessary	560.20 FL	*- FL
21	2		*TAILGAT SIDE INNERTRMS COVERS	Not Necessary	381.20 FL	*- FL
22	1		*TAILGATE CENTRE INNERTRIMS COVER	Not Necessary	212.50 FL	*- FL
23	1		*TAILGAT OPENER SWITCH	Not Necessary	328.20 FL	*- FL
24	1		*TAILGAT OPEN /CLOSE SENSOR	Not Necessary	297.50 FL	*- FL
25	2		*REAR NUMBER PLATE LAMPS	Not Necessary	117.80 FL	*- FL
26	1		*REAR WINDSCREEN	Not Necessary	875.00 FL	*- FL
27	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FL	*- FL
28	1		*REAR BUMPER	Distorted	1,250.70 FL	*1,250.70 FL
29	2		*REAR BUMPER SIDE RETAINER	Necessary	361.20 FL	*361.20 FL
30	2		*REAR BUMPER ATTACHMENT RETAINER	Necessary	261.20 FL	*261.20 FL
31	1		*REAR BUMPER REINFORCEMENT	Distorted	653.60 FL	*653.60 FL
32	1		*REAR BUMPER CENTRE BRACKET	Distorted	365.90 FL	*365.90 FL
33	1		*REAR BUMPER LOWER	Distorted	547.60 FL	*547.60 FL
34	1		*REAR BUMPER REFLECTOR	O/S Smashed	1,210.80 FL	*302.70 FL
35	4		*REAR BUMPER REVERSE SRNSORS	Damaged	992.00 FL	*992.00 FL
36	2		*REAR BUMPER SENSOR HOLDERS	Necessary	76.00 FL	*76.00 FL
37	1		*REAR BUMPER SENSOR HARDNESS	Not Necessary	625.30 FL	*- FL
38	1		*END PANEL	Repair	789.60 FL	*- FL
39	1		*END PANEL TOP GARNISH	Not Necessary	285.70 FL	*- FL
40	1		*REAR KEY ANTENNA SENSOR	Not Necessary	197.60 FL	*- FL
41	1		*SPARE TYRE FLOOR PANEL	Not Necessary	897.30 FL	*- FL
42	2		*REAR FENDER	Not Necessary	3,707.40 FL	*- FL
43	2		*REAR FENDER GARNISH	Not Necessary	793.00 FL	*- FL
44	2		*REAR FENDER INNER TRIM	Not Necessary	851.40 FL	*- FL
45	2		*REAR FENDER INNER COWLING	Not Necessary	375.80 FL	*- FL
46	1		*REAR FENDER AIR DUCT LH	Not Necessary	125.90 FL	*- FL
47	1		*REAR FENDER AIR DUCT COVER LH	Not Necessary	110.60 FL	*- FL
48	1		*REAR SILENCER BOX	Not Necessary	935.60 FL	*- FL
49	2		*REAR EXHAUST MOUNTINGS	Not Necessary	170.00 FL	*- FL
50	1		*REAR EXHAUST GASKET	Not Necessary	65.20 FL	*- FL
51	1		*SPARE TYRE CARRIER	Damaged	398.60 FL	*398.60 FL
52	1		*FRONT BONNET	Distorted	2,850.10 FL	*2,850.10 FL
53	1		*FRONT BONNET INSULATOR	Not Necessary	385.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	2		*FRONT BONNET STOPPER	Not Necessary	77.20 FL	*- FL
55	1		*FRONT SUPPORT PANEL	Distorted	650.80 FL	*650.80 FL
56	1		*FRONT SUPPORT PANEL TOP GARNISH	Distorted	297.80 FL	*297.80 FL
57	2		*FRONT HORNS	Not Necessary	120.00 FL	*- FL
58	1		*FRONT RADIATOR	Not Necessary	980.20 FL	*- FL
59	1		*FRONT RADIATOR TOP HOSE	Not Necessary	125.60 FL	*- FL
60	1		*FRONT RADIATOR BOTTOM HOSE	Not Necessary	126.30 FL	*- FL
61	1		*FRONT RADIATOR FAN COWLING	Not Necessary	198.60 FL	*- FL
62	1		*FRONT RADIATOR FAN MOTOR	Not Necessary	385.40 FL	*- FL
63	1		*FRONT RADIATOR SPARE TANK	Not Necessary	156.30 FL	*- FL
64	1		*FRONT CONDENSER	Not Necessary	1,087.50 FL	*- FL
65	1		*FRONT CONDENSER AIR CON PIPE	Not Necessary	392.80 FL	*- FL
66	1		*FRONT WASHER TANK	Not Necessary	154.70 FL	*- FL
67	1		*FRONT HEADLAMPS	O/S Cracked	1,791.40 FL	*895.70 FL
68	2		*FRONT HEADLAMPS WASHER NOZZLE	Not Necessary	99.60 FL	*- FL
69	2		*FRONT HEADLAMPS WASHER MOTORS	Not Necessary	513.40 FL	*- FL
70	2		*FRONT SIGNAL LAMPS	Not Necessary	945.00 FL	*- FL
71	2		*FRONT SIGNAL LAMPS CHROME GARNISH	Not Necessary	491.20 FL	*- FL
72	1		*FRONT BUMPER	Distorted	2,180.50 FL	*2,180.50 FL
73	1		*FRONT BUMPER LOWER COVER	Not Necessary	326.50 FL	*- FL
74	2		*FRONT BUMPER SIDE RETAINERS	Necessary	361.20 FL	*361.20 FL
75	1		*FRONT BUMPER FRONT REINFORCEMENT	Distorted	450.60 FL	*450.60 FL
76	1		*FRONT BUMPER GRILLE	Cracked	198.70 FL	*198.70 FL
77	1		*FRONT BUMPER GRILLE LOGO	Necessary	65.30 FL	*65.30 FL
78	1		*FRONT BUMPER LOWER GRILLE	Deformed	276.80 FL	*276.80 FL
79	1		*FRONT LOWER GRILLE CHROME MOLDING	Cracked	285.60 FL	*285.60 FL
80	1		*FRONT BUMPER TOWING COVER	Distorted	69.80 FL	*69.80 FL
81	2		*FRONT BUMPER FOGLAMPS	Not Necessary	631.20 FL	*- FL
82	2		*FRONT BUMPER FOGLAMPS COVER	Not Necessary	313.60 FL	*- FL
83	2		*FRONT FENDERS	Repair	1,371.40 FL	*- FL
84	2		*FRONT FENDERS INNER COWLING	Not Necessary	317.40 FL	*- FL
85	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
86	2		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
87	2		*SET REAR FENDER INNER TRIMS CLIPS	Not Necessary	60.00 FS	*- FS
88	2		*END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
89	2		*SET SPARE TYRE FLOOR INSULATOR PADS	Not Necessary	200.00 FS	*- FS
90	1		*SET WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
91	2		*SET SPARE TYRE FLOOR INSULATOR PADS	Not Necessary	200.00 FS	*- FS
92	1		*SET FRONT RADIATOR COOLANT	Necessary	40.00 FS	*40.00 FS
93	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
94	1		*SET TAILGATE INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
95	2		*SET FRONT FENDER INNER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
96	1		*SET FRONT BUMPER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
97	1		*SET REAR NUMBER PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
98	1		*SET END PANEL TOP TRIM CLIPS	Not Necessary	30.00 FS	*- FS
99	1		*SET BONNET INSULATOR CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	47,274.70	15,827.40
- List Item Discount on L Items 10.00/10.00% (\$)	4,627.47	1,562.74
Total Parts (\$)	42,647.23	14,264.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS	New	3,200.00	1,600.00
2	TO RESPRAY AFFECTED AREAS	New	3,000.00	1,400.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	60.00
4	TO REMOVE/REFIT /REPLACE REAR TAILGATE MECHANISM	New	300.00	0.00
5	TO REMOVE/REFIT REAR INTERIOR UPHOLSTERY	New	200.00	60.00
6	TO RMEOVE/REFIT REAR SENSOR AND DISTANCE SETTLING	New	150.00	60.00
7	TO REMOVE/REFIT REAR INTERIOR UPHOLSTERY	New	150.00	60.00
8	TO CONDUCT WIRING CHECK ON FRONT HEADLAMPS	New	120.00	30.00
9	TO CONDUCT WIRING CHECK ON REAR TAILAMPS	New	120.00	30.00
10	TO TOP UP AIR CON GAS FOR CONDENSER REPLACEMENT	New	120.00	120.00
11	TO REMOVE/REFIT REAR WINDSCREEN FOR FENDER REPLACEMENT	New	150.00	0.00
12	TO CONDUCT WATER LEAKAGE TEST	New	151.00	0.00
13	TO REMOVE/REPLACE REAR SILENCER BOX	New	200.00	0.00
14	LABOUR TO APPLY SEALANT ON THE AFFECTED AREA	New	200.00	0.00
Gross Labour Cost (\$\$)			8,261.00	3,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >