Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC4/III19020626/QGA3Q2 Our File No:

Date: 17/11/2020

Odometer:

REFERENCE

India International Insurance Handling Insurer:

Pte Ltd

Policy No: D18MPC0002090 01

Claimant

SMB140P

SLR5395R

Vehicle No:

No:

Claim

Date of Loss:

17/11/2019

Nature of Claim: TP

MPC2019D0001472 No:

574026 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMB140P Reg No:

MERCEDES-BENZ CITARO O530, 6.4 D (A) Make & Model: Engine No: 90292600907870 Reg. Date: 11/03/2011 (Man. Year: 2010) Chassis No: WEB62808323120695

Insured Vehicle

Colour: Multi-colour 6374 cc

Engine Capacity: Market Value/New Car

N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

275/70R22.5 Front Tyre Size: 275/70R22.5 Rear Tyre Size: Front Left Side: Firenza 5 mm Rear Left Side: Firenza 5 mm Front Right Side: Firenza 5 mm Rear Right Side: Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,258.88	5,837.20	4,421.68	43.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,168.00	2,468.00	700.00	22.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,426.88	8,305.20	5,121.68	38.14
Approved Total (Overridden) (S\$)		7,150.00		
Nett Amount (S\$)	13,426.88	7,150.00	6,276.88	46.75
+ Loss of Use (5.5 x S\$250.00/day) (S\$)		1,375.00		
+ Doc/Se	earch Fee (S\$)	7.00		

Nett Liability (S\$)

INSPECTION

Date of Assignment: 20/11/2019

Date Inspected: 20/11/2019 Inspected At: SMRT Automotive Services Pte Ltd

Global Sum Settlement (S\$)

(Woodlands)

8,532.00

8.500.00

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: OI SUN PIN Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 23 Sep 2020)

Parts: N/A MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMB140P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Total Parts (S\$) 10,258.88

Repairer's

Amount

5,837.20

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts No. Qtv Part No. Particulars

140.	Qty	i ait ito.	i diticulais	Contaition	itepairer 3	Amount
1	2		*FASTENER ,FRT BUMPER ,FOR MB CITARO BUS	Serviceable	38.70 F	*- FL
2	1		*LAMP ,BLINKER ,FRONT RIGHT ,FOR MB OC500LE	Cracked	155.30 F	*155.30 FL
3	1		*BUMPER FRONT RH ,FOR MB CITARO O530	Cracked	1,754.79 F	*1,754.79 FL
4	1		*BUMPER ,FRONT ,CENTRE ,FOR MB CITARO 0530	Cracked	1,663.80 F	*1,663.80 FL
5	1		*FLAP ,FRONT ,CENTRE ,FOR MB CITARO O530	Cracked	1,513.05 F	*1,513.05 FL
6	1		*HEADLAMP FOR MERCEDES OC500 LE,RIGHT	Cracked	1,276.50 F	*1,276.50 FL
7	2		*WIPER ARM COVER	Cracked	39.00 F	*39.00 FL
8	1		*HEADLAMP FOR MERCEDES OC500 LE,LEFT	Serviceable	1,276.50 F	*- FL
9	2		*BRACKET :(15) ,FOR MB CITARO BUS	Serviceable	9.12 F	*- FL
10	2		*LOCK: (20) ,FOR MB CITARO BUS	Serviceable	87.60 F	*- FL
11	1		*BRACKET: (40) ,FOR MB CITARO BUS	Repair	439.74 F	*-FL
12	2		*BRACKET: (120),FOR MB CITARO BUS	Serviceable	66.00 F	*-FL
13	2		*HINGE:(35) ,FOR MB CITARO BUS	Repair	96.00 F	*-FL
14	1		*BUMPER :FRONT ,LH FOR MB CITARO 0530	Repair	1,767.78 F	*- FL
15	1		*STICKER SMRT	Necessary	75.00 FS	*75.00 FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.					
			S	ub Total (S\$)	10,258.88	6,477.44
	- List Item Discount on L Items 0.00/10.00% (S\$)					640.24

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	2,120.00	1,590.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAI ITEMS	New	1,048.00	878.00
	Gross Labour Cost (S\$)		3,168.00	2,468.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >