

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

**Our File No:** CC3/AIG19020628/T1QD3E2

**Date:** 15/04/2020

#### REFERENCE

Insured/Claimant: SIN FAI LAM STEPHEN RALPHY YOON NIAN Policy No: 2100482526-03

Date of Loss: 14/11/2019

Nature of Claim: OD

Claim No: 8091231440SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLG186T</b>	Engine No:	CYG010911
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Chassis No:	WAUZZZ4G8GN115383
Reg. Date:	19/09/2016 (Man. Year: 2015)	Odometer:	33667 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$112,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	15,103.00	12,429.00	2,674.00	17.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,252.00	3,022.00	3,230.00	51.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>21,355.00</b>	<b>15,451.00</b>	<b>5,904.00</b>	<b>27.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,494.85	1,081.57	413.28	27.65
<b>Nett Amount (S\$)</b>	<b>22,849.85</b>	<b>16,532.57</b>	<b>6,317.28</b>	<b>27.65</b>

#### INSPECTION

Date of Assignment: 21/11/2019

Date Inspected: 20/11/2019 Inspected At:

281 ALEXANDRA ROAD

Repairer : Premium Automobiles Pte Ltd

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)  
(EXCLUDE CHECK ITEMS S\$680.00 NETT)

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,443.00 FS	*2,443.00 FS
2	1		*FRONT BUMPER FIXING PARTS	* Check	45.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	319.00 FS	*- FS
4	1		*FRONT BUMPER COVER	Not Necessary	46.00 FS	*- FS
5	1		*FRONT WHEEL SPOILER - RH	Not Necessary	242.00 FS	*- FS
6	1		*STONE CHIP GUARD	Not Necessary	66.00 FS	*- FS
7	1		*ADHESIVE TAPE	Not Necessary	50.00 FS	*- FS
8	1		*FRONT FENDER - RH	Bent	1,269.00 FS	*1,269.00 FS
9	1		*FRONT FENDER ATTACHMENT PARTS	* Check	92.00 FS	*- FS
10	1		*FRONT FENDER STONE GUARD FILM - RH	Necessary	110.00 FS	*110.00 FS
11	1		*FRONT FENDER BRACE - RH	* Check	75.00 FS	*- FS
12	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	256.00 FS	*- FS
13	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
14	1		*HEADLIGHT MOUNTING - RH	* Check	107.00 FS	*- FS
15	1		*FRONT BUMPER BRACE - RH	* Check	27.00 FS	*- FS
16	1		*FRONT BUMPER GUIDE PIECE - RH	* Check	34.00 FS	*- FS
17	1		*LED HEADLIGHT - RH	Cut	8,607.00 FS	*8,607.00 FS
18	1		*LIFT CYLINDER - RH	Not Necessary	216.00 FS	*- FS
19	1		*FRONT ALUMINIUM RIM - RH	Not Necessary	733.00 FS	*- FS
20	1		*SUNDRIES	* Check	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 15,103.00 12,429.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,500.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,022.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >