Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19020644/AHB3Q2

Date: 14/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1900057756 Policy No: Claimant SJY4681H Insured Vehicle No: SMJ6032L Vehicle No:

Date of Loss: Nature of Claim: ΤP 18/11/2019 Claim No: 8922189550SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SJY4681H Reg No:

Make & Model: VOLVO S80, 2.5T (A) Engine No: B5254T4458074 Chassis No: Reg. Date: 03/09/2010 (Man. Year: 2010) YV1AS6050A1131859

Colour: Odometer: 239731 km Black

Engine Capacity: 2521 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm Front Right Side: Rear Right Side: Nexen 6 mm Nexen 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|--------------------|------------|------------|--------|
| Parts | 16,648.51 | 5,531.01 | 11,117.50 | 66.78 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,780.00 | 1,260.00 | 1,520.00 | 54.68 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 19,428.51 | 6,791.01 | 12,637.50 | 65.05 |
| Approved Total (Overridden) (S\$) | | 5,400.00 | | |
| (S\$) | 19,428.51 | 5,400.00 | 14,028.51 | 72.21 |
| + GST 7.00/7.00% (S\$) | 1,360.00 | 378.00 | 982.00 | 72.21 |
| Nett Amount (S\$) | 20,788.51 | 5,778.00 | 15,010.51 | 72.21 |
| + Loss of Use (7.0 x S\$1 | 20.00/day) (S\$) | 840.00 | | |
| + Doc/S | 7.45 | | | |
| Ne | tt Liability (S\$) | 6,625.45 | | |
| Global Sum S | Settlement (S\$) | 6,600.00 | | |

INSPECTION

Date of Assignment: 20/11/2019

20/11/2019 Inspected At: MG Solution Pte Ltd (HQ) Date Inspected:

23 Kaki Bukit Avenue 4 #02-03B,

VICOM Inspection Centre

Singapore 415933

Estimated Period of Repair: 5.0 days Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|--|---|----------|-----------------------------------|--------------------|-------------|--------------|--|
| 1 | 1 | | *FRONT BUMPER | Deformed | 1,880.60 FL | *1,880.60 FL | |
| 2 | 1 | | *FRONT BUMPER SIDE RETAINER | N/S Necessary | 246.00 FL | *123.00 FL | |
| 3 | 1 | | *HEADLAMP LH | Cut | 2,155.30 FL | *2,155.30 FL | |
| 4 | 1 | | *FRONT FENDER | Dented | 820.00 FL | *820.00 FL | |
| 5 | 1 | | *FRONT FENDER INNER COWLING | Not Necessary | 180.00 FL | *- FL | |
| 6 | 1 | | *FRONT LOWER ARM LH | Not Necessary | 693.00 FL | *- FL | |
| 7 | 1 | | *FRONT KNUCKLE LH | Not Necessary | 647.00 FL | *- FL | |
| 8 | 1 | | *FRONT SHOCK ABSORBER LH | Not Necessary | 756.00 FL | *- FL | |
| 9 | 1 | | *FRONT WHEEL HUP LH | Not Necessary | 577.00 FL | *- FL | |
| 10 | 1 | | *FRONT WHEEL HUP BEARING LH | Not Necessary | 280.00 FL | *- FL | |
| 11 | 1 | | *FRONT LINKAGE LH | Not Necessary | 155.00 FL | *- FL | |
| 12 | 1 | | *FRONT DRIVESHAFT LH | Not Necessary | 1,870.00 FL | *- FL | |
| 13 | 1 | | *FRONT STEERING RACK AND PINION | Not Necessary | 5,794.00 FL | *- FL | |
| 14 | 1 | | *SET FRONT BUMPER CLIPS | Necessary | 20.00 FS | *20.00 FS | |
| 15 | 1 | | *SET FRONT FENDER COWLING CLIP RH | Necessary | 30.00 FS | *30.00 FS | |
| 16 | 1 | | *REAR WHEEL TYRE LH | Not Necessary | 550.00 FS | *- FS | |
| 17 | 1 | | *SET REAR WHEEL RIM | Cut | 1,600.00 FS | *1,000.00 FS | |
| F=Franchise part. S=SpcNett. L=ListItemDisc. | | | | | | | |
| | | | | Sub Total (S\$) | 18,253.90 | 6,028.90 | |
| | | | - List Item Discount on L Items | 10.00/10.00% (S\$) | 1,605.39 | 497.89 | |
| | | | | Total Parts (S\$) | 16,648.51 | 5,531.01 | |
| | Report was unsubmitted during this print-out. | | | | | | |

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--|-----------------------|------------|----------|
| Lab | our Items | | | |
| 1 | PANEL BEATING ,REMOVAL AND REPLACING PARTS | New | 1,000.00 | 500.00 |
| 2 | TO SPRAY PAINT AFFECTED AREA | New | 1,000.00 | 650.00 |
| 3 | TUFF COAT | New | 250.00 | 0.00 |
| 4 | WIRING CHECK | New | 80.00 | 30.00 |
| 5 | REMOVE AND REFIX FRONT UNDERCARRIAGE | New | 350.00 | 0.00 |
| 6 | FOUR WHEEL ALIGNMENT | New | 100.00 | 80.00 |
| | Gross Lal | oour Cost (S\$) | 2,780.00 | 1,260.00 |
| | Report was unsubmitted d | uring this print-out. | | |

< END OF ESTIMATES >