

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020652/APA3Q2

Date: 14/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800097539

Claimant
Vehicle No : GBD2185S **Insured Vehicle No :** SMD3481A

Date of Loss: 09/11/2019 Nature of Claim: TP Claim No: 5566112786SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD2185S		
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Engine No:	1KD2378211
Reg. Date:	31/07/2014 (Man. Year: 2014)	Chassis No:	KDY2318015924
Colour:	Blue	Odometer:	138040 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13
Front Left Side:	OHTSU 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,030.17	2,577.40	7,452.77	74.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	1,190.00	2,680.00	69.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,900.17	3,767.40	10,132.77	72.90
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	13,900.17	3,000.00	10,900.17	78.42
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,356.45		

INSPECTION

Date of Assignment: 20/11/2019

Date Inspected: 20/11/2019 Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)
13 Kaki Bukit Road 4, #03-29/30
Bartley Biz Centre
Singapore 417807

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Dented	1,837.50 FL	*1,265.00 FL
2	1		*REAR BOOT COVER SIDE BRACKET L LOCK	Not Necessary	207.90 FL	*- FL
3	1		*REAR BOOT COVER SIDE BRACKET RUBBER	Not Necessary	101.00 FL	*- FL
4	1		*REAR BOOT DYNA EMBLEM	Necessary	50.00 FL	*50.00 FL
5	1		*REAR BOOT MEMBER	Dented	410.00 FL	*410.00 FL
6	2		*REAR BOOT REFLECTOR LH & RH	Cracked	190.00 FL	*190.00 FL
7	1		*REAR NUMBER PLATE PANEL	Bent	315.00 FL	*175.00 FL
8	1		*REAR NUMBER PLATE LAMP	Not Necessary	295.00 FL	*- FL
9	2		*REAR LAMP LH & RH	Cracked	550.00 FL	*550.00 FL
10	1		*REAR END PANEL (LOWER MEMBER)	Repeated	1,341.90 FL	*- FL
11	2		*REAR LOWER MEMBER BRACKETE	Not Necessary	290.20 FL	*- FL
12	1		*REAR CHASSIS FRAME (DECK SUPPORT)	Not Necessary	1,659.00 FL	*- FL
13	1		*REAR FLOOR DECKING	Repair	2,079.00 FL	*- FL
14	2		*REAR CHASSIS FRAME U BOLTS	Not Necessary	367.50 FL	*- FL
15	1		*REAR EXHAUST PIPE	Not Necessary	581.00 FL	*- FL
16	2		*REAR EXHAUST PIPE BRACKET	Not Necessary	126.00 FL	*- FL
17	1		*REAR TOW HOOK	Not Necessary	80.20 FL	*- FL
18	1		*REAR BOOT STEP BRACKET	Bent	85.00 FL	*85.00 FL
19	1		*REAR BOOT STEP BRACKET STAINLESS STEEL	Not Necessary	787.50 FL	*- FL
20	2		*REAR BOOT HINGES LH & RH	Not Necessary	160.00 FL	*- FL
21	2		*REAR BOOT STOPPER PILLAR LH & RH	Repair	420.00 FL	*- FL
22	2		*REAR BOOT STOPPER LH & RH	Not Necessary	45.00 FL	*- FL
23	2		*TAILLAMP PANEL LH AND RH	Bent	338.20 FL	*338.20 FL
24	1		*70KM/H STICKER	Necessary	80.00 FS	*15.00 FS
25	1		*13 PAX STICKER	Necessary	70.00 FS	*15.00 FS
26	1		*SET REVERSE SENSOR	Not Necessary	262.50 FS	*- FS
27	1		*REAR BOOT COMPANY STICKER	Necessary	300.00 FS	*200.00 FS
28	1		*REAR CAR PLATE WITH PLATE	Cracked	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,109.40	3,343.20
- List Item Discount on L Items 25.00/25.00% (\$)	3,079.23	765.80
Total Parts (\$)	10,030.17	2,577.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE PARTS	New	1,600.00	600.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	500.00
3	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS	New	250.00	30.00
4	TO CARRY OUT CHASSIS ALIGNMENT	New	350.00	0.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	270.00	60.00
6	TO REMOVE AND REPLACE REAR EXHAUST PIPE & RE-ALIGN	New	200.00	0.00
Gross Labour Cost (S\$)			3,870.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >