Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020654/QBA3Q2

**Date:** 23/06/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900121734

Claimant Vehicle No: SLG3981U Insured Vehicle No: SKW5752D

Date of Loss: 19/11/2019 Nature of Claim: TP Claim No: 8687066552SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLG3981U

 Make & Model:
 HONDA VEZEL, 1.5 HYBRID (A)
 Engine No:
 LEB5908702

 Reg. Date:
 29/09/2016 (Man. Year: 2016)
 Chassis No:
 RU31208692

 Colour:
 Blue
 Odometer:
 177786 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Giti 5 mm Rear Left Side: Giti 5 mm
Front Right Side: Giti 5 mm Rear Right Side: Giti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,068.00	2,478.24	589.76	19.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,000.00	880.00	46.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,948.00	3,478.24	1,469.76	29.70
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	4,948.00	2,800.00	2,148.00	43.41
+ GST 7.00/7.00% (S\$)	346.36	196.00	150.36	43.41
Nett Amount (S\$)	5,294.36	2,996.00	2,298.36	43.41
+ Loss of Use (6.0 x S\$5	50.00/day) (S\$)	300.00		
+ Doc/Se	2.00			
Net	t Liability (S\$)	3,298.00		
Global Sum S	3,200.00			

**INSPECTION** 

Date of Assignment: 21/11/2019

Date Inspected: 21/11/2019 Inspected At: Lion City Rentals Pte Ltd

1090 LOWER DELTA ROAD #05-12

Singapore 169201

Estimated Period of Repair: 4.0 days

Adjuster Report Page 2 of 4

Adjuster: OI SUN PIN Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	955.00 FL	*850.00 FL
2	1		*F/R FENDER WHEEL ARCH MOULDING	Scratched	300.00 FL	*192.60 FL
3	1		*F/R HEADLAMP ASSY (LED)	Crumpled	2,100.00 FL	*1,820.20 FL
4	1		*F/R HEADLAMP LOWER BRACKET	Cracked	40.00 FL	*40.00 FL
5	1		*F/R HEADLAMP TOP BRACKET	Cracked	180.00 FL	*60.00 FL
6	1		*RH BUMPER RETAINER	Necessary	60.00 FL	*60.00 FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
8	1		*SET F/R FENDER WHEEL ARC MOULDING CLIPS	Necessary	80.00 FS	*30.00 FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.			
			S	ub Total (S\$)	3,795.00	3,082.80
			- List Item Discount on L Items 20.00	)/20.00% (S\$)	727.00	604.56
			То	tal Parts (S\$)	3,068.00	2,478.24
			Report was unsubmitted during this prin	nt-out		

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PART ,REPAIR FENDER FR	New	900.00	500.00
2	TO RESPRAY FRONT BUMPER ,F/R FENDER AND F/R FENDER WHEEL ARC MOULDING	New	900.00	500.00
3	TO CHECK AND FOCUS BOTH HEADLAMPS	New	80.00	0.00
	Gross Labour Cost (S\$)		1,880.00	1,000.00
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >