

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19020655/FDB3Q2

**Date:** 16/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994015

**Claimant**  
**Vehicle No :** SHC3557E **Insured Vehicle No :** SGV899A

Date of Loss: 20/11/2019 Nature of Claim: TP Claim No: 2027844952SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                       |             |                   |
|-----------------------------|---------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SHC3557E</b>                       | Engine No:  | G4LEKU296333      |
| Make & Model:               | HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) | Chassis No: | KMHC851CVKU164605 |
| Reg. Date:                  | 10/07/2019 (Man. Year: 2019)          | Odometer:   | 54838 km          |
| Colour:                     | Blue                                  |             |                   |
| Engine Capacity:            | 1580 cc                               |             |                   |
| Market Value/New Car Price: | N/A                                   |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b>     |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/65 R15    | Rear Tyre Size:  | 195/65 R15    |
| Front Left Side:  | Michelin 7 mm | Rear Left Side:  | Michelin 7 mm |
| Front Right Side: | Michelin 7 mm | Rear Right Side: | Michelin 7 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts  | 1,244.26          | 821.12            | 423.14            | 34.01         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour   | 730.00            | 470.00            | 260.00            | 35.62         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing   | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (\$\$)</b>                        | <b>1,974.26</b>   | <b>1,291.12</b>   | <b>683.14</b>     | <b>34.60</b>  |
| <b>+ GST 7.00/7.00% (\$\$)</b>                   | 138.20            | 90.38             | 47.82             | 34.60         |
| <b>Nett Amount (\$\$)</b>                        | <b>2,112.46</b>   | <b>1,381.50</b>   | <b>730.96</b>     | <b>34.60</b>  |
| <b>+ Loss of Use (2.5 x S\$50.00/day) (\$\$)</b> |                   | 125.00            |                   |               |
| <b>+ Car Rental (2.5 x S\$125.19/day) (\$\$)</b> |                   | 312.98            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                   |                   | 7.49              |                   |               |
| <b>Nett Liability (\$\$)</b>                     |                   | <b>1,826.97</b>   |                   |               |

### INSPECTION

Date of Assignment: 21/11/2019

Date Inspected: 21/11/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 2.0 days

**Adjuster:** PARASURAM SHANMUGAM**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition     | Repairer's | Amount     |
|-----|-----|----------|---|---------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                            | Deformed      | 459.40 FL  | *459.40 FL |
| 2   | 1   |          | *REAR BUMPER CENTRE MOULDING ASSY       | Cut           | 451.25 FL  | *451.25 FL |
| 3   | 1   |          | *REAR BUMPER LOWER CENTRE MOULDING ASSY | Not Necessary | 155.00 FL  | *- FL      |
| 4   | 1   |          | *REAR BUMPER STAY                       | Not Necessary | 138.10 FL  | *- FL      |
| 5   | 2   |          | *REAR BUMPER SIDE BRACKET (LH/RH)       | Not Necessary | 66.20 FL   | *- FL      |
| 6   | 1   |          | *REAR BUMPER COVER CLIPS                | Necessary     | 22.00 FL   | *22.00 FL  |
| 7   | 1   |          | *REAR BUMPER REVERSE SENSOR             | Not Necessary | 135.70 FS  | *- FS      |
| 8   | 1   |          | *REAR BUMPER RUBBER MAT                 | Necessary     | 50.00 FS   | *50.00 FS  |
| 9   | 1   |          | *REAR NO PLATE                          | Cracked       | 25.00 FS   | *25.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>1,502.65</b> | <b>1,007.65</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$)</b> | 258.39          | 186.53          |
| <b>Total Parts (\$)</b>                                  | <b>1,244.26</b> | <b>821.12</b>   |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                 | Lab.Type | Repairer's    | Amount        |
|---------------------------------|-----------------------------|----------|---------------|---------------|
| <b><u>Labour Items</u></b>      |                             |          |               |               |
| 1                               | PANEL BEATING               | New      | 350.00        | 240.00        |
| 2                               | SPRAY PAINTING CHARGE       | New      | 250.00        | 200.00        |
| 3                               | WIRING CHARGE               | New      | 50.00         | 0.00          |
| 4                               | REMOVE/REFIX REVERSE SENSOR | New      | 80.00         | 30.00         |
| <b>Gross Labour Cost (\$\$)</b> |                             |          | <b>730.00</b> | <b>470.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >