

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19020661/AGA3Q2

Date: 07/04/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00005463-02

Claimant
Vehicle No : SJF431P **Insured Vehicle No :** SJU2628Y

Date of Loss: 20/11/2019 **Nature of Claim:** TP **Claim No:** 1201900036052

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF431P	Engine No:	L13A4061535
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61053802
Reg. Date:	15/05/2008 (Man. Year: 2008)	Odometer:	176186 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,334.48	3,823.28	2,511.20	39.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	2,690.00	1,460.00	35.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,484.48	6,513.28	3,971.20	37.88
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	10,484.48	5,200.00	5,284.48	50.40
+ GST 7.00/7.00% (S\$)	733.91	364.00	369.91	50.40
Nett Amount (S\$)	11,218.39	5,564.00	5,654.39	50.40
+ Loss of Use (10.0 x S\$50.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,071.45		

INSPECTION

Date of Assignment: 20/11/2019

Date Inspected: 21/11/2019 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2020)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF431P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	788.90 FL	*788.90 FL
2	1		*TAIL GATE EMBLEM FIT	Necessary	60.00 FL	*60.00 FL
3	1		*TAIL GATE INNER LOCK	Not Necessary	198.20 FL	*- FL
4	1		*TAIL GATE CATCH	Not Necessary	55.70 FL	*- FL
5	1		*TAIL GATE WEATHER STRIP	Not Necessary	102.00 FL	*- FL
6	1		*TAIL GATE INNER TRIM	Not Necessary	153.50 FL	*- FL
7	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	97.10 FL	*97.10 FL
8	1		*REAR BUMPER	Distorted	555.30 FL	*555.30 FL
9	1		*REAR BUMPER SIDE RETAINER	O/S Necessary	129.00 FL	*32.40 FL
10	1		*REAR BUMPER TOWING COVER	Distorted	52.30 FL	*52.30 FL
11	1		*TAIL LAMP RH	Smashed	280.00 FL	*280.00 FL
12	1		*TAIL LAMP BRACKET RH	Not Necessary	48.00 FL	*- FL
13	1		*TAIL LAMP PANEL RH	Dented	155.60 FL	*155.60 FL
14	1		*REAR FENDER	Distorted	860.00 FL	*860.00 FL
15	1		*REAR FENDER INNER TRIM	Cracked	320.00 FL	*285.00 FL
16	1		*REAR FENDER AIRVENT	Cracked	90.00 FL	*90.00 FL
17	1		*REAR FENDER QUARTER GLASS MOULDING	Necessary	120.00 FL	*45.00 FL
18	1		*REAR END PANEL	Dented	380.00 FL	*380.00 FL
19	1		*REAR END PANEL TOP GARNISH	Deformed	120.00 FL	*120.00 FL
20	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
21	1		*SET TAIL GATE INNER TRIM CLIP	Not Necessary	20.00 FS	*- FS
22	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
23	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
24	1		*REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
25	1		*REAR BUMPER LOWER LIP	Not Necessary	1,200.00 FS	*- FS
26	1		*SET TAIL LAMP CLIP	Necessary	20.00 FS	*20.00 FS
27	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	20.00 FS	*20.00 FS
28	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
29	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
30	1		*WHEEL RIM	Cut	850.00 FS	*400.00 FS
31	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,247.60	4,583.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	913.12	760.32
Total Parts (\$\$)	6,334.48	3,823.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,600.00	1,200.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	1,000.00
3	TUFF COAT	New	250.00	100.00
4	WIRING CHECK	New	80.00	30.00
5	TRANSFER TAILGATE MECHANISM	New	100.00	80.00
6	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
7	REMOVE AND REFIX QUARTER GLASS	New	100.00	60.00
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	150.00	50.00
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	50.00
Gross Labour Cost (\$\$)			4,150.00	2,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >