

ASS. REC. BY:

REF: 08/FCI/9020669/Ud3n2 Special Instruction:

Surveyor: McKILL

ASSIGNMENT (Office)

From (Person): aus Jason Tea of FCI Date/Time: 11:50am @ 21/11/19

Estimated Cost: _____ Bill to: _____

OD (P) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: VAD5288 Insured: SHC1868Xat Workshop m/s T.K. Lee Automotive Tel: 6509 5521of 1 Kalei Bukit Ave 6 #02-47Policy No: _____ Claim No: D19007298MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15/11/2019
(Client's Record)CA / REV / REP. / REV 24 HRS up H.O.D. Endorsement: _____Date/Time: 12:13pm @ 21/11/19 Person Contacted: Adeline Vehicle IN OUT

Date/Time	Action/Instruction
	<u>Estimate /</u>
	<u>VAD5288-X</u>
	<u>SHC1868X-X</u>
<u>28/11/19</u>	<u>Email preli revised to FCI</u>

ASS. FEO. BY:

mcus

REP:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA LPR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c

Colour

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/11/19 11.000 confirmed with A/H Lai (Red 9593.54, 469)

RECEIVED 26 DEC 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 26/12 - typist

Report Format:

cws

Lump Sum / L.P. /

45 \$11,000k

Days Of Repair:

9

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Inve (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

OSP

26/12/19

10x15 = 150

170 + 150

50

50 + 50

197

667



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19007298MFSH

Our ref: CS/FCI19020669/Uvd3

DATE: 28/11/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO VAD 5288


We thank for your instruction on 21/11/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 21/11/2019 at the premises of M/s T K LEE AUTOMOTIVE PTE LTD

Workshop Estimate Amount	: S\$20,593.54
Revised Estimate Amount	: S\$15,965.62
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear and front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	18-11-2019	Our Ref No. D19007298MFSH
Accident Date	15-11-2019	Claim Type. Third Party
Insured Vehicle	SHC1868X	Third Party Vehicle. VAD5288
Survey Location	1 KAKI BUKIT AVE 6 #02-47 AUTOBAY	
Contact Person.	ADELINE SENG	
Contact No.	65095521/ 0	Fax No. 65095523
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	T K LEE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 28 November 2019 11:17 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Jason Tea'
Subject: RE: SURVEY ASSESSMENT - D19007298MFSH/1-VAD 5288
Attachments: VAD 5288 PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle VAD 5288
Date of survey: 21/11/2019
Number of days (estimated) : 9 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Thursday, 21 November 2019 3:35 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19007298MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 21 November 2019 11:50 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Jason Tea <JasonTea@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19007298MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[Home](#) / [Used Cars](#) / [Toyota](#) / [Innova](#) / [G](#)

Updated on: November 19, 2019

RM 685/month

RM 52,800

2012 Toyota Innova 2.0 G MPV

Updated on: November 19, 2019

 Dealer  Penang » Bukit Mertajam »

Seller Information

 Dealer  Penang » Bukit Mertajam

Key details

 Registration
Card View Car type
Used Car Make Toyota Model Innova Variant G Year 2012 Engine Capacity
1998 cc Transmission
Automatic Seat Capacity 8 Mileage
135000 - 140000 Colour Silver

ADVERTISING

[View All 13 Cars From This](#)

[Home](#) / [Used Cars](#) / [Toyota](#) / [Innova](#) / [G](#)

Updated on: November 17, 2019

2012 Toyota Innova 2.0 G MPV -- BEST DEAL --

Updated on: November 17, 2019

 Dealer 
 Johor » Johor Bahru »

RM 672/month

RM 51,800

Seller Information

 Dealer 
 Johor » Johor Bahru

Key details

 Car type
Used Car

 Make
Toyota

 Model
Innova

 Variant
G

 Year
2012

 Engine Capacity
1998 cc

 Transmission
Automatic

 Seat Capacity
8

 Mileage
70 - 75K

 Colour
Silver

[View All 55 Cars From This](#)


ADVERTISING



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

DTGRGEK

No. Pendaftaran	: VAD5288	WX C 8559
No. ID	: 911111016927	
Nama Pemunya Berdaftar	: LOW YONG HOU	
Alamat	: NO 23 JALAN SASA 23 TAMAN GAYA 81800 ULU TIRAM JOHOR	
No. Chasis/No. Enjin	: PN111NV4008632726 / ITR7326800	
Buatan>Nama Model	: TOYOTA / INNOVA 2.0 G (AT)	
Keupayaan Enjin	: 1998	
Bahan Bakar	: PETROL	
Status Asal	: PEMASANGAN TEMPATAN	
Kelas Kegunaan	: PERSENDIRIAN-MOTOKAR INDIVIDU	
Jenis Badan/Tahun Dibuat	: MOTOKAR PELBAGAI UTILITI / 2012	
Tarikh Pendaftaran	: 26/07/2012	
B. D. M/B. G. K/BTM	: - / - / -	
Syarat Pendaftaran 1	: -	
Syarat Pendaftaran 2	: -	
Syarat Pendaftaran 3	: -	



LONPAC INSURANCE BHD (307414-T)

Head Office: Lower Ground, 6th, 7th, 21st to 25th Floor, Bangunan Public Bank, 6 Jalan Sultan Sulaiman, 50000 Kuala Lumpur, Malaysia P.O. Box 10708, 50722 Kuala Lumpur, Malaysia
Tel: (03) 2262 8688 Fax: (03) 2072 3385 - Underwriting Website: www.lonpac.com

INSURANCE COVER NOTE

Account No : J15945JHR-8 Cover Note No : A3529782-7
Replacing Policy No : J/18/VP02/174533/JHR Date : 30/04/2019
Case : Renewal

CBC REGULATION

Section 84(1) of the Financial Services Act 2013:

No licensed insurer shall assume any risk in respect of such description of policy as may be prescribed by the Bank unless and until the premium payable is received by the licensed insurer in such manner and within such time as may be prescribed by the Bank.

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)
THE MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE
THE MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES (REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS) ACT (CAP 90) NEGARA BRUNEI DARUSSALAM

Whereas the Applicant named in the Schedule below having proposed for insurance and paid the premium in respect of the Motor Vehicle described in the Schedule below, the risk is hereby HELD COVERED in the terms of the Company's usual form of COMPREHENSIVE Policy applicable thereto for the period from 00:01 hours on 02/05/2019 to midnight on 01/05/2020 unless cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and the Company will return a proportionate part of the premium already collected for such insurance after due allowance for the period the Company has been on risk.

Name : LOW YONG HOU
Address : 23 JALAN SASA 23 TAMAN GAYA
81800 ULU TIRAM
JOHOR, MALAYSIA
NRIC : (Old) -
(New) 911111-01-6927

Make & Model	: TOYOTA INNOVA G TGN40R 4D WAGON 4 SP AUTOMATIC	Vehicle Regn. No	: VAD 5288
Regn. Card No	: -	Engine No	: 1TR7326800
Use of Vehicle	: PRIVATE CAR SECURE	Chassis No	: PN111NV4008632726
C.C./Tonnage/Other	: 1998	Year of Manufacture	: 2012
Seating Capacity	: 8	Hire Purchase Company	: NONE
Sum Insured	: RM 50,000.00 (AGREED VALUE)	NCB	: 25.00 %
Extra Benefits	: - LLP FOR NEGLIGENT ACTS - LEGAL LIABILITY TO PASSENGERS - WINDSCREEN RM 1,000.00	Excess	: SECTION A Policy Excess : Nil Compulsory Excess : RM400.00
Named Drivers	: ANY AUTHORISED DRIVERS	Premium Payable	: RM 1,665.38

Additional Policy
E-ASSIST SMART DRIVER

Premium Payable : RM 99.06
Service Tax : RM 5.94

Stamp Duty : RM 10.00
Total Amount Due : RM 1,780.38

We hereby certify that this Covering Note is issued on accordance with the provisions of Part IV of the Road Transport Act, 1987 (Malaysia) and The Motor Vehicles (Third Party Risks And Compensation) Act (Cap 189) Republic of Singapore, The Motor Vehicle Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

The Cover Note should be presented for registration with the RIMV within fourteen (14) days from the date of issuance of Cover Note.

Note:

1. Vehicles insured under Comprehensive Private Car must be repaired at our Panel Workshops. For lists of our panel workshops, please refer www.lonpac.com/web/my/panels.
2. Kindly contact Lonpac Insurance Bhd if you have not received your insurance policy after one month of purchase.

SY CONSULTANCY & MANAGEMENT
NO. 3, JALAN SASA 6 TAMAN GAYA 81800
ULU TIRAM JOHOR

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

FIRST CAPITAL INSURANCE LTD

NO.1 NORTH BRIDGE ROAD

#08-01 HIGH STREET CENTRE

SINGAPORE 179094

SHC1868X

ESTIMATE

DATE : 19.11.2019

VEHICLE NO : VAD5288

MAKE/MODEL : TOYOTA INNOVA

ACC DATE : 15.11.2019

Not Accident
2 car
2/3 #11,000
2/11/19
The Motor Claims Dept.

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	SS	SS
1	1 REAR WINDSCREEN MOULDING 145.50	297.54	297.54
2	1 REAR TAILGATE 138/60	1,519.28	1,519.28
3	2 REAR TAILGATE HINGE RH/LH	69.10	138.20
4	2 REAR TAILGATE DAMPER RH/LH	201.60	403.20
5	1 REAR TAILGATE RUBBER 287.50	381.55	381.55
6	1 REAR TAILGATE LOCK	361.48	361.48
7	1 REAR TAILGATE LOCK CATCH	46.20	46.20
8	1 REAR TAILGATE INNER TRIM 257.10	606.23	606.23
9	1 REAR TAILGATE EMBLEM LOGO	76.95	76.95
10	1 REAR TAILGATE EMBLEM 2.0	58.50	58.50
11	1 REAR TAILGATE EMBLEM G	59.10	59.10
12	2 REAR TAILLAMP RH/LH	481.65	963.30
13	1 REAR BUMPER 665.10	902.43	902.43
14	2 REAR BUMPER REFLECTOR	82.65	165.30
15	2 REAR BUMPER BRACKET RH/LH	110.35	220.70
16	2 REAR BUMPER SIDE RETAINER RH/LH	141.55	283.10
17	1 REAR SPARE TYRE CARRIER	353.10	353.10
18	1 REAR EXHAUST PIPE 699.10	794.10	794.10
19	2 REAR EXHAUST MOUNTING	45.30	90.60
20	1 REAR END PANEL 665.10	687.66	687.66
21	1 REAR END PANEL GARNISH 266.50	315.02	315.02
22	2 REAR FENDER INNER TRIM RH/LH	672.43	1,344.86
23	1 FRONT BONNET 739.10	916.65	916.65
24	1 FRONT BONNET MOULDING 166.50	241.65	241.65
25	1 FRONT BONNET RUBBER 68.30	126.03	126.03
26	1 FRONT BONNET LOCK	151.90	151.90
27	1 FRONT BONNET LOCK GARNISH	75.02	75.02
28	1 FRONT GRILLE	551.63	551.63
29	1 FRONT GRILLE EMBLEM LOGO	75.90	75.90
30	2 FRONT HEADLAMP RH/LH 680.50 x 2 = 1361.00	978.15	1,956.30
31	1 FRONT BUMPER 688.10	1,095.72	1,095.72
32	1 FRONT BUMPER FOG LAMP LH	315.60	315.60
33	1 FRONT BUMPER FOG LAMP COVER LH	126.08	126.08
34	1 FRONT BUMPER REINFORCEMENT 339.10	481.65	481.65
35	2 FRONT BUMPER SIDE RETAINER RH/LH 65 x 2 = 130	96.10	192.20
36	1 FRONT SUPPORT PANEL 919.10	1,216.43	1,216.43
37	2 FRONT SUPPORT PANEL GARNISH RH/LH	98.10	196.20
38	1 FRONT BRACE PANEL	120.43	120.43

T K LEE AUTOMOTIVE PTE.LTD

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
39	1 AIR CON CONDENSER	1,427.32	1,427.32 ✓
40	1 RADIATOR	1,989.61	1,989.61 X
			21,324.72
		LESS 25%	5,331.18
			15,993.54

SPECIAL NETT ITEMS

1	1 REAR WINDSCREEN SPONGE TAPE	20.00	20.00 ✓
2	1 (SET) REAR WINDSCREEN SEALANT	80.00	80.00 40
3	1 (SET) REAR BUMPER REVERSE SENSOR	280.00	280.00 200
4	1 (SET) REAR BUMPER CLIPS	35.00	35.00 ✓
5	1 (SET) FRONT NUMBER PLATE WITH CASING	50.00	50.00 40
6	1 (SET) FRONT BUMPER CLIPS	45.00	45.00 35
7	1 AIR CON OIL	45.00	45.00 X
8	1 RADIATOR COOLANT	25.00	25.00 X
			580.00

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD REAR PANEL, FRONT SUPPORT PANEL	1,600.00	1,200
2	AND REPLACE ACCIDENT PARTS.		
3	TO SPRAY PAINTING ON ACCIDENT PORTION	1,600.00	1,500
4	TO CHECK WIRING	60.00	30
5	TO REMOVE, REPLACE CONDENSER AND REFILL GAS	120.00	100
6	TO REMOVE, REFIX REAR WINDSCREEN	120.00	120
7	TO TRANSFER REAR TAILGATE PARTS	100.00	60
8	TO REMOVE, REFIX CUSHION AND INNER TRIM	120.00	80
9	TO REMOVE, REPLACE REVERSE SENSOR	80.00	50
10	TO REMOVE, REPLACE REAR EXHAUST PIPE	120.00	50
	TO TUFF KOTE	100.00	90
		4,020.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 20,593.54

LKKV
 (1) Repairer of the following:
 • To resurvey be repaired spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

13621.07
 252
 P-10214.80
 S.N-370.00
 - 1-3280.00
 13864.80
 2070
 11092.44



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19020669/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-01-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1868X	Veh. Inspected	VAD 5288	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19007298MFSH	Excess (\$)	0.00	
Assign From	JASON TEA	Assign Date	21/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA INNOVA (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	PN111NV4008632726	Colour	GREY	
Odometer	344686	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R15	HANKOOK	5 mm	
L/H Front Tyre	205/65 R15	HANKOOK	5 mm	
R/H Rear Tyre	205/65 R15	HANKOOK	5 mm	
L/H Rear Tyre	205/65 R15	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/11/2019	Inspection Date	21/11/2019	
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. VAD 5288

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING	NECESSARY	297.54	145.50
1	REAR TAILGATE	BADLY DENTED	1,519.28	1,391.60
2	REAR TAILGATE HINGE RH/LH @\$69.10	NOT NECESSARY	138.20	-
2	REAR TAILGATE DAMPER RH/LH @\$201.60	NOT NECESSARY	403.20	-
1	REAR TAILGATE RUBBER	TWISTED	381.55	281.50
1	REAR TAILGATE LOCK	TWISTED / SHORTED	361.48	361.48
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	46.20	-
1	REAR TAILGATE INNER TRIM	DEFORMED / CRACKED	606.23	587.10
1	REAR TAILGATE EMBLEM LOGO	NECESSARY	76.95	76.95
1	REAR TAILGATE EMBLEM 2.0	NECESSARY	58.50	58.50
1	REAR TAILGATE EMBLEM G	NECESSARY	59.10	59.10
2	REAR TAILLAMP RH/LH @\$481.65	O/S CRACKED	963.30	481.65
1	REAR BUMPER	DEFORMED	902.43	665.10
2	REAR BUMPER REFLECTOR @\$82.65	CRACKED (1 PC ONLY)	165.30	82.65
2	REAR BUMPER BRACKET RH/LH @\$110.35	O/S BENT	220.70	110.35
2	REAR BUMPER SIDE RETAINER RH/LH @\$141.55	O/S BENT	283.10	141.55
1	REAR SPARE TYRE CARRIER	JAMMED	353.10	353.10
1	REAR EXHAUST PIPE	BENT / TWISTED	794.10	699.10
2	REAR EXHAUST MOUNTING @\$45.30	NOT NECESSARY	90.60	-
1	REAR END PANEL	DENTED	687.66	665.10
1	REAR END PANEL GARNISH	TWISTED	315.02	266.50
2	REAR FENDER INNER TRIM RH/LH @\$672.43	NOT NECESSARY	1,344.86	-
1	FRONT BONNET	BENT / BUCKLED	916.65	739.10
1	FRONT BONNET MOULDING	CRACKED	241.65	166.50
1	FRONT BONNET RUBBER	NECESSARY	126.03	68.50
1	FRONT BONNET LOCK	TWISTED	151.90	151.90
1	FRONT BONNET LOCK GARNISH	NOT NECESSARY	75.02	-
1	FRONT GRILLE	CRACKED	551.63	551.63
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	75.90	75.90

Report Ref No. CS/FCI19020669/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT HEADLAMP RH/LH @\$978.15	CRACKED	1,956.30	1,361.00
1	FRONT BUMPER	DEFORMED	1,095.72	688.10
1	FRONT BUMPER FOG LAMP LH	CRACKED	315.60	315.60
1	FRONT BUMPER FOG LAMP COVER LH	MISSING	126.08	126.08
1	FRONT BUMPER REINFORCEMENT	BENT	481.65	339.10
2	FRONT BUMPER SIDE RETAINER RH/LH @\$96.10	BENT	192.20	130.00
1	FRONT SUPPORT PANEL	BENT	1,216.43	919.10
2	FRONT SUPPORT PANEL GARNISH RH/LH @\$98.10	TORN	196.20	196.20
1	FRONT BRACE PANEL	TWISTED	120.43	120.43
1	AIR CON CONDENSER	BENT	1,427.32	1,245.10
1	RADIATOR	NOT NECESSARY	1,989.61	-
	LESS 25% DISCOUNT		-5,331.18	-3,405.27
			15,993.54	10,215.80
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SPONPE TAPE (SN)	NECESSARY	20.00	20.00
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
1	SET FRONT NUMBER PLATE WITH CASING (SN)	CRACKED	50.00	40.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	45.00	35.00
1	AIR CON OIL (SN)	NOT NECESSARY	45.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	25.00	-
			580.00	370.00
	LABOUR			
	TO KNOCK OUT DENT,CUT/WELD REAR PANEL,FRONT SUPPORT PANEL AND REPLACE ACCIDENT PARTS.		1,600.00	1,200.00
	TO SPRAY PAINTING ON ACCIDENT PORTION.		1,600.00	1,500.00
	TO CHECK WIRING.		60.00	30.00
	TO REMOVE,REPLACE CONDENSER AND REFILL GAS.		120.00	100.00
	TO REMOVE,REFIX REAR WINDSCREEN.		120.00	120.00
	TO TRANSFER REAR TAILGATE PARTS.		100.00	60.00
	TO REMOVE,REFIX CUSHION AND INNER TRIM.		120.00	80.00
	TO REMOVE,REPLACE REVERSE SENSOR.		80.00	50.00

Report Ref No. CS/FCI19020669/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE,REPLACE REAR EXHAUST PIPE. TO TUFF KOTE.		120.00 100.00 4,020.00	50.00 90.00 3,280.00
GRAND TOTAL			20,593.54	13,865.80

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00
---	--	--	--	-----------

Report Ref No. CS/FCI19020669/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.