Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC4/III19020670/QGA3Q2 Our File No:

Date: 24/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant Insured Vehicle No: SHC1982Z SMM2420K

Vehicle No:

Date of Loss: Nature of Claim: ΤP 06/11/2019 Claim No: MCT19110148

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMM2420K Reg No:

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR2D40814 Reg. Date: 24/06/2019 (Man. Year: 2019) Chassis No: ZYX102173763 Colour: Odometer: 25728 km Black

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17 Rear Left Side: Front Left Side: Firestone 6 mm Firestone 6 mm Front Right Side: Rear Right Side: Firestone 6 mm Firestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,914.32	2,079.42	1,834.90	46.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	950.00	430.00	31.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,294.32	3,029.42	2,264.90	42.78
+ GST 7.00/7.00% (S\$)	370.60	212.06	158.54	42.78
Nett Amount (S\$)	5,664.92	3,241.48	2,423.44	42.78
. 1	100 00/ L \ \ (00\)	000.00		

+ Loss of Use (4.0 x S\$80.00/day) (S\$) 320.00

> 3,561.48 **Nett Liability (S\$)** Global Sum Settlement (S\$) 3.500.00

INSPECTION

Date of Assignment: 21/11/2019

Date Inspected: 30/12/2019 Inspected At: Hua Hong Pte Ltd (Sungei Kadut)

25D Sungei Kadut Street 1

Singapore 729332

Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference			
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2020)	
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	Print Code: (Unsubmitted, no print-code for SMM2420K)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR (LH)	Repair	1,168.30 FL	*-FL
2	1		*FRONT DOOR TAPE (LH)	Serviceable	82.40 FL	*-FL
3	1		*FRONT DOOR WEATHER STRIP (LH)	Serviceable	232.10 FL	*-FL
4	1		*FRONT DOOR GARNISH (LH)	Scratched	380.00 FL	*380.00 FL
5	1		*REAR DOOR (LH)	Dented	1,084.90 FL	*1,084.90 FL
6	1		*REAR DOOR GARNISH (LH)	Scratched	321.70 FL	*321.70 FL
7	1		*REAR DOOR TAPE (LH)	Necessary	81.70 FL	*81.70 FL
8	1		*REAR DOOR WEATHER STRIP (LH)	Serviceable	245.70 FL	*-FL
9	1		*REAR FENDER ARCH GARNISH (LH)	Scratched	278.50 FL	*278.50 FL
10	1		*SIDE SKIRT (LH)	Scratched	529.10 FL	*529.10 FL
11	10		*SIDE SKIRT CLIP	Necessary	51.00 FL	*30.00 FL
12	1		*REAR RIM (RH) (LOCAL REPAIR)	Damaged	350.00 FS	*50.00 FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.					
				Sub Total (S\$)	4,805.40	2,755.90
	- List Item Discount on L Items 20.00/25.00% (S\$)			891.08	676.48	
				Total Parts (S\$)	3,914.32	2,079.42
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	<u>Labour Items</u>					
1	TO DISMANTLE & CHARGE FRONT LH DOOR ,REAR LH DOOR ,LH SIDE SKIRT ,KNOCKING & PULL STRAIGHT ALL AREA AFFECTED BY ACCIDENT	New	600.00	400.00		
2	TO PERFORM WIRE CHECKING	New	20.00	20.00		
3	TO DISMANTLE & REFIX FRONT LH DOOR ,REAR LH DOOR MECHANISM AND FITTING TO NEW DOOR	New	120.00	60.00		
4	TO DISMANTLE & REFIT LH REAR RIM & BALANCING	New	40.00	20.00		
5	TO SPRAY FRONT LH DOOR ,REAR LH DOOR AND ALL AREA AFFECTED BY ACCIDENT	New	600.00	450.00		
	Gross Labou	ır Cost (S\$)	1,380.00	950.00		

< END OF ESTIMATES >

Report was unsubmitted during this print-out.