

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020698/KDA3Q2

Date: 29/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994197

Claimant
Vehicle No : SKX4028M **Insured Vehicle No :** GBF8103D

Date of Loss: 19/11/2019 Nature of Claim: TP Claim No: 6923572260SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX4028M	Engine No:	2ZR1686193
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W70J003479
Reg. Date:	10/12/2015 (Man. Year: 2015)	Odometer:	119775 km
Colour:	Metallic Gold		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 3 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Yokohama 3 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,142.34	1,966.32	1,176.02	37.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,020.00	1,160.00	53.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,322.34	2,986.32	2,336.02	43.89
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	5,322.34	2,350.00	2,972.34	55.85
+ GST 7.00/7.00% (S\$)	372.56	164.50	208.06	55.85
Nett Amount (S\$)	5,694.90	2,514.50	3,180.40	55.85
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
(S\$)		2,834.50		
Liabe Amount (80.00%) (S\$)		2,267.60		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,275.05		
Global Sum Settlement (S\$)		2,400.00		

INSPECTION

Date of Assignment: 22/11/2019

Date Inspected: 22/11/2019 Inspected At:

Wei Lee Motor Works (HQ)
BLOCK 9 SIN MING INDUSTRIAL

ESTATE #01-32
Singapore 575644

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER ,LH	Bent	773.40 FL	*773.40 FL
2	1		*FRONT WHEEL BEARING	Not Necessary	119.43 FL	*- FL
3	1		*FRONT WHEEL BEARING HUP	Not Necessary	179.90 FL	*- FL
4	1		*FRONT ABSORBER ,LH	Bent	425.50 FL	*425.50 FL
5	1		*LINKAGE ,LH	Serviceable	178.70 FL	*- FL
6	1		*LOWER ARM	Bent	459.33 FL	*459.33 FL
7	1		*RIM ,LH	Dented	280.00 FS	*250.00 FS
8	1		*HEADLAMO	Serviceable	1,050.00 FL	*- FL
9	1		*FRONT BUMPER	Cracked	574.90 FL	*574.90 FL
10	1		*BUMPER RETAINER	Distorted	55.30 FL	*55.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,096.46	2,538.43
- List Item Discount on L Items 25.00/25.00% (\$)	954.12	572.11
Total Parts (\$)	3,142.34	1,966.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS AND ATTACHMENTS ,REPAIR /RESHAPE DENTED AREAS STRAIGHTEN FRONT GRILLE REPLACE /ALIGN ABOVE PARTS INTO POSITION	New	950.00	400.00
2	TO SPRAY PAINT	New	800.00	400.00
3	TO REMOVE/REPLACE UNDERCARRIAGE PARTS	New	350.00	160.00
4	REDO WHEEL ALIGNMENT	New	80.00	60.00
Gross Labour Cost (S\$)			2,180.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >