

ASSIGNMENT

Surveyor: ADRIAN DOI: 21.11.2019 Date / Time: 21.11.2019Registered in Merimen: —

Pre-assign / CCU / FTE

Insured Vehicle No. : GBJ 4042BClaim No. : Name of Insured : KONTOURZ PTE LTDPolicy No. : Insured Tel No. : HP: Make / Model : Excess Sec II : \$ D.O.A : 20/11/2019 11:20Place of Accident : BLK 5022 AMK PARK 2 (LOT NO: 27) CARPARKIs driver the owner? (YES ☒ NO ☐) Nature of Accident : If NO, Driver Name / Age : OI GIA REPORT: ☒ YES / NO : TP GIA REPORT ☒ YES / NODriver Tel No. : (V/L: ☒ YES ☐ NO)Insured Liability : % Final ? Yes / No

GBB 6880C

INSRS:
WSP: FASTECH
Tel :
Liability :
RMKS: INSRS:
WSP:
Tel :
Liability :
RMKS: INSRS:
WSP:
Tel :
Liability :
RMKS: INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☒ ☐
	After call ltr to OI:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☒ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA :	☒ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☐ ☐
	LOD	☒ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	\$S	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time: <u>8/2/2020</u>	Confirm with: <u>Joan</u>
Final Liability:	% <u>100</u>	(Agreed / Assessed) BOLA S/N No. : <u>24</u>	Email ☒ Call ☐
Repair Cost: <u>(w/hjt)</u>	\$S <u>2675.00</u>	<u>at reversing</u>	If NO or B 28, Ass. Lia :
Loss of Rental (LOR):	\$S <u>200.00</u>	(<u>2</u> days) x \$100	
Loss of Use (LOU):	\$S <u>-</u>	(\$ x days)	
Loss of Income (LOI):	\$S <u>-</u>	(\$ x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	\$S <u>2.00</u>		
Medical:	\$S <u>-</u>		
Disbursement:	\$S <u>-</u>	(e.g. Tow/ Independent)	
Legal Cost	\$S <u>-</u>		
Total:	\$S <u>2877.00</u>	Global Sum \$S:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$S <u>2877.00</u>	Name 1:	<u>Fastech Auto Pte Ltd</u>
Payee 2: (Strike if N.A.)	\$S	Name 2:	
Payee 3: (Strike if N.A.)	\$S	Name 3:	

REFS

2072 Ad

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:			
IDAC Accident Rpt:		Consistent? :	Yes or No
GIA / PR Seen:		Consistent? :	Yes or No
Est. Repairs:	4	days	Res.: Yes or No
Lum Sum:	20	%	3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Veh No: G886880L Yr Reg: 2009 / NoV
 Type: M.Car / M.Cycle / Bus / Van (Lor) / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mit Canter CC 2977
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 119015 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: F370BBA20103
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 155 R15C
 R: 155 R15C

(BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO OF

Front	Rear
R/Bal. <u>06</u> mm	R/Bal. <u>06</u> mm
L/Bal. <u>06</u> mm	L/Bal. <u>06</u> mm
D.O.A. _____	D.O.I. <u>21/11/19</u>

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Churn.
	COE Expiry: 31/10/18.
	LI - \$2500 (Red \$ 9070.70 782)
	MV:
	PV:
	Nett.

Date/Time, File Path etc

☐: Prel. Report

35

☐: Final Report

CircleTime, Film Forum Inc.

2

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Trustworthiness

© 1999 Blackwell Science Ltd

1994

Report Format:

1999-2000 / LEA: 02

Add Fee: : Site Insp (\$

Site Insp (3)

 Interview (3)

☐ Tech. inv. 6

10/10/2012 12:18

FASTECH AUTO PTE LTD

Page 1 to 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 21525

Date : 22.11.2019

Vehicle Num : GBB 6880C

Make/Model : MIT CANTER

Chassis/Engine no :

Accident Date : 20.11.2019

Claim No : 1119-21525

Reference :

Policy No :

TP China

Jiale

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

1 pc	Front windscreen mldg	new	\$	352.50	+
1 pc	Front panel	new	\$	915.80	+
1 pc	Front corner panel (RH)	Dented	\$	235.60	✓
1 pc	Front head lamp (RH)	Crashed	\$	659.20	✓
1 pc	Front side lamp (RH)		\$	221.20	✓
1 pc	Front signal lamp (RH)		\$	235.10	✓
1 pc	Front bumper	Best	\$	998.50	✓
2 pc	Front bumper bracket @ 253.20	new	\$	506.40	+
1 pc	Front grille	new	\$	456.20	+
1 pc	Front grille emblem		\$	195.20	+
1 pc	Front side mirror stay bar (RH)	Best	\$	235.50	✓
2 pc	Front side mirror @ 159.20	new	\$	318.40	+
2 pc	Front side mirror cover @ 165.30	new	\$	330.60	✓
1 pc	Front door (RH)	new	\$	1,652.20	+
1 pc	Front door lock (RH)		\$	525.30	+
2 pc	Front door hinge @ 101.20 (RH)		\$	202.40	+
1 pc	Front door rubber (RH)		\$	351.20	+
1 pc	Front door inner board (RH)		\$	985.20	+
1 pc	Front door inner pillar (RH)		\$	851.60	+
1 pc	Front door step plate (RH)		\$	199.50	+
List Item Total :			\$	10,427.60	
Discount 25 % :			\$	2,606.90	
			\$	7,820.70	

2915.70

2186.77

Special Nett Item

1 pc	Front number plate	new	\$	45.00 +
1 pc	Front windscreen glass sealant	new	\$	100.00 +
1 pc	Front door company name sticker	new	\$	45.00 - 30
Special Nett Total :			\$	190.00

30

FASTECH AUTO PTE LTD

Page 2 to 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Estimate : 21525

Date : 22.11.2019

Vehicle Num : GBB 6880C

Make/Model : MIT CANTER

Chassis/Engine no :

Accident Date : 20.11.2019

Claim No : 1119-21525

Reference :

Policy No :

Qty	Particular	Amount S\$
	<u>Labour Charge :</u>	
	To check wiring	\$ 80.00 ³⁰
	Remove and refix front windscreen glass	\$ 180.00 +
	Remove and refix meter , dashboard and wire	\$ 450.00 +
	Remove and refix cushion seat and carpet	\$ 150.00 +
	Knock dent on damage portion, cut welding and renew parts	\$ 1,500.00 ⁴⁰⁰
	Respray painting	\$ 1,200.00 ⁵⁰⁰
	Labour Charge Total :	\$ 3,560.00

Singdollars :Seventy Four Thousand Six Hundred Fourty Three And Cents Ninety Five Only .

E & O .E

Total Amount : \$ 11,570.70

FASTECH AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

As acknowledged by Repairer

Adrian Lj
w/s 21/11/19.
04 P.yp

total 314677
w/s 2.5K.

Mei Kwan (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 9 January, 2020 11:14 AM
To: Mei Kwan (LKKAuto)
Cc: Admin A; Jia Le (LKK Auto)
Subject: RE: OUR REF: SNM19D205640/GBJ4042B/CBS & YOUR REF: (TP : LKK REF - CC6/CTI19020702/Ada3 -Direct Settlement - Accident Involving GBJ4042B AND GBB6880C) on 20/11/2019
Attachments: insured report.PDF
Categories: HMK

Dear Mei Kwan,

Pls find Insured report.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, January 9, 2020 10:22 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: Admin A <admin-a@lkkauto.com>; Jia Le (LKK Auto) <JiaLe@lkkauto.com>
Subject: RE: OUR REF: SNM19D205640/GBJ4042B/CBS & YOUR REF: (TP : LKK REF - CC6/CTI19020702/Ada3 -Direct Settlement - Accident Involving GBJ4042B AND GBB6880C) on 20/11/2019

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Wishing you a Happy and Prosperous Lunar New Year



Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Meanwhile, kindly let us have a copy of insured's accident report for our necessary action.

Kindly take note that the case handler in-charge is Jia Le and she can be contacted at DID: 6749 5792.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No, 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI19020702/Ada3q2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 26-03-2020	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBJ 4042B	Veh. Inspected	GBB 6880C	
Policy No.	DMCVSN1935821900	Coverage (\$)	0.00	
Claim No.	SNM19D205640	Excess (\$)	0.00	
Assign From		Assign Date	21/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	FB70BBA20103	Colour	WHITE	
Odometer	119015	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/11/2019	Inspection Date	21/11/2019	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 6880C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT WINDSCREEN MLDG	NOT NECESSARY	352.50	-
1	FRONT PANEL	NOT NECESSARY	915.80	-
1	FRONT CORNER PANEL (RH)	DENTED	235.60	235.60
1	FRONT HEAD LAMP (RH)	CRACKED	659.20	659.20
1	FRONT SIDE LAMP (RH)	CRACKED	221.20	221.20
1	FRONT SIGNAL LAMP (RH)	CRACKED	235.10	235.10
1	FRONT BUMPER	BENT	998.50	998.50
2	FRONT BUMPER BRACKET @\$253.20	NOT NECESSARY	506.40	-
1	FRONT GRILLE	NOT NECESSARY	456.20	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	195.20	-
1	FRONT SIDE MIRROR STAY BAR (RH)	BENT	235.50	235.50
2	FRONT SIDE MIRROR @\$159.20	NOT NECESSARY	318.40	-
2	FRONT SIDE MIRROR COVER @\$165.30	CRACKED	330.60	330.60
1	FRONT DOOR (RH)	TO REPAIR SEE LABOUR	1,652.20	-
1	FRONT DOOR LOCK (RH)	NOT NECESSARY	525.30	-
2	FRONT DOOR HINGE (RH) @\$101.20	NOT NECESSARY	202.40	-
1	FRONT DOOR RUBBER (RH)	NOT NECESSARY	351.20	-
1	FRONT DOOR INNER BOARD (RH)	NOT NECESSARY	985.20	-
1	FRONT DOOR INNER PILLAR (RH)	NOT NECESSARY	851.60	-
1	FRONT DOOR STEP PLATE (RH)	NOT NECESSARY	199.50	-
	LESS 25% DISCOUNT		-2,606.90	-728.93
			7,820.70	2,186.77
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	FRONT WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	100.00	-
1	FRONT DOOR COMPANY NAME STICKER (SN)	NECESSARY	45.00	30.00
			190.00	30.00
<u>LABOUR</u>				
	TO CHECK WIRING		80.00	30.00

Report Ref No. CC6/CTI19020702/Ada3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX FRONT WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	REMOVE AND REFIX METER ,DASHBOARD AND WIRE.	NOT NECESSARY	450.00	-
	REMOVE AND REFIX CUSHION SEAT AND CARPET.	NOT NECESSARY	150.00	-
	KNOCK DENT ON DAMAGE PORTION ,CUT WELDING AND REEW PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR (RH) .		1,500.00	400.00
	RESPRAY PAINTING.		1,200.00	500.00
			3,560.00	930.00
GRAND TOTAL			11,570.70	3,146.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CC6/CTI19020702/Ada3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.