Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020710/HBA3N2

**Date:** 22/05/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant GBA801B Insured Vehicle No: SLQ5122S

Vehicle No: GBA801B Insured vehicle No: SEQ51225

Date of Loss: 20/11/2019 Nature of Claim: TP Claim No: 6969339355SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: GBA801B

Make & Model: TOYOTA HIACE, 3.0 D (M) Engine No: 1KD1566856

Reg. Date: 07/02/2007 (Man. Year: 2006) Chassis No: JTFHT02P600001889

Colour: Blue Odometer: 454624 km

Engine Capacity: 2982 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: CST TIRE 5 mm Rear Left Side: CST TIRE 4 mm
Front Right Side: CST TIRE 5 mm Rear Right Side: CST TIRE 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,411.20	718.56	2,692.64	78.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	840.00	1,470.00	63.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,721.20	1,558.56	4,162.64	72.76
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	5,721.20	1,250.00	4,471.20	78.15
+ GST 7.00/7.00% (S\$)	400.48	87.50	312.98	78.15
Nett Amount (S\$)	6,121.68	1,337.50	4,784.18	78.15
+ Car Rental (4.0 x S\$110.00/day) (S\$) + Doc/Search Fee (S\$)		440.00		
		2.00		
Ne	tt Liability (S\$)	1,779.50		

**INSPECTION** 

Date of Assignment: 26/11/2019

Date Inspected: 26/11/2019 Inspected At: Abwin Service Pte Ltd (HQ)

No. 8 Kaki Bukit Avenue 4, #07-48

Premier@Kaki Bukit Gate 2

Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster Report Page 2 of 4

Adjuster: LEE HOCK ANN Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*TAIL LAMP RH	Cracked	265.20 F	*231.85 FL		
2	1		*TAIL LAMP BRACKET RH	Serviceable	48.50 F	*- FL		
3	1		*TAIL LAMP LOWER GARNISH RH	Serviceable	108.90 F	*- FL		
4	1		*TAIL LAMP LOWER GARNISH RETAINER RH	Serviceable	51.60 F	*- FL		
5	1		*REAR BUMPER	Crumpled	396.10 F	*396.10 FL		
6	1		*REAR BUMPER SIDE RETAINER RH	Necessary	51.60 F	*36.80 FL		
7	1		*REAR FENDERRH	Repair	1,553.70 F	*- FL		
8	1		*REAR SLIDING DOOR TRACK RH	Serviceable	428.90 F	*- FL		
9	1		*REAR SLIDING DOOR TRACK COVER RH	Serviceable	56.70 F	*- FL		
10	10		*REAR BUMPER CLIPS (1 SET)	Necessary	50.00 FS	*20.00 FS		
11	1		*REAR FENDER RH SEALANT	Serviceable	50.00 FS	*-FS		
12	1		*REAR SLIDING DOOR TRACK RH SEALANT	Serviceable	50.00 FS	*- FS		
13	1		*REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS		
F=Fra	ınchise	part. S=SpcI	Nett. L=ListItemDisc.	*				
				Sub Total (S\$)	3,411.20	884.75		
	- List Item Discount on L Items 0.00/25.00% (S\$)					166.19		
				Total Parts (S\$)	3,411.20	718.56		
	Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	New	1,000.00	500.00				
2	TO SPRAY PAINT ON AFFECTED AREAS	New	800.00	300.00				
3	TO CHECK WIRING	New	120.00	20.00				
4	TO APPLY UNDERCOATING FOR RUST PROOFING	New	150.00	0.00				
5	TO DISMANTLE ,REPLACE AND /OR REPAIR REVERSE SENSOR & TESTING	New	120.00	20.00				
6	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	New	120.00	0.00				
	Gross Labour Cost (S\$)		2,310.00	840.00				
	Report was unsubmitted duri	ng this print-out.						

< END OF ESTIMATES >