

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19020712/GKB3Q2

Date: 17/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : FBN1635P

Insured Vehicle No : SKW8012L

Date of Loss: 09/09/2019

Nature of Claim: TP

Claim No: 7483121023SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN1635P**

Make & Model: YAMAHA NMAX155, 155cc

Engine No: G3H6E0009529

Reg. Date: 25/07/2018 (Man. Year: 2018)

Chassis No: MH3SG431000007400

Colour: White

Odometer: 0 km

Engine Capacity: 155 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-13

Rear Tyre Size:

130/70-13

Front Left Side: Dunlop 4 mm

Rear Left Side:

Dunlop 4 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 786.00 | 561.80 | 224.20 | 28.52 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 343.00 | 235.00 | 108.00 | 31.49 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (\$\$) | 1,129.00 | 796.80 | 332.20 | 29.42 |
| + GST 7.00/7.00% (\$\$) | 79.03 | 55.78 | 23.25 | 29.42 |
| Nett Amount (\$\$) | 1,208.03 | 852.58 | 355.45 | 29.42 |
| + Loss of Use (3.0 x S\$20.00/day) (\$\$) | | 60.00 | | |
| + Doc/Search Fee (\$\$) | | 2.00 | | |
| Nett Liability (\$\$) | | 914.58 | | |

INSPECTION

Date of Assignment: 21/11/2019

Date Inspected: 21/11/2019 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|------------|------------|
| 1 | 1 | | *BELLY PAN | Cut | 34.00 F | *34.00 FL |
| 2 | 1 | | *BOARD FOOTREST LH | Not Necessary | 52.00 F | *- FL |
| 3 | 1 | | *BOARD FOOTREST RH | Cut | 52.00 F | *52.00 FL |
| 4 | 1 | | *BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT | Cut | 208.00 F | *208.00 FL |
| 5 | 1 | | *COVER CLUTCH OUTER | Not Necessary | 28.00 F | *- FL |
| 6 | 1 | | *COVER CLUTCH OUTER DAMPER 1 | Not Necessary | 12.00 F | *- FL |
| 7 | 1 | | *COVER CLUTCH OUTER DAMPER 2 | Not Necessary | 7.00 F | *- FL |
| 8 | 1 | | *COVER CLUTCH OUTER DAMPER 3 | Not Necessary | 7.00 F | *- FL |
| 9 | 1 | | *COVER CLUTCH OUTER DAMPER 4 | Not Necessary | 12.00 F | *- FL |
| 10 | 1 | | *COVER SIDE CENTRE RH (WHITE) | Not Necessary | 30.00 F | *- FL |
| 11 | 1 | | *COWLING FRONT RH (WHITE) | Cut | 38.00 F | *38.00 FL |
| 12 | 2 | | *EMBEM (YAMAHA) LOGO | Necessary | 22.00 F | *22.00 FL |
| 13 | 1 | | *LEVER BRAKE RH | Cut | 18.00 F | *18.00 FL |
| 14 | 1 | | *MIRROR RH | Cut | 37.00 F | *37.00 FL |
| 15 | 1 | | *MUDGUARD FRONT (WHITE) | Cut | 52.00 F | *52.00 FL |
| 16 | 4 | | *NUT SPRING | Necessary | 8.00 F | *8.00 FL |
| 17 | 1 | | *PANEL 1 | Cut | 19.00 F | *19.00 FL |
| 18 | 1 | | *PANEL 2 | Not Necessary | 22.00 F | *- FL |
| 19 | 1 | | *PROTECTOR EXHAUST | Cut | 38.00 F | *38.00 FL |
| 20 | 8 | | *SCREW TAPPING | Necessary | 16.00 F | *16.00 FL |
| 21 | 1 | | *STICKER (CISCO) COWLING FRONT RH | Necessary | 37.00 FS | *37.00 FS |
| 22 | 1 | | *STICKER (CISCO) MUDGUARD FRONT | Necessary | 37.00 FS | *37.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|---------------|---------------|
| Sub Total (\$\$) | 786.00 | 616.00 |
| - List Item Discount on L Items 0.00/10.00% (\$\$) | 0.00 | 54.20 |
| Total Parts (\$\$) | 786.00 | 561.80 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|---------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | TRANSPORT CHARGES | New | 49.00 | 35.00 |
| 2 | LABOUR QUOTED FOR DISMANTLE AND INSTALLATION OF PARTS | New | 294.00 | 200.00 |
| Gross Labour Cost (S\$) | | | 343.00 | 235.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >