Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020727/QPA3Q2

Date: 13/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SLH360B Insured Vehicle No: SLR4755S

Date of Loss: 20/11/2019 Nature of Claim: TP Claim No: 0544992201SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH360B

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRR957637

Reg. Date: 21/10/2016 (Man. Year: 2016) Chassis No: JTDKB3FU703536490

Colour: Silver Odometer: 220078 km

Engine Capacity: 1798 cc
Market Value/New Car
N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Rovelo 5 mm Rear Left Side: Rovelo 5 mm
Front Right Side: Rovelo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,099.92	1,149.67	1,950.25	62.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	700.00	1,700.00	70.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,499.92	1,849.67	3,650.25	66.37
Approved Total (Overridden) (S\$)		1,450.00		
(S\$)	5,499.92	1,450.00	4,049.92	73.64
+ GST 7.00/7.00% (S\$)	384.99	101.50	283.49	73.64
Nett Amount (S\$)	5,884.91	1,551.50	4,333.41	73.64
+ Loss of Use (3.0 x S\$	+ Loss of Use (3.0 x S\$80.00/day) (S\$) + Doc/Search Fee (S\$)			
+ Doc/S				
Ne	1,793.50			
Global Sum	1,790.00			

INSPECTION

Date of Assignment: 21/11/2019

Date Inspected: 21/11/2019 Inspected At: Lion City Rentals Pte Itd (HQ)

1090 LOWER DELTA ROAD #05-12

Singapore 169201

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: OI SUN PIN Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Cut	423.90 FL	*423.90 FL	
2	1		*REAR BUMPER CENTER PAD	Necessary	552.30 FL	*552.30 FL	
3	1		*REAR BUMPER RH RETAINER	Broken	112.70 FL	*83.00 FL	
4	1		*REAR BUMPER LH RETAINER	Serviceable	112.70 FL	*- FL	
5	1		*REAR BUMPER REINFORCEMENT	Serviceable	318.80 FL	*- FL	
6	1		*REAR BUMPER UNDERSIDE RH COVER	Serviceable	133.60 FL	*- FL	
7	1		*REAR BUMPER LOWER COVER	Serviceable	303.90 FL	*- FL	
8	1		*REAR BUMPER RH SIDE EXTENSION FILLER	Serviceable	148.40 FL	*- FL	
9	1		*REAR BUMPER TOW COVER	Serviceable	35.90 FL	*- FL	
10	1		*REAR END PANEL	Repair	356.80 FL	*- FL	
11	1		*REAR END PANEL TOP GARNISH	Serviceable	105.30 FL	*- FL	
12	1		*R/R COMBINATION LAMP	Cracked	433.70 FL	*433.70 FL	
13	1		*R/R LAMP LED AND BODY	Serviceable	481.90 FL	*- FL	
14	1		*SET BUMPER AND END PANEL CLIPS	Necessary	200.00 FS	*30.00 FS	
15	1		*SET REVERSE SENSOR	Serviceable	260.00 FS	*- FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
				Sub Total (S\$)	3,979.90	1,522.90	
	- List Item Discount on L Items 25.00/25.00% (S\$)				879.98	373.23	
				Total Parts (S\$)	3,099.92	1,149.67	
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO LABOUR CHARGE FOR REMOVING REAR BUMPER ,REAR BUMPER REINFORCEMENT OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	New	900.00	300.00				
2	TO RESPRAY REAR BUMPER ,END PANEL REAR BOOT	New	900.00	400.00				
3	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST SCAN TEST AS AREQUIREMENTS FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	0.00				
4	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS	New	300.00	0.00				
	Gross Labour	2,400.00	700.00					
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >