



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 6196Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR NUMBER PLATE (CONSISTENT) (SN)	BENT	18.00	18.00
1	REAR NUMBER PLATE LAMP (CONSISTENT) (SN)	CRACKED	28.00	28.00
1	REAR SAFETY BAR (CONSISTENT) (SN)	BENT	480.00	480.00
1	REAR SAFETY BAR NUT (CONSISTENT) (SN)	NECESSARY	40.00	40.00
2	REAR WOODEN MAIN CHASSIS 'U' CRANK @\$80.00 (CONSISTENT) (SN)	DISTORTED	160.00	160.00
			726.00	726.00
	<u>LABOUR</u>			
	REMOVE AND REFIX REAR SAFETY BAR ASSY ,REAR NO PLATE LAMP AND REPAIR NO PLATE PANEL.REMOVE AND REFIX REAR STEP BAR ,REAR WOODEN MAIN CHASSIS 'U' CRANK REPAIR REAR LH MAIN CHASSIS MEMBER AND REALIGN REAR WOODEN TRUCK POSITION.		600.00	450.00
	TO RESPRAY REAR SAFETY BAR ,STEP BAR AND REAR STICKER .		300.00	220.00
			900.00	670.00
GRAND TOTAL			1,626.00	1,396.00
RECOMMENDED COST OF REPAIRS				1,396.00

Report Ref No. CC4/ASM19020812/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.