

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19020824/R1EA3Q2

Date: 27/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SMB3024Y

Insured Vehicle No : GBH3244C

Date of Loss: 19/11/2019

Nature of Claim: TP

Claim No: 3508211877SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMB3024Y

Make & Model: MAN NL320F (A22), 10.5 D (M)

Engine No: 50331301103131

Reg. Date: 02/01/2013 (Man. Year: 2012)

Chassis No: WMAA22ZZ0C7001529

Colour: Green

Odometer: 438664 km

Engine Capacity: 10518 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size:

275/70 R22.5 (D)

Front Left Side: Michelin 8 mm

Rear Left Side:

Michelin 8/8 mm

Front Right Side: Michelin 8 mm

Rear Right Side:

Michelin 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,625.90	3,165.90	460.00	12.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,250.00	6,010.00	2,240.00	27.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,875.90	9,175.90	2,700.00	22.74
+ GST 7.00/7.00% (S\$)	831.31	642.31	189.00	22.74
Nett Amount (S\$)	12,707.21	9,818.21	2,889.00	22.74
+ Loss of Use (5.0 x S\$250.00/day) (S\$)		1,250.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,070.21		

INSPECTION

Date of Assignment: 25/11/2019

Date Inspected: 25/11/2019 Inspected At:

Tower Transit Singapore Pte Ltd (HQ)

21 Bulim Drive, Bulim Bus Depot

Singapore 648170

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S/R CORNER BUMPER	Deformed	678.00 F	*678.00 F
2	2		*STOP LAMP	Cracked	226.60 F	*226.60 F
3	1		*FLASHER ASSY	Cracked	319.30 F	*319.30 F
4	1		*N/S SIDE PANEL L7	Repair	230.00 F	*- F
5	1		*N/S SIDE PANEL L8	Repair	230.00 F	*- F
6	1		*N/S SIDE PANEL L10	Cut	682.00 F	*682.00 F
7	1		*N/S SIDE PANEL L11	Cut	760.00 F	*760.00 F
8	1		*ADVERTISEMENT STICKER	Necessary	500.00 F	*500.00 F

F=Franchise part.

Total Parts (S\$)	3,625.90	3,165.90
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED BODY PART	New	3,250.00	1,950.00
2	SPRAY PAINTING	New	3,200.00	2,560.00
3	TO REMOVE REPLACE ADVERTISEMENT STICKER *SPECIAL NETT BY CONTRACTOR*	New	1,800.00	1,500.00
Gross Labour Cost (S\$)			8,250.00	6,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >