

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 2782X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (SN)	BROKEN	1,000.00	800.00
1	REAR BUMPER TOW EYE COVER - RH (SN)	MISSING	38.00	30.40
2	REAR BUMPER RETAINER - LH / RH (SN)	BROKEN	80.00	64.00
2	REAR BUMPER LIGHT REFLECTOR - LH / RH (SN)	NOT NECESSARY	100.00	-
2	REAR BUMPER PARKING SENSOR - LH / RH (SN)	SHORTED	400.00	320.00
1	REAR REINFORCEMENT BAR (SN)	NOT NECESSARY	488.00	-
2	REAR BUMPER BRACKET - LH / RH (SN)	NOT NECESSARY	100.00	-
1	REAR END PANEL - OUTER (SN)	TO REPAIR SEE LABOUR	625.00	-
1	ACRYLIC SEALANT (SN)	NOT NECESSARY	180.00	-
1	CAVITY WAX (SN)	NOT NECESSARY	140.00	-
1	STONE CHIP (SN)	NOT NECESSARY	180.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			3,381.00	1,214.40
	<u>LABOUR</u>			
	TO REMOVE AND TRANSFER REAR PARKING SENSOR WIRING, CHECK FUNCTION.		80.00	50.00
	TO DISLODGE AND REINSTALL REAR WIRING HARNESS TO REPAIR SPARE WHEEL HOUSING.	NOT NECESSARY	100.00	-
	TO DISMANTLE AND RENEW REAR BUMPER AND REAR BUMPER SPOILER. CUT OUT REWELD END PANELLING. TO REPAIR SPARE WHEEL HOUSING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. INCLUSIVE OF THE REPAIR OF REAR END PANEL - OUTER.		1,200.00	200.00
	TO RESPRAY REAR BUMPER, SPARE WHEEL HOUSING, AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT.		1,000.00	200.00
	TO CARRY OUT DIAGNOSTIC CHECK.		150.00	120.00
			2,530.00	570.00
	GRAND TOTAL		5,911.00	1,784.40

RECOMMENDED COST OF REPAIRS (CONFIRMED)		1,784.40
---	--	----------

Report Ref No. CS/INC19020829/Eqd3e2





Report Ref No. CS/INC19020829/Eqd3e2



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser