

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**INV** Date

## TAX INVOICE

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No.

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSE

SINGAPORE 189556

ATTN: JEFF LIN

No. AC2003312

20/04/2020

Reference CS/INC19020830/R1qd3n2

Code I

#### PROFESSIONAL SERVICE FEE

Vehicle No. SJU 122C

Insured Veh. SLP 8141Y

Claim No. MT/1071968-002

Policy No.

Accident Date 16/11/2019

Inspection Date 19/12/2019

Description	Total
Damage Assessment	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 

HYN



5b.

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19020830/R1qd3n2

1410	C INCOME INSUIT	RANCE CO-OPERATIVE LID	Rei.	C3/111C 19020030	5/1X 14u3112			
		D UNION HOUSESINGAPORE	Date:	20-04-2020				
ATT	N: JEFF LIN		Code:	INC				
1.	1. Policy Particulars :- THIRD PARTY CLAIM							
	Insured Veh.	SLP 8141Y	Veh. Ir	nspected	SJU 122C			
	Policy No.		Cover	age (\$)	0.00			
	Claim No.	MT/1071968-002	Exces	s (\$)	0.00			
	Assign From	HAZALYSA BINTI IBRAHIM	Assig	n Date	25/11/2019			
2.		Vehicle Partic	culars 8	Condition				
	Make & Model	AUDI A3 SB 1.0 TFSI S TRONIC	c.c		999			
	Engine No.	HIDDEN	Year o	f Reg.	2017			
	Chassis No.	WAUZZZ8V2HA103411	Colou	ſ	GREY			
	Odometer	34140 KM	Steeri	ng	IN ORDER			
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM			
	General	FAIR						
3.		Conditi	ons of 7	Tyres				
		Size	Make		Balance			
	R/H Front Tyre	205/55 R16	BRIDG	ESTONE	6 mm			
	L/H Front Tyre	205/55 R16	BRIDG	ESTONE	6 mm			
	R/H Rear Tyre	205/55 R16	BRIDG	ESTONE	6 mm			
	L/H Rear Tyre	205/55 R16	BRIDG	ESTONE	6 mm			
4.		Description	on of Da	ımages				
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	S FRONT	PORTION.				
5.		Genera	l Inform	ation				
	Accident Date	16/11/2019	Inspec	t Date / Time	19/12/2019 ( 02:59 PM )			
	Survey held at	281 ALEXANDRA ROAD						
	Repairer	PREMIUM AUTOMOBILES PTE	LTD					
5a.		Re	emarks					

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

ESTIMATED NORMAL PERIOD FOR REPAIR:

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**Estimate Days of Repair** 

**6 Working Days** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 122C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER GUIDE SECTION-LH (SN)	SERVICEABLE	35.00	-
1	FRONT FENDER-LH (SN)	BENT	778.00	622.40
1	FRONT FENDER ATTACHMENT PARTS-LH (SN)	NECESSARY	65.00	52.00
1	FRONT FENDER UPPER BRACKET-LH (SN)	SERVICEABLE	25.00	-
1	FRONT FENDER BRACKET-LH (SN)	SERVICEABLE	43.00	-
1	FRONT FENDER SEAL-LH (SN)	NOT NECESSARY	31.00	-
1	FRONT FENDER BRACE-LH (SN)	SERVICEABLE	88.00	-
1	FRONT FENDER CLOSING ELEMENT-LH (SN)	SERVICEABLE	54.00	-
1	FRONT WHEEL HOUSING LINER-LH (SN)	SERVICEABLE	158.00	-
1	FRONT ALUMINIUM RIM-LH (SN)	SCRATCHED	651.00	520.80
1	RUBBER VALVE (SN)	NECESSARY	13.00	10.40
1	LED HEADLIGHT-LH (SN)	SERVICEABLE	5,029.00	-
1	SUNDRIES (SN)	NOT NECESSARY	200.00	-
1	FRONT WHEEL HOUSING LINER ATTACHMENT PART-LH (SN)	NOT NECESSARY	52.00	-
			7,222.00	1,205.60
	<u>LABOUR</u>			
	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.		100.00	100.00
	TO DISMANTLE FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.TO RENEW LHS FRONT FENDER AND LHS HEADLIGHT.TO REPAIR FRONT BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.		800.00	400.00
	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER,LHS FRONT DOOR.		1,000.00	600.00
	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.		120.00	120.00
	TO CARRY OUT DIAGNOSTIC CHECK.		150.00	150.00
			2,170.00	1,370.00
	GRAND TOTAL		9,392.00	2,575.60

Report Ref No. CS/INC19020830/R1qd3n2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		2,575.60
(CONFIRMED)		

Report Ref No. CS/INC19020830/R1qd3n2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SJU 122C

#### INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SJU 122C

## RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315





